MARYLAND DEPARTMENT OF THE ENVIRONMENT

1800 Washington Boulevard, **Suite 620** • Baltimore Maryland 21230-**1719**
(410) 537-3442 • 1-800-633-6101 • http:// www. mde. state. md. us

WASTE MANAGEMENT ADMINISTRATION
~~Oil Control Program~~
Report of Observations

Time in/out
Case # ~3 PM / ~5 PM (Phone Messages)

Type of Inspection/Observations: Solid Waste - Landfill (LF) Inspection Date: 12/22/08

Site/Facility Name: Site B Municipal Landfill Vertical Expansion Follow Up Facility ID # 2003-WMF-0582

Location: 9031 Reichs Ford Rd., Frederick 21704 (Frederick Co.) Page # 1 of 1

Remarks: (Background) See report of observations under 12/18/08 Inspection. There was a suspicious area on the South side of Cell 2.

(Observations & Actions)

- Phil Harris of the LF left me a phone message saying that the area that had the sheen-containing water was tested for electrical conductivity and it was lower than drinking water standards, suggesting that the sheen was ~~to~~ not due to leachate. Phil added that the result could have been influenced by the rain, and said the LF will continue to monitor the area.
- The conductivity result suggests that the sheen was due to natural extracts in the run-off, but I concur that the LF should continue to observe the area.

Observer: James P. Wagner, REGIONAL INSPECTOR Person Interviewed: I WILL GIVE THE LF A COPY AT MY NEXT OPPORTUNITY (Gave the LF a copy 2/9/09)

Form Number MDE/WAS/Com.031
TTY Users 1-800-735-2258

Recycled Paper