

Start Point: Spicebush Drive / Shawfield Lane Sidewalk-Inventor

(Right)

End Point: Kendall Drive

50050a ^{Pg 1 of 2} 370

Direction of Increasing Station: _____

Inspector Name: T/W/D
Date: 9-9-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Total Number of Driveways: 14 ~~||||~~ ~~||||~~ ~~||||~~

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Shawfield Ln.	0+00	0+75	0+75	0+79	CS	
	0+79	0+87	0+87	1+04	CS	
			1+04		DS	3713
			1+04	1+13	CS	
	1+13	4+17	4+17		VC	
	4+17	4+46	4+46		VC	
	4+46	4+82	4+82		VC	GAS Valve
	4+82	4+89	4+89		PO	TREE
	4+89	5+27	5+27		VC	
			5+27		PO	Bush
	5+27	8+12	8+12		VC	GAS VALVE
	8+12	10+19	10+19	10+49	CS	TREE TRIM
	10+49	11+32	11+32		VC	
	11+32	11+59	11+59		PO	Bush

50052

Start Point:

Spice bush Dr / Shawfield Ln.

Sidewalk Inventory

(Right)

pg 2 of 2

End Point:

Kendall Drive

500sb

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name:

T/W/D

Date:

4-9-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

111 111 111 1

(16)

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	11+59	12+82	12+82		VC	
	12+82	15+58	15+58	15+62	CS	
	15+62	15+98	15+98	16+06	CS	
	16+06	16+29	16+29		VC	
	16+29	16+94	16+94	17+03	CS	
	17+03	19+72				
Sweet Briar Lane	0+00	1+98	1+98		VC	
	1+98	2+61				
Triton St.	0+00		0+00	0+08	CS	
	0+08	1+29	1+29		DS	3771
			1+29	1+38	CS	
	1+38	2+83	2+83		DS	3775
			2+83	2+92	CS	
	2+92	3+70				

Kendall Drive

3+70

500sb

Start Point: Spice Bush Dr. / Shawfield Ln
End Point: Left

Sidewalk Inventory

19#

4995a

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTS
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Shawfield Ln	0+81	0+81	0+81		CS	
		0+81	0+81	0+93	DS	39' 2" H.
			0+93	1+03	CS	
	1+03	1+15	1+15	1+15	VC	greater than 1/2" Gap
	1+15	1+66	1+66	1+66	VC	" " "
	1+66	4+93				
Kendall Dr.	0+00	0+30	0+30	0+39	CS	
			0+39	0+39	DS	38' 0"
			0+39	0+47	CS	
	0+47	2+04	2+04	2+04	VC	> 1/2" Gap
	2+04	3+17	3+17	3+17	VC	" " "
	3+17	3+45	3+45	3+45	VC	" " "
	3+45	3+61	3+61	3+61	VC	" " "
	3+61	4+19	4+19	4+19	VC	" " " "

4995a

27A

Sidewalk Inventory

Start Point: Spice Bush Dr. / Ken Drail Dr. / Shawfield

499sb

End Point: _____

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWDDate: 4/09/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 7/11 1/11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Ken Drail Dr.</u>	4+19	4+53	4+53	4+53	VC	Greater than 1/2" Gap
	4+53	5+71	5+71	5+80	CS	
			5+80	5+80	DS	37 3744
			5+80	5+88	CS	
	5+88	6+73	6+73	6+73	VC	7 1/2" Gap.
	6+73	6+81	6+81	6+81	VC	" " "
	6+81	7+19	7+19	7+19	VC	" " "
	7+19	7+55	7+55	7+55	VC	"
	7+55	7+73	7+73	7+87	CS	
			7+87	7+87	DS	3748
			7+87	7+96	CS	
	7+96	10+60	10+60	10+72	CS	
	10+72		10+72	11+05	CS	
			11+05	11+05	DS	3750
			11+05	11+29	CS	

499sb

37A

Start Point: Spice Bush Dr. / Ken Ladd Dr. / Shaw Field

499Sc

End Point: _____

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TJW
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 1111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	11+29	11+92	11+92	11+92	VC	Greater than 1/2" Gap
	11+92	11+97	11+97	11+97	VC	
	11+97	12+38	12+38	12+51	CS	
			12+51	12+51	DS	3754
			12+51	12+60	CS	
	12+60	14+80	14+80	14+80	VC	> 1/2" "
	14+80	15+27	15+27	15+27	VC	" " "
	15+27	15+57	15+57	15+74	CS	
			15+74	15+74	DS	3762
			15+74	15+83	CS	
	15+83	15+95	15+95	15+95	VC	
	15+95	16+61	16+61	16+61	VC	
	16+61	16+89	16+89	17+10	CS	
			17+10	17+10	DS	3766

499Sc

7 9 7

4995d

Sidewalk Inventory

Start Point: Spice Bush Dr / Randall Dr / Shawfield.

End Point: Kendall Dr

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWS

Date: 4/9/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 1

Street Name: _____

Compliant

From

To

Non-Compliant

From

To

Code

Comments

[illegible]

4995d

Start Point: Kimber Ln R / Sugar Loaf Pkwy

End Point: Carriage Hill DR

Direction of Increasing Station: Rt 54

520
118

4985

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWS
Date: 4/9/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugar Loaf Pkwy	0+00	0+45	0+45	0+49	CS	
	0+49	1+71	1+71	1+87	CS	
	1+87	2+71	2+71	2+79	CS	
	2+79	5+12	5+12	5+12	VC	Greater than 1/4" Cy
	5+12	5+60				
Alkyway	0+00	0+24	0+24	0+48	CS	
	0+48	0+56	0+56	0+68	CS	
	0+68	1+18				
118						
Carriage Hill Dr						
118						

4985

pg. 1 of 1
Left
8+19

Start Point: Kinnerton PLACE / Sugarloaf Pkwy.

End Point: Carrage Hill Drive

4975

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: D. WIT
Date: 4-9-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: (2)

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugarloaf Pkwy.	0+00	2+46	2+46	2+46	VC	greater than 1/2" Lip
	2+46	3+81	3+81	3+86	CS	
	3+86	5+55	5+55	5+55	PO	Trim Tree
	4+55		5+55	5+59	CS	
	5+59	6+07	6+07	6+07	VC	" "
	6+07	6+47	6+47	6+ 51	CS	CS
	6+47					
Carrage Hill Dr 8+19	6+51	8+19				

4975

Start Point: Shawfield LA / Sugarloaf Pkwy.

End Point: _____

Direction of Increasing Station: Left

4965a

Reason Codes for NON-COMPLIANCE:

Inspector Name: T. W. J
Date: 4-9-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Intersecting
Street Name:

Compliant

Non-Compliant

From

To

From

To

Code

Comments

Sugarloaf Pkwy.			0+00	0+11	CS	trees need trimmed (to low)
	0+11	0+79	0+79	0+95	CS	
Alley @ 3900	0+95	1+23	1+23	1+27	CS	
	0+00	0+68	0+68	0+81		
Spicebush Dr	0+81	1+14				
	0+00	0+93	0+93	0+99		
	0+99	1+52	1+52	1+61	CS	
			1+61	1+72	ds	@ 3908
	1+72	2+27	2+27	2+27	VS	
	2+27	2+36	2+36	2+36	VC	
	2+36	2+85	2+85	2+85	VC	
	2+85	3+61	3+61	3+61	VC	
Penrose St.	3+61	4+11				

Start Point: Dunraven St. / Alley 3936 ^{Sidewalk Inventory}

End Point: Addison Woods Rd

Direction of Increasing Station: Right

Dun Raven St

299

4955

Reason Codes for NON-COMPLIANCE:

Inspector Name: WJT
Date: 9/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Alley 3936	0+00	1+10				
Shaw Field Ln	0+00	0+33	0+33	0+53	CS	
	0+53	0+67	0+67	0+67	VC	Gravel down 1/2" up.
	0+67	0+90	0+90	0+90	VC	" " " "
	0+90	1+50	1+50	1+50	VC	" " " "
	1+50	1+59	1+59	1+59	VC	" " " "
	1+59	1+99	1+99	1+99	VC	" " " "
	1+99	2+03	2+03	2+03	VC	" " " "
	2+03	2+62	2+62	2+66	CS	
ADDISON Woods Rd						
2+66						
+33						

4955

Start Point: Addison Woods RD. / Carriage Hill St.

End Point: Sugar Loaf Pkwy

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWJ
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Carriage Hill St	0+00	2+38	2+38	2+46	CS	
	2+46	3+93	3+93	4+31	CS	
	4+31	4+54	4+54	4+68	CS	
	4+68	5+31	5+31	5+39	CS	
	5+39	6+47	6+47	6+63	CS	
	6+63	7+85	7+85	7+85	VC	Greater than 1/2" Gap
	7+85	7+94	7+94	7+94	VC	" " " "
	7+94	9+10				
Alley 3901	0+00	0+11	0+11	0+27	CS	
	0+27	0+92	0+92	0+92	VC	" " " "
	0+92	1+37				
Sugar Loaf Pkwy						
0+92 1+37						

794
137
931

494B

4945

159

Dunraven
Sidewalk Inventory

Start Point: Dunraven St / Prospect Hill Pl.

End Point: _____

4935

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: WJ
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Prospect Hill Pl</u>	0+00	0+47	0+47	0+67	CS	Trim trees
	0+67	2+27	2+27	2+48	CS	
<u>Carriage Hill St</u>			0+00	0+69	CS	9433 Alley 9400
	0+69	1+22				
<u>Gange 9433</u>						greater than
<u>Alley way</u>	0+00	2+85				> 1/2 Lip.
<u>Alley way 9463</u>	0+00	1+39	1+39	1+39	VC	3882 9463
	1+39	1+59				
<u>Carriage Hill Dr.</u>						
<u>159</u>						

4935

Start Point: Cornwell Meadow St

Sidewalk Inventory

Carriage Hill Dr.

138
309
107

End Point: _____

Direction of Increasing Station: Left

4915

Reason Codes for NON-COMPLIANCE:

Inspector Name: WJ
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

TRIM
Bushes

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Carriage Hill Dr.	0+00		0+00	0+09	CS	Greater than 1/2" Lip.
	0+09	0+22	0+22	0+22	VC	" " " "
	0+22	0+67	0+67	0+71	CS	
	0+71	1+05	1+05	1+09	CS	9425 L
	1+09	1+38				
Alley way 3862	0+00	2+89	2+89	2+89	VC	3862 Greater than 1/2" Lip
9425	2+89	3+09	3+09	3+17		
Alley way 9401	0+00	1+07				9401 L

4915

Start Point: Carriage Hill St / Dun Raver St

Sidewalk Inventory

4905

173
212

End Point:

312

Direction of Increasing Station:

Right

115

712

Reason Codes for NON-COMPLIANCE:

Inspector Name: WST
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Dun Raver St	0+00	1+07				
Alleyway 9411	0+00	0+73	0+73	0+87	CS	
Alleyway 9417	0+00	0+21	0+21	0+44	CS	3978 Alleyway between 9412
	0+44	2+12				
Adison Underpass	0+00	2+26	2+26	2+26	VC	Greater than 1/2" Lip.
	2+26	2+42	2+42	2+42	VC	" " " "
	2+42	2+53	2+53	2+53	VC	" " " "
	2+53	2+73	2+73	2+73	VC	" " " "
	2+73	3+12				
Alleyway 9441			0+00	0+33	CS	
Alleyway 3824	0+33	1+11	1+11	1+15	CS	
Carriage Hill Dr						
1+15						

4905

Start Point: Bronxheart Cir / Bronxheart Dr Sidewalk Inventory

400

4895

End Point: _____

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: WD
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bronxheart Dr	0+00	1+27				
Alleyway 3931 3914	0+00	0+54	0+54	0+54	VC	Greater than 1/2" Lip
	0+54	1+38	1+38	1+38	VC	" " " "
	1+38	3+84	3+84	3+88	C/S	
	3+88	4+00				
Longhorne 29	3					
3901: Park.						
400						

4895

4885

Phil's
Start Point: Phil's Rd @ Talbot Dr. R
End Point: Wilcomco Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Talbot Dr.	0+00	2+73	2+73	2+73	PO	Tree
	2+73	3+44	3+44	—	VC	
	3+44	3+55				End

4885

4875a

Start Point: Wicomico Dr. @ Phils Rd ^{Sidewalk Inventory} REnd Point: Talbot Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KADate: 4/9/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 12

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Phils Rd	0+00	0+25	0+25	—	VC	
	0+25	0+40	0+40	—	VC	
	0+40	1+21	1+21	—	VC	
	1+21	1+36	1+36	1+36	DS	5521
	1+36	2+00	2+00	—	VC	
	2+00	2+14	2+14	—	VC	
	2+14	2+19	2+19	2+19	DS	5523
	2+19	2+24	2+24	—	VC	
	2+24	2+77	2+77	—	VC	
	2+77	2+87	2+87	—	VC	
	2+87	4+11	4+11	—	VC	
	4+11	4+22	4+22	—	VC	
	4+22	5+17	5+17	—	VC	
	5+17	5+47	5+47	—	VC	

4875a

Start Point: Wilcomico Dr @ Phillips Rd E

End Point: Talbot Dr

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 10

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+47	6+32	6+32	6+44	CS	
	6+44	9+08	9+08	—	VC	
	9+08	9+13	9+13	9+13	PO	tree
	9+13	9+50	9+50	—	VC	
	9+50	9+73	9+73	9+73	PO	tree
	9+73	10+18	10+18	—	VC	
	10+18	10+48	10+48	10+48	DS	5547
	10+48	10+76	10+76	—	VC	
	10+76	11+41	11+41	—	VC	End

111

Sidewalk Inventory

Start Point: Ross Ct @ Royal Oak Dr. R

End Point: Royal Oak Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: 02, KA
Date: 4/9/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 8

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Royal Oak Dr.	0+00	0+89	0+89	—	VC	
	0+89	1+81	1+81	1+81	DS	5494
	1+81	2+18	2+18	—	VC	
	2+18	2+32	2+32	—	VC	
	2+32	2+53	2+53	—	VC	
	2+53	2+80	2+80	2+96	CS	
	2+96	2+96	2+96	2+96	DS	5490
	2+96	2+96	2+96	3+05	CS	
	3+05	3+45	3+45	—	VC	
	3+45	3+59	3+59	—	VC	
	3+59	3+74	3+74	—	VC	
	3+74	3+98	3+98	—	VC	
	3+98	4+49	4+49	4+61	CS	
	4+61	4+61	4+61	—	VC	

486sb

Sidewalk Inventory

Start Point: Ross Ct. @ Royal Oak Dr.End Point: Royal Oak Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, LA
Date: 4/9/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 12

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	4+61	5+76	5+76	-	VC	
	5+76	5+81	5+81	-	VC	
	5+81	5+98	5+98	-	VC	
	5+98	6+07	6+07	-	VC	
	6+07	6+90	6+90	-	VC	
	6+90	7+01	7+01	7+01	DS	5485
	7+01	7+44	7+44	-	VC	
	7+44	7+44	7+44	7+54	CS	
	7+54	8+29	8+29	8+29	DS	5489
	8+29	9+29	9+29	-	VC	
	9+29	9+90	9+90	-	VC	
	9+90	10+05	10+05	-	VC	
	10+05	10+70	10+70	10+70	DS	5499
	10+70	11+00	11+00	11+25	CS	

11+25

12+13

End

486sb

Start Point: Wicomico Cir @ Talbot Dr.

R+

4855

End Point: 5552 Wicomico Cir

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KA
Date: 4/9/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 10

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Talbot Dr.	0+00	1+44	1+44	1+57	CS	
	1+57	1+89	1+89	1+89	DS	5555
	1+89	1+94	1+94	2+00	CS	
	2+00	2+00	2+00	—	VC	
	2+00	4+15	4+15	4+15	DS	5556
	4+15	4+66	4+66	—	VC	
	4+66	5+55	5+55	5+55	DS	5562 End

4855

4845

Sidewalk Inventory

Start Point: Mussetter Rd @ Old National Pike R

End Point: Hazelcraft Ave

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Old Nat. Pike	0+00	0+47	0+47	1+07	CS	
	1+07	1+84				
Entrance 1	0+00	0+10	0+10	0+31	CS	
	0+31	1+81	1+81	—	VC	
	1+81	1+94				
Entrance 2	0+00	3+25				
Entrance 3	0+00	0+15	0+15	0+34	CS	
	0+34	1+79	1+79	—	VC	
	1+79	1+84	1+84	—	VC	
	1+84	2+73				
Whitrose Way	0+00	2+08				
Mussetter Ct	0+00	1+59	1+59	1+75	CS	
Dewey Way E	0+00	4+12				End

4845

Sidewalk Inventory

Start Point: Hazelcroft Ave @ Mussetter Rd E

End Point: Whiterose Dr

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KA
Date: 4/19/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 15

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Mussetter Rd	0+00	5+22	5+22	—	VC	
	5+22	7+13	7+13	7+29	CS	
	7+29	7+58	7+58	—	VC	
	7+58	10+22	10+22	—	VC	
	10+22	10+32	10+32	—	VC	
	10+32	12+70	12+70	—	VC	
	12+70	14+08	14+08	14+08	DS	5816
	14+08	14+18	14+18	—	VC	
	14+18	17+30	17+30	17+30	DS	5810
	17+30	18+13	18+13	—	VC	
	18+13	18+68	18+68	—	VC	
	18+68	21+31				End

4835

111
11

4825

Sidewalk Inventory

Start Point: Whiterose Dr @ Mussetter Rd R

End Point: Meyer Ave

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/9/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 7

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Mussetter Rd.	0+00	0+43	0+43	0+54	CS	
	0+54	2+32	2+32	—	VC	
	2+32	3+06	3+06	3+06	PO	tree
	3+06	4+19				
Drexel Ave	0+00	0+05	0+05	—	VC	
	0+05	0+16	0+16	0+40	CS	
	0+40	1+19	1+19	—	VC	
	1+19	2+10	2+10	—	VC	
	2+10	2+22	2+22	—	VC	
	2+22	5+50	5+50	—	VC	
	5+50	5+80	5+80	—	VC	
	5+80	7+16	7+16	7+57	CS	
	7+57	9+27	9+27	—	VC	
	9+27	12+50				End

4825

4.15

Sidewalk Inventory

Start Point: Jordan Blvd @ Old National Pike R

End Point: Meyer Ave

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/9/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 18

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Old Nat. Pike	0+00	2+06	2+00	2+06	DS	5601
	2+06	2+93	2+93	—	VC	
	2+93	4+18	4+18	—	VC	
	4+18	4+39	4+39	4+61	CS	
	4+61	4+87	4+87	—	VC	
	4+87	5+42				
Meyer Ave			0+00	0+08	CS	
	0+08	14+37				End

14815

480Sa

Sidewalk Inventory
 Start Point: Meyer Ave @ Jordan Blvd R
 End Point: Jordan Blvd

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: QZ, KA
 Date: 4/9/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 30

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Jordan Blvd	0+00	0+94	0+94	—	VC	
	0+94	1+04	1+04	—	VC	
	1+04	1+22	1+22	—	VC	
	1+22	1+34	1+34	—	VC	
	1+34	3+75	3+75	—	VC	
	3+75	4+62	4+62	—	VC	
	4+62	6+15	6+15	—	VC	
	6+15	7+28	7+28	—	VC	
	7+28	12+32	12+32	—	VC	
	12+32	13+29	13+29	—	VC	
	13+29	13+38	13+38	13+38	DS	5727
	13+38	14+36	14+36	—	VC	
	14+36	16+86	16+86	16+86	DS	5731
	16+86	19+54	19+54	19+54	DS	5737

480Sa

480sb

Start Point: Meyer Ave @ Jordan Blvd

End Point: Jordan Blvd

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA

Date: 4/9/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 15

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	19+54	20+71	20+71	—	VC	
	20+71	20+91	20+91	—	VC	
	20+91	21+12	21+12	—	VC	
	21+12	21+21	21+21	21+21	DS	5741
	21+21	21+96	21+96	21+96	DS	5745
	21+96	23+85	23+85	—	VC	
	23+85	25+34	25+34	25+34	VC	
	25+34	26+86				
Whiterose Dr.	0+00	7+17				
Jordan Blvd	0+00	2+27	2+27	2+27	DS	5718
	2+27	3+89	3+89	3+89	DS	5714
	3+89	5+84	5+84	—	VC	
	5+84	6+68	6+68	—	VC	
	6+68	6+77	6+77	—	VC	

480sb

4805c

Direction of Increasing Station:

Inspector Name: 02, KA
Date: 4/9/14

WP Width of Panel

Total Number of Driveways: 2

4805c

Start Point: Bennet Creek Ave @ Fannie Mae
 End Point: Fingerboard Rd.

4785

Right

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: CM/CB
 Date: 4/8/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Fannie Mae Bldg	0+00	1+46	1+46	1+46		3/4" Gap
Future Ent	0+00	1+87				" "
Bennet Creek Blvd	0+00	0+05	0+05	0+15		
	0+15	2+73				
3275	0+00	2+34				Fingerboard Rd - End

4785

4775 2674

End Point: MTD 2 + 355

Direction of Increasing Station:

Date: 2/1/2014

WP Width of Panel

Total Number of Driveways: 0

[illegible]

4475

Direction of Increasing Station: 100

Reason Codes for NON-COMPLIANCE:

Inspector Name: B. J. A.

Date: 5-23-19

VC Vertical Clearance

PP Pinch Point

PZ: Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name: Bonita Canyon From Compliant

Compliant

Non-Compliant

Street Name: <u>Shawnee Lane</u>		From	To	From	To	Code	Comments

[illegible]

4765

4755

Sidewalk Inventory

Start Point: Union Plwy @ Union Terr

End Point: RT 80

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: LT

Date: 11-10-10

Total Number of Driveways: 0

Street Name: <u>Union Plwy</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Union Terr</u>	<u>0+00</u>	<u>3+52</u>	<u>3+52</u>	<u>3+96</u>		
	<u>3+96</u>	<u>4+97</u>				
<u>FNWA Ent #1</u>	<u>0+00</u>	<u>0+10</u>	<u>0+10</u>	<u> </u>	<u>VC</u>	<u>Valve box</u>
	<u>0+10</u>	<u>1+13</u>	<u>1+13</u>	<u>1+23</u>	<u>CS</u>	
	<u>1+23</u>	<u>1+49</u>	<u>1+49</u>	<u>2+60</u>	<u>CS</u>	
	<u>2+60</u>	<u>3+31</u>	<u>3+31</u>	<u>3+46</u>	<u>CS</u>	
<u>FNWA Ent #2</u>			<u>0+00</u>	<u>0+05</u>	<u>CS</u>	
	<u>0+05</u>	<u>3+48</u>				
<u>Bennett Creek Rd</u>	<u>0+00</u>	<u>0+88</u>	<u>0+88</u>	<u>1+08</u>	<u>CS</u>	
	<u>1+08</u>	<u>3+54</u>				
<u>Co Rd Entrance #1</u>	<u>0+00</u>	<u>0+30</u>	<u>0+30</u>	<u>0+75</u>	<u>CS</u>	
	<u>0+75</u>	<u>1+80</u>				<u>End @ Dead End RT 80</u>

4755

A 745

End Point: Urban Parkway

Direction of Increasing Station: UA

Inspector Name: J. J. [Signature]

Date: 4-8-14

WP Width of Panel

Total Number of Driveways: 0

Non-Compliant

From

To

From

To

Code

Comments

[illegible]

4745

4735

Start Point: BENNETT CREEK BLVD @ URBANA PKWY

End Point: Bennett creek Dr

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

(L)

Inspector Name: JH, BF
Date: 9-9-14

Total Number of Driveways: 0

Street Name: <u>Bennett Creek Dr</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
URBANA PKWY	0+00	1+20	1+20	1+35	CS	
	1+35	2+35				
Future ENT #1: L	0+00	0+94	0+94	1+28	CS	
	1+28	2+27				
Bennett Creek Dr.	0+00	5+62				
Future ENT #2	0+00	9+39				
Urban Tacc.	0+00	11+04				END @ Bennett Creek Dr

4735

Sidewalk Inventory

Start Point: DEAD END ON BENNETT CREEK AVE

End Point: 50' SHORT OF FINGERBOARD RD.

Direction of Increasing Station: LT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF, JH
Date: 9/8/11

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
DEAD END	0+00	1+12	1+12	1+28	CS	
	1+28	4+15	4+15	4+27	CS	
BENNETT CREEK BLVD	4+27	4+94				
	6+00	1+66	1+66	1+82	CS	
	1+82	2+02	2+02	2+08	CS	
NO NAME ENTRANCE	2+08	3+38				
	0+00	1+98	1+98	2+12	CS	
DEAD END			2+12	2+12		DEAD END - APPROX 50' SHORT OF FINGERBOARD RD

4125

A715

End Point: RT 85 BUCKETS TOWAL PIKE.

Direction of Increasing Station: LT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JHCN
Date: 4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

0

Street Name:

Compliant

Non-Compliant

From

To

From

To

Code

5/ SUPERMARK

Comments

[illegible]

4715

Sidewalk Inventory

4705

Start Point: GENSTAR DR @ URBANA PIKE

End Point: MARK TRAIN STATION ENTRANCE

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF JH
Date: 4/18/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
URBANA PK	0+00	0+07	0+07	2+18	CS	
SHOPPING CTR ENT #1	2+18	2+18				
	0+00	1+16	1+16	2+65	CS	
SHOPPING CTR ENT #2	2+65	2+74				
	0+00	0+00	0+00	0+08	CS	
	0+08	2+33	2+33	2+78	CS	
	2+78	4+07	4+07	4+12	CS	
MARK TRAIN STA. ENT.	4+12	4+12				END

4705

Sidewalk Inventory

Start Point: Genstar Dr @ R+355

End Point: Genstar Dr @ Train Parking

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: CM/SJB
Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
R+ 355	0+00	0+52	0+52	0+90	CS	
	0+90	1+21	1+21	1+52	CS	
	1+52	2+36	2+36	2+36	VC	
			2+41	2+41	VC	
	2+41	2+57				
Ent @ Home Depot	0+00		0+00	0+65	CS	
			0+34	0+34	VC	
	0+65	1+54	1+54	1+70	CS	
	1+70	2+10	2+10	2+10	VC	
	2+10	2+53	2+53	2+53	VC	
			2+53	2+82	CS	
	2+82	2+94	2+94	3+18		
			3+02	3+02	VC	6"

4685

Sidewalk Inventory

Start Point: Genstar Dr @ MD Rt 355

End Point: Genstar Dr @ Train Parking

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: cm / CB

Date: 4/18/15

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

[illegible]

ACGS Right

End Point: Finger board Rd

Direction of Increasing Station:

PO Protruding Object

Date: 4/3/4

Total Number of Driveways:

Non-Compliant

Comments

4675

AGGS Right

Sidewalk Inventory

Start Point: Bennett Creek Dr @ Bennett Creek Blvd

End Point: Urbana Terr

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: CM/CB

Date: 4/8/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bennett Creek	0+00	3+90	3+90	4+00	CS	Sidewalk Removed
	4+00	8+52				New Water Line
	4+00	8+52	8+52	8+80	CS	Sidewalk Removed
	8+80	8+94				Construction SSA
Bennett Creek Blvd	0+00	0+98	0+98	1+03	VC	
	1+03	1+23	1+23	1+23	VC	Urbana Terr - End
	1+23	11+69				

AGGS

ALSS

End Point: Urban Parkway

Direction of Increasing Station: RT

PO Protruding Object

Date: 4/8/14


Total Number of Driveways: 0

[illegible]

465s

Sidewalk Inventory

Start Point: Bennett Creek Blvd @ Urbana Parkway
 End Point: Bennett Creek Dr.



Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: CM/CB
 Date: 4/8/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: _____

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
@ Ramp	0+00	1+25	1+25	1+40	CS	
	1+40	2+67				
Service Ent	0+00	2+27				
Bennett Crk Ave	0+00	2+34	2+34	2+49	CS	
Dumpsters	2+49	2+78				
Urbana Pkwy ^{Single}	0+00	12+66				End-Bennett Creek Dr

4645

1 of 1

4635

Start Point: LOWERS LN @ SPECTRUM DR.

End Point: RT 355 URBANA PIKE

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JH CM
Date: 4/3/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
SPECTRUM DR	0+00	0+00	0+00	0+11	CS	
	0+11	0+36	0+36		VC	
ENTRANCE TO 560 S RST.	0+36	1+95				
	0+00	2+27	2+27		VC	TREE ROOTS
	2+27	2+36	2+36		VC	TREE ROOTS
URBANA PK.	2+36	2+70				END

4635

Start Point: Lowes Ln @ Spectrum Dr

Sidewalk Inventory

4625

End Point: MD 355

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF & CB
Date: 4-8-19

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name: <u>Lowes Ln</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Spectrum Dr</u>	<u>0+00</u>	<u>0+13</u>	<u>0+13</u>	<u>0+25</u>	<u>CS</u>	
	<u>0+25</u>	<u>0+61</u>	<u>0+61</u>	<u>0+65</u>		
	<u>0+65</u>	<u>0+66</u>				
<u>Shopping center #1</u>	<u>0+00</u>	<u>0+52</u>	<u>0+52</u>	<u>0+60</u>	<u>CS</u>	
	<u>0+60</u>	<u>1+00</u>				
<u>Shopping center #2</u>	<u>0+00</u>	<u>0+14</u>				<u>END</u>

4625

Start Point: Pontius Ct. / ^{Sidewalk Inventory} ~~Fingerboard Rd.~~ school (#3511) AGIS

End Point: Fingerboard Rd.

Direction of Increasing Station: Lt

Inspector Name: T/w/J
Date: 4-8-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 1 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
School	0+00	0+08				
(#3511)						
3511 Pontius	0+00	1+12				
(Ent.) Ct.						
Entrance	0+00	2+42				
Fingerboard	2+42					
Rd.						

Start Point: Spice Bush Dr / Sweet Briar LA 4605a Rt. pg. 1 & 2

End Point: _____

Direction of Increasing Station: Rt

Reason Codes for NON-COMPLIANCE:

Inspector Name: T. J. W
Date: 4-8-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: |||||

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Spice Bush Dr.			0+00	0+12	CS	
Sweet Briar Lane	0+12	1+27	1+27	1+27	VC	greater than 1/2" Lip
	1+27	2+92	2+92	2+92	VC	" "
	2+92	4+94	2+92	4+94	CS	
	4+94	6+95	6+95	7+03	CS	
			7+03	7+03	DS	@ 39/6
	7+03	7+30	7+30	7+46	CS	
	7+46	8+48	8+48	8+48	VC	
	8+48	9+88	9+88	9+88	VC	
	9+88	11+15	11+15	11+15	VC	
	11+15	12+51	12+51	12+62	CS	
	12+62	14+30	14+30	14+30	VC	
	14+30	16+01	16+01	16+10	CS	
	16+10	16+80	16+80	16+80	VC	

4605a

Start Point:

Spice Bush Dr / Sweet Briar Ln

Sidewalk Inventory

460sb

Pg. 242

292

Rt. 1915

End Point:

Sweet Briar Ct.

Direction of Increasing Station:

Right

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Inspector Name: J.T.W

Date: 4-8-14

Total Number of Driveways:

11 (2)

Street Name:

Compliant

Non-Compliant

From

To

From

To

Code

Comments

	16+80	17+88	17+88	17+99	CS	@3929
			17+99	17+99	DS	@3929
			17+99	18+09	CS	
	18+09	18+90	18+90	18+90	VC	
	18+90	19+03	19+03	19+03	VC	
Sweet Briar Ct.	19+03	19+15				
19+15						

460sb

Start Point: Triton La / Sweet Brian Ln Sidewalk Inventory

End Point: Kendall Dr.

Direction of Increasing Station: RT

4595

582

Reason Codes for NON-COMPLIANCE:

Inspector Name: WJT

Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sweet Brian	0+00	0+00 0+06	0+06	0+06	VC	Greater than 1/2" gap
	0+06	1+74	1+74	1+74	VC	" " " "
	1+74	2+40	2+40	2+40	VC	" " " "
	2+40	3+31	3+31	3+31	VC	" " " "
	3+31	4+05	4+05	4+05	VC	" " " "
	4+05	4+59	4+59	4+59	VC	" " " "
	4+59	4+97	4+97	4+97	VC	" " " "
	4+97	5+78	5+78	5+78	VC	
	5+78	5+82	5+82			
Kendall Dr.						

4595

Start Point: Triton St. / Triton LA. 193 4585a ✓

End Point: _____

Direction of Increasing Station: R+

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWJ
Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11 Ⓢ

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Triton La.	0+00	0+65	0+65	0+86	CS	
	0+86	1+42	1+42	1+42	VC	Greater than 1/2" up
	1+42	1+89	1+89	1+89	VC	" " " "
	1+89	2+19	2+19	2+21	CS	
	2+21	2+48	2+48	2+66	CS	
			2+66	2+66	DS	3985 #
			2+66	2+75	CS	
	2+75	3+13	3+13	3+22	CS	
			3+22	3+22	DS	3983 #
			3+22	3+31	CS	
	3+31	3+71	3+71	3+81	CS	
			3+81	3+81	DS	3981 #
			3+81	3+89	CS	
	3+89	4+28				

4585a

293

4589b

✓

Start Point: Triton St / Triton La Sidewalk Inventory

End Point: _____

Direction of Increasing Station: R+

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Inspector Name: WTD

Date: 9/8/14

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	<u>2</u>		<u>4+28</u>	<u>4+37</u>	<u>CS</u>	
			<u>4+37</u>	<u>4+37</u>	<u>DS</u>	<u>3979#</u>
			<u>4+37</u>	<u>4+51</u>	<u>CS</u>	
	<u>4+51</u>	<u>4+86</u>	<u>4+86</u>	<u>4+95</u>	<u>CS</u>	
			<u>4+95</u>	<u>4+95</u>	<u>DS</u>	<u>3977</u>
			<u>4+95</u>	<u>5+03</u>	<u>CS</u>	
	<u>5+03</u>	<u>5+42</u>	<u>5+42</u>	<u>5+51</u>	<u>CS</u>	
			<u>5+51</u>	<u>5+51</u>	<u>DS</u>	<u>3975</u>
			<u>5+51</u>	<u>5+60</u>	<u>CS</u>	
	<u>5+60</u>	<u>6+30</u>	<u>6+30</u>	<u>6+30</u>	<u>VC</u>	<u>Grate is 1/2" up</u>
	<u>6+30</u>	<u>6+48</u>	<u>6+48</u>	<u>6+65</u>	<u>CS</u>	
			<u>6+65</u>	<u>6+65</u>	<u>DS</u>	<u>3971</u>
			<u>6+65</u>	<u>6+74</u>	<u>CS</u>	
	<u>6+74</u>		<u>7+12</u>	<u>7+12</u>	<u>VC</u>	

4589b

Start Point:

Triton St. / Triton Ca

Sidewalk Inventory

393

4585c

End Point:

Direction of Increasing Station:

R +

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name:

TWS

Date:

4/8/14

Total Number of Driveways:

1111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
			7+12	7+21	CS	
			7+21	7+21	DS	3969 (on other side)
			7+21	7+37	CS	
	7+37	7+57	7+37	7+57	VC	Greater than 1/2" Gap
	7+57	7+69	7+57			
			7+69	7+78	CS	
			7+78	7+78	DS	3967
			7+78	7+87	CS	
	7+87	8+22	8+22	8+22	VC	Greater than 1/2" Gap
	8+22	8+44	8+44	8+44	VC	" " " "
	8+44	8+84	8+84	8+84	VC	" " " "
	8+84	10+34	10+34	10+37	CS	
Spice Bush Dr.						
1037						

4585c

Start Point: Sweet Briar Ct. / Sweet Briar Lane ^{Sidewalk Inventory} (Circle) (Left) 4575

End Point: Sweet Briar Lane

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/W
Date: 9-8-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sweet Briar	0+00	1+27	1+27		VC	
Lane	1+27	1+64	1+64		DS	3947
			1+64	1+81	CS	
	1+81	2+85	2+85		DS	3941
			2+85	2+95	CS	
	2+95	3+60				
Sweet Briar	3+60					
Lane						

4575

Start Point: Sweet Briar Lane / Spicebush Drive ^{Sidewalk Inventory}

(Left)

4565

End Point: Sweetbriar Ct.

Direction of Increasing Station: _____

Inspector Name: T/W
Date: 4-8-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Spicebush Dr.	0+00	0+12	0+12		PO	Bush
	0+12	2+12	2+12		VC	
	2+12	4+55	4+55		DS	3911
			4+55	4+66	CS	
	4+66	6+05	6+05		DS	3915
			6+05	6+15	CS	
	6+15	7+54	7+54		DS	3919
			7+54	7+63	CS	
	7+63	9+24				
Triton Lane	0+00	1+86				
Sweetbriar Ct.	0+00	0+50				
Sweet Sweetbriar Ct.	0+50					

4565

Start Point:

Triton Street / Triton Lane

Sidewalk Inventory

(Left)

4555

End Point:

Spice bush Drive

Direction of Increasing Station:

Inspector Name:

T/W

Date:

4-8-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

15

Street Name:

Compliant

Non-Compliant

From

To

From

To

Code

Comments

Triton Lane	0+00	1+73	1+73		VC	
	1+73	2+82	2+82		DS	3982
			2+82	2+91	CS	
	2+91	3+32	3+32		VC	
	3+32	3+59	3+59		VC	
	3+59	4+14	4+14	4+27	CS	
	4+27	5+79	5+79		DS	3972
			5+79	5+88	CS	
	5+88	6+10	6+10		VC	
	6+10	7+08	7+08		VC	
	7+08	7+49	7+49	7+59	CS	
			7+59		DS	3966
			7+59	7+75	CS	
	7+75	8+75	8+75		DS	3962
			8+75	8+84	CS	
	8+84	10+21				
Spice Bush Drive	10+21					

4555

Start Point: Triton Lane / Sweet Briar Lane (Left)

4545

End Point: Kendall Drive

Direction of Increasing Station:

Inspector Name: T/w
Date: 4-8-14

Reason Codes for NON-COMPLIANCE:
VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 1111 (4)

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sweet Briar Lane	0+00	2+31	2+31	2+39	CS	
	2+39	2+61				
Triton St.	0+00	2+66				
Kendall Dr.	2+66					

4545

Start Point: Denison Street / Sugarloaf Pkwy (Right)

End Point: E driveway #3637

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/W
Date: 7-8-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugarloaf Pkwy	0+00	0+65	0+65		VC	
	0+65	0+86	0+86		VC	
	0+86	1+75	1+75	2+04	CS	
	2+04	5+20	5+20	5+37	CS	
	5+37	5+61	5+61		DS	3616
			5+61	5+70	CS	
	5+70	6+43	6+43	6+66	CS	
			6+66		DS	3612
			6+66	6+78	CS	
	6+78	6+95	6+95	7+23	CS	
			7+23		DS	3614
			7+23	7+35	CS	
	7+35	7+51	7+51	7+60	CS	
	7+60	8+53	8+53		VC	

45352

Start Point:

Denison Street / Superblock Plwy (Right)

453SB
Pg 2 of 2

End Point:

E driveway #3637

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name:

T/V

Date:

4-8-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

12
11

Street Name:

Compliant

Non-Compliant

From

To

From

To

Code

Comments

		8+53	8+74	8+74	8+90	CS	
		8+90	9+22	9+22		DS	3626
				9+22	9+33	CS	
		9+33	9+57	9+57		VC	
		9+57	10+28	10+28	10+36	CS	
		10+36	12+03	12+03		VC	
		12+03	12+69	12+69	12+78	CS	
		12+78	15+19	15+19		DS	3644
				15+19	15+35	CS	
		15+35	15+44	15+44		VC	
		15+44	15+93	15+93		VC	
		15+93	16+10	16+10	16+30	CS	
				16+30		DS	3639
				16+30	16+61	CS	
		16+61	16+73	16+73	16+77	CS	
		16+77	16+95				

E driveway
#3637

453SB

Start Point:

Denison St / Sugar Loaf Pkwy.

Sidewalk Inventory

193

4525a

End Point:

Direction of Increasing Station:

Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTS

Date: 4/8/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

1111 1111

Street Name:

Compliant

Non-Compliant

From

To

From

To

Code

Comments

Sugar Loaf Pkwy	0+00	0+42	0+42	0+54	CS	
	0+54	0+87	0+87	2+87	VC	greater than 1/2" lip
	0+87	1+75	1+75	1+88	CS	
			1+88	1+88	DS	3605 MB
			1+88	1+98	CS	
	1+98	2+05	2+05	2+05	VC	> 1/2" lip
	2+05	2+45	2+45	2+45	VC	> 1/2" lip
	2+45	3+40	3+40	3+40	VC	" " "
	3+40	3+75				
ELGIN La	0+00	0+84	0+84	0+84	VC	" " " "
	0+84	2+91	2+91	2+91	VC	" " " "
	2+91	3+33	3+33	3+33	VC	" " " "
	3+33	3+46	3+46	3+46	VC	" " " "
	3+46	3+56	3+56	3+65	VC CS	

3+65	3+65	DS	3621 MB
3+65	3+74	CS	

4525a

Start Point: Demison St, / Sugar Loaf Pkwy ^{Sidewalk Inventory} **273** 

End Point: _____

Direction of Increasing Station: Left

452sb

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTD
Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
ELgin La.	3+74	4+10	4+10	4+19	CS	
			4+19	4+19	DS	3623
			4+19	4+31	CS	
	4+31	4+57	4+57	4+67	CS	
	4+67	4+83	4+83	4+83	VC	greater than 1/2" Lf
	4+83	5+14	5+14	5+18	CS	
ELgin La. (2) 3623	0+00	0+52	0+52	0+52	VC	" " " "
	0+52	1+14	1+14	1+14	VC	" " " "
	1+14	3+25	3+25	3+25	VC	" " " "
	3+25	4+55	4+55	4+55	VC	" " " "
	4+55	4+76	4+76	4+76	VC	" " " "
	4+76	4+99	4+99	5+09	CS	3631
			5+09	5+09	DS	3631 MB
			5+09	5+18	CS	

452sb

Start Point: Denison St / Sugar Corn & PK Sidewalk Inventory

452 So

End Point:

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: W3T
Date: 7/8/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:

Compliant

From

To

Non-Compliant

From

To

Code

Comments

[illegible]

452sc

Start Point: Elgin Lane / Sidewalk Inventory Devison Street (Left)

4515

End Point: Devison Street

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/W
Date: 4-8-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 8 ~~111~~ 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Devison St.	0+00	1+03	1+03		VC	
	1+03	1+36	1+36		VC	
	1+36	4+43	4+43		VC	
	4+43	5+24	5+24	5+73	CS	
	5+73	5+91	5+91		DS	9308
			5+91	6+01	CS	
	6+01	6+21	6+21	6+33	CS	
	6+33	6+79	6+79	7+08	CS	
	7+08	11+26				
Devison St.	11+26					

4515

Start Point: Spicebush Way / Sugarleaf Pkwy Sidewalk Inventory

End Point: Kendall Lane

Direction of Increasing Station:

Inspector Name:

Date:

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:

From

To

From

To

Code

Comments

[illegible]

450s

Start Point: Kendall Lane / ^{Sidewalk Inventory} Spicebush Way (Left)

End Point: Kendall Drive

4495

Direction of Increasing Station: _____

Inspector Name: T/W
 Date: 9-8-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

2

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Spicebush Way	0+00	0+21	0+21		VC	
	0+21	0+64	0+64	0+76	CS	
			0+76		DS	3720
			0+76	0+91	CS	
	0+91	2+46				
Kendall Drive	2+46					

4495

(Left)

4485a

Start Point: Kendall Drive / Kendall Lane Sidewalk Inventory
 End Point: Triton Lane

Pg 1 of 2

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/W
 Date: 7-8-17

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 1111 1111 1111 15

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Kendall Lane	0+00	6+39	0+39		PO	TREE
	0+39	0+65	0+65		DS	3724 3724
			0+65	0+80	CS	
	0+80	1+31	1+31		DS	3803
			1+31	1+45	CS	
	1+45	2+92	2+92		VC	
	2+92	3+04	3+04		VC	
	3+04	4+84	4+84		DS	3813
			4+84	4+93	CS	
	4+93	6+27	6+27		VC	
	6+27	9+22	9+22		VC	
	9+22	10+16	10+16		VC	
	10+16	11+08	11+08	11+23	CS	
			11+23		DS	3829

4485a

4485b

(Left)

Start Point: Kendall Drive / Kendall Lane Sidewalk Inventory

End Point: Triton Lane

pg 2 of 2

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/W

Date: 7-8-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

(9)

Total Number of Driveways: ~~111~~ 1111


Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
			11+23	11+40	CS	
	11+40	12+32	12+32		VC	
	12+32	14+64	14+64	14+75	CS	
	14+75	14+93	14+93		VC	
	14+93	17+29	17+29		VC	
	17+29	17+42	17+42		VC	
	17+42	17+60	17+60		VC	
	17+60	18+64				
Triton Lane	18+64					

4485b

Start Point: Elgin La. / Denison St. Sidewalk Inventory

End Point: Denison St.

Direction of Increasing Station: Rt.



4475

1297

Reason Codes for NON-COMPLIANCE:

Inspector Name: T.W.J.
Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Denison St.	0+00	0+17	0+17	0+17	VC	greater than 1/2" Lip
	0+17	0+62	0+62	0+62	VC	" " " "
	0+62	1+59	1+59	1+59	VC	" " " "
	1+59	2+09	2+09	2+09	VC	" " " "
	2+09	2+17	2+17	2+17	VC	" "
	2+17	2+83	2+83	2+83	VC	" "
	2+83	3+08	3+08	3+08	VC	" "
	3+08	3+88	3+88	3+88	VC	" "
	3+88	5+50	5+50	5+50	VC	" "
	5+50	5+82	5+82	5+82	VC	" "
	5+82	8+74	8+74	8+74	VC	" "
	8+74	9+39	9+39	9+57	CS	
Elgin La / Denison St	9+57	12+97				
Denison St.						

12+97

4475

Sidewalk Inventory

Start Point: Spice Bush way / Sugar Corn f. PKW

End Point: Spice Bush Dr.

4465

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTS

Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugar Corn f. PKW	0+00	0+58	0+58	0+78	CS	
	0+78	1+52	1+52	1+52	VC	greater than 1/2" up
	1+52	1+69	1+69	1+69	VC	" " " "
	1+69	1+99	1+99	1+99	VC	" " " "
	1+99	2+86	2+86	2+90	CS	
	2+90	3+35	3+35	3+58	CS	
			3+58	3+61	CS	Panel 7 Ramp Replacement
Spice Bush Dr.						
361						

4465

Start Point: Ken Dall Dr. Sidewalk Inventory / Spice Bush Dr.

445Sa

End Point: _____

Direction of Increasing Station: RT

Pg. 1 of

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWJ
Date: 4/8/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Spice Bush Dr.	0+00	1+10	1+10	1+19		Ramp middle sidewalk ²
	1+19	1+27	1+27	1+27	VC	greater than 1/2" gap
	1+27	1+79	1+79	1+79	VC	" " " "
	1+79	2+79	2+79	2+79	VC	" " " "
	2+79	3+59	3+59	3+59	VC	" " " "
	3+59	4+58				
Spice Bush Dr. ²	0+00	1+30	1+30	1+30	VC	" " " "
	1+30	2+25	2+25	2+25	VC	" "
	2+25	2+65	2+65	2+74	CS	
	2+74	2+82	2+82	2+92	CS	
	2+92	3+46	3+46	3+55	CS	
	3+55	3+88	3+88	4+09	CS	
			4+09	4+09	DS	@ 38/6
			4+09	4+22	CS	

Start Point: Kendall Dr / Spicebush Dr. / 2nd mile after Spine Dr ③

End Point: Triton LA

Direction of Increasing Station: R+

4455b

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWJ
Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: |||||

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	4+22	5+36	5+36	5+36	VC	greater than 1/2" Lip
	5+36	5+48	5+ 48 48	5+57	CS	
			5+57	5+57	DS	@ 3820
			5+57	5+66	CS	
	5+66	5+98	5+98	6+02	CS	
	6+02	6+39	6+39	6+43	CS	
	6+43	6+90	6+90	6+94	CS	Replace block
	6+94	7+85	7+85	7+85	VC	> 1/2" Lip
	7+85	9+66	9+66	9+66	VC	
Triton LA	9+66	11+88				
11+88						

4455b

Sidewalk Inventory

Start Point: Gulford Dr @ Bucklestown Pike R

End Point: New Design Pk.

~~4445a~~

4445a

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 9/8/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bucklestown			0+00	0+46	CS	
	0+46	2+58	2+58	2+58	PO	tree
	2+58	4+03	4+03	4+11	CS	
Entrance 1	0+00	1+28	1+28	1+44	CS	
	1+44	2+90	2+90	-	VC	
Entrance 2	0+00	1+65	1+65	1+74	CS	
Frederick Crossing			0+00	0+86	CS	
	0+86	1+53	1+53	2+15	CS	
	2+15	3+02	3+02	3+34	CS	
Entrance 3	0+00	0+18	0+18	0+60	CS	
	0+60	1+67	1+67	1+81	CS	
	1+81	2+16	2+16	3+82	CS	
	3+82	4+07				
Industry Ln			0+00	0+17	CS	

4445a

44456

T4A35

Direction of Increasing Station:

Inspector Name: 022A
Date: 4/8/14

PO Protruding Object

Total Number of Driveways: 0

Non-Compliant

From

To

From

To

Code

Comments

[illegible]

T 4435

4425

Sidewalk Inventory

Start Point: HUTA Spectrum Dr (H6626/11) @ 1-85 (L)End Point: Holiday Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/8/14VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding ObjectDS Driveway Cross Slope
CS Panel Cross Slope
WP Width of PanelTotal Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
1-85 (Bob Evans)			0+00	0+05	VC	
	0+05	2+63				
Holiday Dr.	0+00	5+07				
5595, 5597, 5595 Spectrum	0+00	2+63				
Lowes Ln			0+00	0+05	VC	
	0+05	1+62				
5605 / 5609 Spectrum	0+00	0+81	0+81	1+01	CS	
	1+01	2+09	2+09	2+92	CS	
	2+92	3+05				
5611 Spectrum (Applebee's)	0+00	1+80	1+80	—	VC	
	1+80	1+88	1+88	—	VC	
	1+88	3+12				
5617 Spectrum	0+00	3+70				End

4425

Start Point: Lowes Ln @ Spectrum Dr. 4

End Point: RT 355

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: DZ KA
Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Compliant

Non-Compliant

Street Name:

From

To

From

To

Code

Comments

4415

4405

Sidewalk Inventory

Start Point: Lowe's Ln @ Spectrum Dr. R

End Point: 355 RT

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Spectrum			0+00	0+13	CS	
	0+13	1+14	1+14	1+41	CS	
	1+41	1+93				
Entrance 1	0+00	2+23	2+23	—	VC	
	2+23	2+32	2+32	—	VC	
	2+32	2+120				End

4405

Sidewalk Inventory
Start Point: Holiday Dr @ 355 RT

(2)

4395

End Point: Spectrum Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ LA
Date: 4/18/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
355 RT	0+00	1+21	1+21	1+26	CS	
0681 Spectrum (Golden Corral Entrance)	0+00	1+26				End

4395

Sidewalk Inventory

Start Point: ~~then~~ Guilford Dr. @ Buckeystown Pike (4)

End Point: Entrance 2

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA

Date: 4 8 14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Compliant

Non-Compliant

Street Name:

From

To

From

To

Code

Comments [illegible]

4385

Sidewalk Inventory *lane*

Start Point: Frederick Crossing @ Guilford Dr L

End Point: Entrance 4

4375

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KA
 Date: 4/18/14

VC Vertical Clearance DS Driveway Cross Slope
 PP Pinch Point CS Panel Cross Slope
 PZ Passing Zone WP Width of Panel
 PO Protruding Object

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Guilford Dr.			0+00	0+13	CS	
	0+13	2+07	2+07	—	VC	
	2+07	2+28				
Entrance 1			0+00	0+09	CS	
	0+09	1+20				
Entrance 2	0+00	4+34				
Entrance 3	0+00	2+44				End

4375

165



Start Point: Crestwood Blvd @ Hamner Dr

End Point: Ballenger Creek Pike

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF & SC
Date: 4-4-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

(LT)

Street Name: <u>Crestwood Blvd</u>	Compliant		Non-Compliant		Code	Comments
From	To	From	To			
<u>Hamner Dr</u>		<u>0+00</u>	<u>0+11</u>	<u>CS</u>		
	<u>0+11</u>	<u>0+34</u>				
<u>Shopping Center Ent #1</u>	<u>0+00</u>	<u>0+27</u>	<u>0+27</u>	<u>/</u>	<u>VC</u>	
	<u>0+22</u>	<u>1+33</u>	<u>1+33</u>	<u>1+45</u>	<u>CS</u>	
	<u>1+45</u>	<u>1+59</u>				
<u>Shopping Center Ent #2</u>	<u>0+00</u>	<u>1+83</u>				<u>END @ Ballenger Creek Pike</u>

14365

Bluel

Sidewalk Inventory

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

S: 

Compliant

Non-Compliant

Street Name:

From

To

From

To

Code

Comments

[illegible]

4355

Start Point: John Simmons Street / Sugarloaf Pkwy (Right) pg 1 of 2
 End Point: 9 C-0-3

Direction of Increasing Station: _____

4345a

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/W

Date: 7-4-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 111 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugarloaf Pkwy	0+00	1+09	1+09		VC	
	1+09	1+94	1+94		VC	
	1+94	2+40	2+40		VC	
	2+40	2+51				
Hendry Terra			0+00		VC	
	0+00	0+08	0+08		VC	
	0+08	0+25	0+25		VC	
	0+25	1+69	1+69	1+81	CS	
John Simmons Ct.	0+00	1+76	1+76		VC	
	1+76	1+88	1+88		VC	
	1+88	2+05	2+05		VC	
	2+05	2+66	2+66		VC	
	2+66	4+26	4+26		VC	
	4+26	4+43	4+43		VC	

4345a

Start Point: John Simmons Street / Superlat Pkwy (Right) pg 2 of 2
End Point: E of C-D-S

End Point: E of C-D-S

434SL

Inspector Name: T/W
Date: 4-04-19

Date: 4-04-19

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Non-Compliant

From

To

From

To

Code

Comments

[illegible]

434sb

(Circle)

Start Point: John Simmons Court / John Simmons Street (Right)

4335

End Point: John Simmons St.

Direction of Increasing Station: _____

Inspector Name: T/w

Date: 4-4-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: |||||

8

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
John Simmons St.			0+00	0+11	CS	
	0+11	1+16 1+16	1+16		DS	3602
			1+16	1+23	CS	
	1+23	1+47	1+47		VC	
	1+47	2+25	2+25		VC	
	2+25	2+29	2+29	2+60	CS	
	2+60	3+03	3+03		VC	
	3+03	3+06	3+06	3+14	CS	
	3+14	3+63	3+63	3+68	CS	
	3+68	4+38	4+38	4+63	CS	
	4+63	7+32				
John Simmons St.	7+32					

4335

Start Point: Hendry Terrace / Sugarloaf Pkwy (Left) pg 1 of 3
 End Point: Johna Simmons St. 4325a

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/V
 Date: 4/4/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 1111 (4)

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugarloaf Pkwy			0+00	0+05	CS	
	0+05	0+60	0+60		VC	
	0+60	0+86	0+86		VC	
	0+86	1+28	1+28	1+341	CS	Ramp
	1+41	2+91	2+91		VC	
	2+91	3+55	3+55		VC	
	3+55	3+67	3+67		VC	
	3+67	3+95	3+95		VC	
	3+95	4+35	4+35		VC	
	4+35	4+44	4+44		VC	
	4+44	4+68	4+68		VC	
	4+68	4+81	4+81		VC	
	4+81	5+07	5+07		VC	
	5+07	5+16	5+16		VC	

4325a

Start Point: Hardy Terrace / Sidewalk Inventor Pkwy (Left)
 End Point: John Simmons St.

pg 2 of 3

432sb

Direction of Increasing Station: _____

Inspector Name: T/V
 Date: 4-9-19

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

4

Total Number of Driveways: 1111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+16	5+27	5+27		VC	
	5+27	5+47	5+47		VC	
	5+47	5+59	5+59		VC	
	5+59	5+78	5+78		VC	
	5+78	5+86	5+86		VC	
	5+86	6+07	6+07		VC	
	6+07	6+18	6+18		VC	
	6+18	6+27	6+27		VC	
	6+27	6+63	6+63		VC	
	6+63	6+86	6+86		VC	
	6+86	7+71	7+71		VC	
	7+71	8+01	8+01		VC	
	8+01	8+12	8+12		VC	
	8+12	8+51	8+51		VC	

432sb

Start Point: Henry Terrace / Sugarloaf Pkwy Sidewalk Inventory

Sidewalk Inventory

(Left)

pg 3 of 3

End Point: John Simons St.

4325c

Direction of Increasing Station:

Inspector Name:

Date:

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

[illegible]

43250

Start Point: SP 5199 St. / ^{South.} Sidewalk Inventory Worthy Lane

End Point: Urbyana Pike

Direction of Increasing Station: Left Right

Inspector Name: T.J.
Date: 4/4/14

PO Protruding Object

Total Number of Driveways: 0

4315

Start Point: Hinks Lane / Sugarleaf Pkwy (Rt.)
 End Point: Rine's Tavern Lane

430S

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/W
 Date: 4-3-14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugarleaf Pkwy			0+00	0+35	CS	
	0+35	0+90	0+90	1+00	CS	
	1+00	1+15				
"Bank Entrance"	0+00	0+05	0+05	0+19	CS	
	0+19	0+52	0+52 0+52	0+76	CS	
	0+76	0+86	0+86	0+95	CS	
	0+95	1+05	1+05	1+22	CS	
	1+22	2+02	2+02	2+12	CS	
	2+12	2+27				
Rine's Tavern Ln	2+27					

430S

(937)


 Start Point: Sprigg St. South / Urbana Pike

End Point: _____

4295

 Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Total Number of Driveways: _____

 Inspector Name: J. T.

 Date: 4/4/14

Compliant

Non-Compliant

Street Name:

From

To

From

To

Code

Comments

Urbana Pike	0+00	0+91				
Sprigg Alky	0+00	0+72	0+72	0+72	VC	Greater than 1/2" Lip
	0+72	1+27				
Sprigg Alky #2	0+00	0+49	0+49	0+53	CS	
McPherson St.	0+00	0+75	0+75	0+75	VC	" " " "
	0+75	2+19				
Washington						
6437						

4295

4285

4275

Right

pg. 1 of 4

1155

Start Point: Hendry Terr. / Sugarloaf Parkway

End Point:

Direction of Increasing Station:

Right

pg. 1 of 4

4245a

Reason Codes for NON-COMPLIANCE:

Inspector Name: J.T. W
Date: 4-4-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugarloaf Pkwy			0+00	0+56	CS	greater than 1/2" Lip
	0+56	0+95	0+95	0+95	VC	" "
	0+95	1+87	1+87	1+87	VC	" "
	1+87	2+10	2+10	2+10	VC	" "
	2+10	2+26	2+26	2+26	VC	" "
	2+26	2+49	2+49	2+49	VC	" "
	2+49	2+93	2+93	2+93	VC	" "
	2+93	4+19	4+19	4+26	DS	@ 9109
			4+26	4+43	CS	
	4+43	4+75	4+75	4+85	CS	
	4		4+85	4+85	DS	@ 9111
	4		4+85	4+94	CS	
	4+94	5+14	5+14	5+14	VC	7 1/2" Lip
	5+14	5+35	5+35	5+35	VC	" "

4245a

Right ✓

Pg. 2 of 4

Start Point: Hendry Terr / Sugarloaf Parkway

End Point: 424sb

Direction of Increasing Station: Right Pg 2 of 4

Reason Codes for NON-COMPLIANCE:

Inspector Name: J.T. W
Date: 4-4-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+35	5+77	5+77	5+77	VC	greater than 1/2" Lip
	5+77	5+97	5+97	5+97	VC	" "
	5+97	6+23	6+23	6+23	VC	" "
	6+23	6+31	6+31	6+31	VC	" "
	6+31	6+39	6+39	6+39	VC	" "
	6+39	6+65	6+65	6+65	VC	" "
	6+65	7+35	7+35	7+35	VC	" "
	7+35	7+55	7+55	7+55	VC	" "
	7+55	7+66	7+66	7+66	VC	" "
	7+66	7+87	7+87	7+87	VC	" "
	7+87	8+39	8+39	8+39	VC	" "
	8+39	8+54	8+54	8+54	VC	" "
	8+54	8+72	8+72	8+72	VC	" "
	8+72	8+83	8+83	8+83	VC	" "

424sb



Start Point: Hendry Terr. / Sugarloaf Pkwy.

End Point: _____

pg. 3 of 4

424Sc

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T. J. W.
Date: 4-4-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	8+83	8+91	8+91	8+91	VC	greater than 1 1/2" lip
	8+91	8+95	8+95	8+95	VC	" "
	8+95	9+04	9+04	9+04	VC	" "
	9+04	9+42	9+42	9+42	VC	" "
	9+42	9+62	9+62	9+71	CS	
			9+71	9+71	DS	@ 9/27
			9+71	9+80	CS	
	9+80	9+92	9+92	9+92	VC	" "
	9+92	10+00	10+00	10+00	VC	" "
	10+00	10+16	10+16	10+16	VC	" "
	10+16	10+32	10+32	10+32	VC	" "
	10+32	10+41	10+41	10+41	VC	" "
	10+41	10+52	10+52	10+52	VC	" "
	10+52	11+01	11+01	11+01	VC	" "

424Sc

Sidewalk Inventory

pg 4 of 4

Start Point: Hendry Terr / Sugarloaf Pkwy.

End Point: ~~RE~~

pg 4 of 4

424sd

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T.J.W
Date: 4-4-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	11+01	11+09	11+09	11+09	VC	greater than 1/2" Lip
	11+09	11+20	11+20	11+20	VC	" "
	11+20	11+28	11+28	11+28	VC	" "
	11+28	11+41	11+41	11+41	VC	" "
John Simmons St 11+41			11+41	11+55	CS	
11+55						

424sd

Start Point: John Simmons St

Sidewalk Inventory

Sugan Lant. Pkwy

194
4235a

End Point: _____

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: TWS

Date: 4/4/14

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Sugan Lant. Pkwy</u>	0+00	0+20	0+20	0+20	VC	Crack thru 1/2" wj.
	0+20	0+28	0+28	0+28 ³²	CS	
	0+32	0+49	0+49	0+53	CS	
	0+53	0+81	0+81	0+93	CS	
	0+93	1+05	1+05	1+05	VC	" " "
	1+05	1+17				
<u>White Hope Commons Ct</u>	0+00	0+11	0+11	0+11	VC	" " "
	0+11	0+20	0+20	0+20	VC	
	0+20	0+31	0+31	0+31	VC	
	0+31	0+71	0+71	0+71	VC	" " "
	0+71	0+91	0+91	0+91	VC	
	0+91	1+31	1+31	1+31	VC	
	1+31	1+43	1+43	1+43	VC	" " "
	1+43	1+70	1+70	1+70	VC	" " "
	1+70	1+70	1+70	1+70	VC	

4235a1

294

Start Point: John Simmons St. / Sugar Land Pkwy

4235b

End Point: _____

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTS
Date: 4/4/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	1+70	1+90	1+90	1+90	VC	Greater than 1/2" Lip.
	1+90	2+13	2+13	2+13	VC	" " " "
	2+13	2+60	2+60	2+60	VC	" " " "
	2+60	2+97	2+97	2+97	VC	
	2+97	3+36	3+36	3+36	VC	
	3+36	3+52	3+52	3+65	CS	
			3+65	3+65	DS	9104 M box
			3+65	3+82		
	3+82	4+34	4+34	4+43	CS	
			4+43	4+43	DS	9106
			4+43	4+52		
	4+52	4+97	4+97	4+97	VC	> 1/2" Lip.
	4+97	5+06	5+06	5+19	CS	
			5+19	5+19	DS	MB 9108
			5+19	5+29	CS	

4235b

374

423SC

Start Point: John Simmons St Sidewalk Inventory/ Suzan Court Pl.

End Point: _____

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWJ
Date: 4/4/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 4

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+29	5+57	5+57	5+81	CS	
			5+81	5+81	DS	MB 9110
			5+81	6+07	CS	
	6+07	6+15	6+15	6+23	CS	
	6+23	6+32	6+32	6+41	CS	
			6+41	6+41	DS	
			6+41	6+50	CS	
	6+50	6+59	6+59	6+59	VC	Greater than 1/2" Lip.
	6+59	7+53	7+53	7+53	VC	" " " "
	7+53	7+92	7+92	7+92	VC	" " " "
	7+92	8+06	8+06	8+06	VC	" " " "
	8+06	8+54	8+54	8+63	CS	
			8+63	8+63	DS	9118
			8+63	8+72	CS	

423SC

4235d

1162

Start Point: Bush Creek Dr / Cleunden Way

End Point: Major Smith Ln.

4225

Direction of Increasing Station: RT.

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTS
Date: 4/4/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Cleunden Way			0+00	0+08	CS	
	0+08	0+53	0+53	0+53	VC	Breaker Run 1/2" Lip
	0+53	1+02	1+02	1+02	VC	" " " "
	1+02	1+38	1+38	1+38	VC	" " " "
	1+38	1+54	1+54	1+54	VC	" " " "
	1+54	1+62	1+62	1+62	VC	
Major Smith Ln						
1+62						

4225 ✓

Start Point: Bush Creek Dr. / Sprigg Street N.

End Point: Clendenin Way

4215

Direction of Increasing Station: Rt.

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTS
Date: 4/4/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sprigg St. N.	0+00	0+32	0+32	0+32	VC	greater than 1/2" Lip.
	0+32	0+51	0+51	0+51	VC	" " " "
	0+51	0+92	0+92	0+92	VC	" " " " note TRIM TREE
	0+92	1+16	1+16	1+16	VC	" " " "
1+81	1+16	1+81				
Harris Street	0+00	0+43	0+43	0+43	VC	" " " "
	0+43	1+30	1+30	1+30	VC	" " " "
	1+30	1+73	1+73	1+73	VC	" " " "
	1+73	2+02	2+02	2+02	VC	
	2+02	2+11	2+11	2+11	VC	
	2+11	2+23	2+23	2+23	VC	
	2+23	2+33	2+33	2+37	CS	
Clendenin Way						
2+37						

4215

Start Point: Bush Creek Dr. / Bush Creek Circle

4205

End Point: Spring St. North

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWJ
Date: 4/4/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Circle	0+00	0+22	0+22	0+22	VC	greater than 1/2" Lip
	0+22	0+56	0+56	0+56	VC	" "
	0+56	1+12	1+12	1+12	VC	" "
	1+12	1+90	1+90	1+98	CS	tree - sidewalk replacement between 3830 & 3828
	1+98	2+37	2+37	2+37	VC	7 1/2" lip
	2+37	2+45	2+45	2+59	CS	
			2+59	2+59	DS	MB 3826
			2+59	2+68	CS	
	2+68	3+26	3+26	3+26	VC	7 1/2" Lip
Seward La	3+26	4+04				
4205	0+00	1+15	1+15	1+15	VC	" "
	1+15	1+27	1+27	1+27	VC	" "
	1+27	1+84	1+27	1+27	B	
Spring St. North						

1111 (4)

No Driveways

4205

1+84

192

Start Point: Bush Creek Circle / Bush Creek Dr

End Point: Bush Creek Dr

4195a

Direction of Increasing Station: Rt.

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____
Date: 4/4/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 1111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Dr.	0+00	0+32	0+32	0+32	VC	gravel to 1/2" up
	0+32	0+87	0+87	0+87	VC	" " " "
	0+87	2+26	2+26	2+26	PZ	manhole depressed?
	2+26	2+53	2+53	2+53	VC	> 1/2" up
	2+53	3+26	3+26	3+26	VC	" " "
	3+26	3+34	3+34	3+34	VC	" " "
	3+34	3+82	3+82	3+82	VC	" " "
	3+82	4+17	4+17	4+17	VC	" " "
	4+17	4+65	4+65	4+65	VC	" " "
	4+65	5+42	5+42	5+58	CS	
	5+58	7+64	7+64	7+64	VC	
			7+64	7+64	VC	
	7+64	7+69	7+64	7+69	VC	
			7+69	7+69		

4195a

○

272

1267

Start Point: Bush Creek Circle / Bush Creek Dr

End Point: Bush Creek Circle / Bush Creek Dr

4195b

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWS
Date: 4/4/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	7+69	9+58	9+58	9+58	VC	Greater than 1/2" Gf.
	9+58	9+96	9+96	9+96	VC	" " " "
	9+96	11+45	11+45	11+45	VC	" " " "
	11+45	11+73	11+73	11+73	VC	" " " "
	11+73	11+90	11+90	11+90	VC	" " " "
	11+90	12+03	12+03	12+03	VC	" " " "
	12+03	12+67				
Bush Creek Dr.						
Circle						
12+67						

4195b

Start Point: Bush Creek Drive / Bush Creek Circle ^{Sidewalk Inventory}
 End Point: Sugarloaf Pkwy

(Left)

pg 1 of 2
 4185a

Direction of Increasing Station: _____

Inspector Name: T/W
 Date: 4-4-14

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 44 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek	0+00	2+14	2+14		VC	
Circle	2+14	2+80	2+80	2+92	CS	
	2+92	3+01	3+01		VC	
	3+01	3+34	3+34		VC	
	3+34	3+42	3+42		VC	
	3+42	3+88	3+88		VC	
	3+88	4+33	4+33		VC	
	4+33	7+68	7+68		VC	
	7+68	8+18	8+18		VC	
	8+18	8+34	8+34		VC	
	8+34	9+33				
TRAVENER Circle	0+00		0+00	0+08	CS	
	0+08	0+67	0+67		VC	
	0+67	3+21	3+21	3+33	CS	

4185a

Start Point: Bush Creek Drive / Bush Creek Circle (Left)
 End Point: Sugarloaf Pkwy

pg 2 of 2

418SB

Direction of Increasing Station: _____

Inspector Name: T/W
 Date: 4-4-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: _____

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+33	3+54				
Travener Circle	0+60	0+63				
sidewalk	0+63					
Dead ends						
Towards						
Sugarloaf Pkwy						

418sb

Start Point: Bush Creek Drive / Major Smith Lane ^{Sidewalk Inventory} (Right)

End Point: Sugarloaf Pkwy 4175

Direction of Increasing Station: _____

Inspector Name: T/W

Date: 4-4-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Major Smith Lane	0+00	0+66	0+66		VC	
	0+66	3+27	3+27		VC	
	3+27	4+43	4+43		VC	
Sugarloaf Pkwy	4+43	5+92				
	5+92					

4175

Start Point: Bush Creek Circle / Bush Creek Drive (Left)
 End Point: Bush Creek Drive

pg 1 of 2

Direction of Increasing Station: _____

4165a

Inspector Name: T/W

Date: 4-4-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

(19)

Total Number of Driveways: |||||

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Dr.	0+00	0+23	0+23		VC	
	0+23	2+66	2+66		DS	9006
			2+66	2+75	CS	
	2+75	3+21	3+21		VC	
	3+21	3+44	3+44		DS	9008
			3+44	3+53	CS	
	3+53	5+38	5+38		VC	
	5+38	5+49	5+49		VC	
	5+49	7+05	7+05		VC	
	7+05	9+06	9+06		VC	
	9+06	10+87	10+87	10+97	CS	
	10+97	12+31	12+31		VC	
	12+31	12+87	12+87		DS	9034
			12+87	12+98		

4165a

Start Point: Bush Creek Circle / Bush Creek Drive (Left)
 End Point: Bush Creek Dr.

pg 2 of 2
 4165b

Direction of Increasing Station: _____

Inspector Name: T/w
 Date: 4-4-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

②

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	12+98	13+12	13+12		VC	
	13+12	13+23	13+23		VC	
	13+23	14+32	14+32		DS	9038
			14+32	14+46	CS	
	14+46	15+85				
Bush Creek Dr.	15+85					
(House #3829)						

4165b

4145

Start Point: BANK CT @ CRESTWOOD DR

End Point: Private

Direction of Increasing Station: LT + RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: CM RH
Date: 4/3/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>CRESTWOOD</u>	<u>0+00</u>	<u>1+50</u>	<u>1+50</u>	<u>1+61</u>	<u>CS</u>	
<u>PRIVATE</u>	<u>1+61</u>	<u>1+89</u>				
<u>CRESTWOOD</u>	<u>10+00</u>	<u>1+50</u>				
<u>PRIVATE</u>						

Not sure
about these
L + Rs -
Check-

4145

End Point: DEAD END

5

PO Protruding Object

Date: 4/3/14

Total Number of Driveways: 0

Non-Compliant

Comments

4133

Start Point:

President's @ Corporate

Sidewalk Inventory

4125

End Point:

Direction of Increasing Station:

RT

Reason Codes for NON-COMPLIANCE:

Inspector Name:

CM, RH

Date:

4/3/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Corporate Dr	0+00	2+94				
Private Dr 1	0+00	2+21				
" " 2	0+00	0+27				
" " 3	0+00	0+64				
" " 4	0+00	0+00	00+00	0+10	CS	
	0+10	3+51	3+51	3+78	CS	
	3+78	3+97				
Private Dr 5	0+00	1+88				
Corporate Dr						

4125

4115

Start Point: CHAIRMAN'S Sidewalk Inventory @ Corporate Dr

End Point: " " " "

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: RA, CM
Date: 4/3/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Corporate Dr	0+00	0+64	0+64	0+84	CS	
	0+84	1+25	1+25	1+38	CS	
	1+38	1+38				
Private Dr 1	0+00	0+20				
Private Dr 2	0+00	0+66				
Private Dr 3	0+00	0+71				
Private Dr 4	0+00	2+12				
Corporate Dr						

4115

4100

DR
 Start Point: CORPORATE @ NEW DESIGN RD
 End Point: CRESTWOOD DR

Direction of Increasing Station: LT

Reason Codes for NON-COMPLIANCE:

Inspector Name: L H C M
 Date: 4/3/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
NEW DESIGN	0+00	0+00	0+00	0+25	CS	
	0+25	2+86	2+86	3+86	CS	
	3+86	4+62	4+62	4+83	CS	
	4+83	4+83				
ACROSS FROM CHARMANS CT	0+00	3+96	3+96		VC	
	3+96	4+12	4+12	4+42	CS	
	4+42	5+67	5+67	5+93	CS	
	5+93	6+04				
ACROSS FROM PRESIDENTS CT	0+00	0+20	0+20	0+76	CS	
	0+76	1+46	1+46		VC	
CRESTWOOD DR	1+46	2+56				

4105

4095

Sidewalk Inventory

Start Point: CHESTWOOD BLVD @ Corporate Dr

End Point: @ 85

Direction of Increasing Station: LT

Reason Codes for NON-COMPLIANCE:

Inspector Name: RH CM
Date: 4/3/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Corporate	0+00	0+39	0+39	0+49	CS	
	0+49	1+40	1+40	1+70	CS	
	1+70	2+05	2+05	2+44	CS	
	2+44	2+70	2+70	3+01	CS	
	3+04	4+66	4+66	5+01	CS	BIG HEAVE
	5+01	5+24	5+24	5+36	CS	
RT 85	5+36	5+87				

4095

4085

Start Point: Ladd LN @ NEW DESIGN RD

End Point: PRIVATE

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: CM, CH
Date: 4/3/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
New Design Rd	0+00	0+57	0+57	0+67	CS	
	0+57	1+57				
LADD CT	0+00	0+19	0+19		VC	
	0+19	1+38	1+38		VC	
	1+38	1+51	1+51	1+74	CS	
PRIVATE	1+74	2+11				

4085

Sidewalk Inventory

4075

Start Point: Ballinger Creek Pike @ Lambert Dr

End Point: Corporate Dr

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: RTN

Date: 2-3-14

Total Number of Driveways:

Street Name: Ballinger Creek Pk	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Lambert Dr	0+00	1+25				Dead END
Tuscarora High Ex	0+00	2+26	2+26	3+56	CS	Separate Driv
	3+56	6+92	6+92	/	VC	Large Crack
	6+92	10+45	10+45	/	VC	Concrete 5'
	10+45	10+91	10+91	/	VC	
	10+91	13+62	13+62	/	VC	
	13+62	15+02				END @ Corporate Dr

4075

Sidewalk Inventory

1 of 2
4065a

Start Point: Ballenger Creek Pike @ Lambert Dr

End Point: Tuscorora High ENT.

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: RF/OZ

Date: 6-3-14

Total Number of Driveways:

LT

Street Name: Ballenger Creek	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Lambert Dr	0+00	1+27	1+27	3+50	CS	
	3+50	6+05	6+05	6+33	CS	
	6+33	6+42	6+42	—	VC	
	6+42	6+58	6+58	11+08	CS	
		10+57	10+57	—	VC	(Ramp to Nowhere)
	11+08	11+48	11+48	12+09	CS	
	12+09	13+19	13+19	13+04	CS	
	13+24	13+99	13+89	14+34	CS	
	14+34	14+70				
Ballenger Creek Ct.	0+00	0+04	0+04	0+65	CS	
	0+65	0+65	0+84	1+11	CS	
	1+11	4+18				
Tuscorora High Ent			0+00	0+54	CS	
	0+54	2+38	2+38	4+24	CS	

4065a

End Point: Tussers High Estate

Direction of Increasing Station: up

Inspector Name: BF602
Date: 4-26-14

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Non-Compliant

Street Name: Bullwag Creek Pike From

To

From

To

Code

Comments

[illegible]

4065b

10FZ

4055a

Sidewalk Inventory

Start Point: Corporate Dr @ New Design Rd

End Point: Crestwood Blvd

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BT 30Z

Date: 4-3-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0



Compliant

Non-Compliant

Street Name: Corporate Dr

From

To

From

To

Code

Comments

New Design Rd	0+00	0+70	0+70	1+11	CS	
	1+11	1+51	1+51	—	VC	
			1+51	1+61	CS	
	1+61	1+91	1+91	—	VC	
	1+91	2+01				
Advisors CT	0+00	0+28	0+28	0+44	CS	
	0+44	1+00	1+00	—	PO	Tree
	1+00	1+12	1+12	—	VC	
			1+12	1+24	CS	
	1+24	1+40				
Childcare Ent.	0+00	0+16	0+16	—	VC	
			0+16	0+25	CS	
	0+25	0+45				
Chairman's CT	0+00	2+01				

4055a

2 2 2

4055b

4055b

End Point: Critical End

Direction of Increasing Station: 90

Reason Codes for NON-COMPLIANCE:

Inspector Name: BA 602
Date: 4-3-94

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ: Passing Zone

WP Width of Panel

PO Protruding Object

Total Number of Driveways:

Compliant

Non-Compliant

Street Name: Celebrate Dr

From

To

From

To

Code

Comments

[illegible]

405	sb
-----	----

10F 2

404Sa

Sidewalk Inventory

Start Point: Crestwood Blvd @ Corporate Dr

End Point: RT 85

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: RFE B02

Date: 4-3-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name: Crestwood Blvd	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Corporate Dr	0+00	0+19	0+19	—	VC	
	0+19	2+77	2+77	3+40	CS	
	3+40	4+53				
Corp. Entrance #1	0+00	0+08				
Corp. Entrance #2	0+00	2+65	2+65	2+90	CS	
	2+90	3+20	3+20	3+35	CS	
	3+35	3+60	3+60	4+60	CS	
	4+60	4+84	4+84	4+96	CS	No PZ
	4+96	5+30				
Westview Dr	0+00	0+80	0+80	1+10	CS	5' Sidewalk
	1+10	1+31	1+31	1+46		
	1+46	2+53	2+53	2+73	CS	
	2+73	2+83	2+83	3+93	CS	
	3+93	4+52				

404Sa

Sidewalk Inventory

Start Point: Crestwood Blvd @ Corporate Dr

End Point: 785

Direction of Increasing Station: 0

Reason Codes for NON-COMPLIANCE:

Inspector Name: BT 302
Date: 4-3-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Street Name: Cashmere Blvd

Compliant

From

To

Non-Compliant

From

To

Code

Comments

[illegible]

4045b

PAM see Jerry.

Sidewalk Inventory

Start Point: Hinks La / Sugar Loaf Parkway
 End Point: Hinks La (Side walks in to a circle)
 Direction of Increasing Station: Left

403S

147
65
3.2

Inspector Name: TWS
 Date: 4/3/14

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hinks La	0+00	0+96	0+96	1+18	CS	
Sugar Loaf Pk			1+18	1+18	DS	9114
			1+18	1+39	CS	
1+30	1+39	1+61	1+61	2+03	CS	
	2+03	2+21				
Alley 9155						
9155			0+00	0+21	CS	
	0+21	0+55	0+55	0+81	CS	
Man+2 La.		0+82				
Hink La → Panik circle	0+00	1+47				Trim bushes entire circle
Drive's R. Open McPherson St circle	0+00	1+65				
McPherson St.	0+00	0+74				
Circle Man+2 La	0+00	0+09	0+09	0+09	VC	greater than 1/4" Lip.
circle	0+09	0+68				

Hink La
See Map

Hinks La.

403S

Start Point: TRAVENOR CIRCLE / BUSH CREEK DR.

End Point: _____

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Inspector Name: WTS
Date: 4/3/14

Total Number of Driveways: 1

Street Name: _____

Compliant	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Dr.	0+00	0+81	0+81	0+81	VC	Greater than 1/2" Gap.
	0+81	1+38	1+38	1+38	VC	" " " "
	1+38	2+58	2+58	2+58	VC	" " " "
	2+58	2+73	2+73	2+73	VC	
	2+73	3+35	3+35	3+35	VC	" " " "
	3+35	3+77	3+77	3+77	VC	" " " "
	3+77	4+82	4+82	4+91	CS	
			4+91	4+91	DS	M69111
			4+91	5+00	CS	
	5+00	5+63	5+63	5+63	VC	Greater than 1/2" Gap
	5+63	5+89	5+89	5+89	VC	" "
	5+89	7+13	7+13	7+13	VC	" " " "
	7+13	7+91	7+91	7+91	VC	" " " "
	7+91	8+84	8+84	8+72	CS	

40252

293

Start Point: TRAVANCER in / Bush Creek Dr

Sidewalk Inventory

End Point: _____

4025b

Direction of Increasing Station: Rt.

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____

Date: _____

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Dr.			8+72	8+72	DS	9119. M/SX.
			8+72	9+01	CS	
	9+01	9+55	9+55	9+65	CS	Note 10+06 Trim Tree
	9+65	10+67	10+67	10+75	CS	
	10+75	11+17	11+17	11+17	VC	Greater than 1/2" Gap
	11+17	11+62	11+62	11+62	VC	" " " "
	11+62	12+13	12+13	12+29	CS	(include one Driveway Panel
	12+29	12+34				(DW. - 9/23)
	12+29	12+47	12+47	12+47	VC	Greater than 1/2" Gap.
	12+47	12+84	12+84	12+84	VC	" " " "
	12+84	12+96	12+96	12+96	VC	" " " "
	12+96	13+26	13+26	13+26	VC	" " " "
	13+26	13+42	13+42	13+42	VC	" " " "
	13+42	14+74	14+74	14+74	VC	" " " "

4025b

Start Point: Traverse Cui / Bush Creek Dr Sidewalk Inventory

End Point:

402Sc

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTS

Date: 4/3/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:

Compliant

From

To

Non-Compliant

From

To

Code

Comments

[illegible]

40250

Start Point: Travener Circle / Bush Creek Drive (Left)

End Point: Sidewalk dead ends

Direction of Increasing Station: _____

Inspector Name: T/W

Date: 4-3-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Drive	0+00	2+64	2+64		VC	
	2+64	3+49	3+49		VC	
	3+49	3+68	3+68		VC	
	3+68	4+24	4+24		VC	
	4+24	5+04	5+04		VC	
	5+04	5+48	5+48		VC	
	5+48	5+95	5+95		VC	
	5+95	6+30	6+30		VC	
	6+30	6+62	6+62	6+ 67 ⁷⁶	CS	
			6+76		DS	9116
	6+76	7+34	7+34		VC	
	7+34	7+67	7+67		VC	
	7+67	8+08	8+08		VC	
	8+08	8+36	8+36		VC	

pg 1 of 2
4015a

12

Holsa

Start Point:

Traverse ~~B~~ Circle / Bush Creek Dr. (Left)

End Point:

sidewalk dead ends

pg 2 of 2

401sb

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name:

T/W

Date:

4/3/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

111

③

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	8+36	8+71	8+71		VC	
	8+71	10+08	10+08		VC	
	10+08	10+16	10+16		VC	
	10+16	10+37	10+37		VC	
	10+37	10+68	10+68		DS	9126
	10+68	10+83	10+83		VC	
	10+83	11+47	11+47		VC	
	11+47	11+57	11+57		VC	
	11+57	12+17	12+17		VC	
	12+17	12+70				
Sidewalk dead	12+70					
ENDS						

401sb

Start Point:

Harris St. / Sprigg St. N.

Sidewalk Inventory

Right
1/2

End Point:

Bush Creek DR

4005a

Direction of Increasing Station:

Right 1 of 2

Reason Codes for NON-COMPLIANCE:

Inspector Name:

Tina, Joe Wayne

Date:

4-3-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

11 11 11

(12)

Street Name:

Compliant

From

To

Non-Compliant

From

To

Code

Comments

Sprigg St. N.	0+00	1+47				
Sprigg St. ^{no} / Alley ^{no name} (middle of 9023)	0+00	0+99	0+99	0+99	VC	greater than 1/2" Lip
	0+99	1+61	1+61	1+71	CS	
	1+71	3+09	3+09	3+09	VC	" "
	3+09	3+39	3+39	3+39	VC	" "
	3+39	3+57	3+57	3+57	VC	" "
	3+57	3+78	3+78	3+78	VC	" "
	3+78	5+59	5+59	5+59	VC	" "
	5+59	5+67	5+67	5+67	VC	" "
	5+67	5+94	5+94	5+94	VC	" "
	5+94	6+55	6+55	6+55	VC	" "
	6+55	7+79	7+79	7+79	VC	" "
	7+79	7+87	7+87	7+87	VC	" "
	7+87	7+99	7+99	7+99	VC	" "

4005a

Start Point: Harris St / Spriggs St. N Sidewalk Inventory

2 of 2 851

End Point: Bush Creek Dr

400sb

Direction of Increasing Station: Right

Inspector Name: T.J.W
Date: 3-4-14

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	7+99	8+18	8+18	8+18	VC	greater than 1/2" lip
	8+18	8+38	8+38	8+38	VC	" "
Bush Creek Dr.	8+38	8+51				
8+51						

400sb

clendenin
Start Point: ~~clendenin~~ way / Bush Creek Dr.
End Point:

Sidewalk Inventory

Right
1 of 3

3995a

Direction of Increasing Station: Right.

Inspector Name: J. T. W
Date: 4/3/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 10

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Dr	0+00	0+08	0+08	0+08	VC	greater than 1/2" gap.
	0+08	0+45	0+45	0+45	VC	" " " "
	0+45	1+09	1+09	1+09	VC	" " " "
	1+09	1+17	1+17	1+17	VC	" " " "
	1+17	1+48	1+48	1+68	CS	
	1+68	1+99	1+99	2+08	CS	
			2+08	2+08	DS	MB 9036
			2+08	2+18	CS	
	2+18	2+29	2+29	2+29	VC	" "
	2+38	2+38	2+38	2+38	VC	" "
	2+38	3+12	3+12	3+12	VC	" "
	3+12	3+58	3+58	3+58	VC	" "
	3+58	3+70	3+70	3+70	VC	" "
	3+70	4+40	4+40	4+40	VC	" "

3995a

2 of 3 Right

Start Point: Clendenn Way / Bush Creek DR

End Point: _____

399sb

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T.J.W
Date: 4-3-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	4+40	5+00	5+00	5+00	VC	greater than 1/2" lip
	5+00	5+75	5+75	5+75	VC	" "
	5+75	6+46	6+46	6+46	VC	" "
	6+46	6+72	6+72	6+72	VC	" "
Alley @ Pool House	6+72	7+36				
	0+00	2+68	2+68	2+86	CS	
	2+86	3+09	3+09	3+09	VC	" "
	3+09	3+61	3+61	3+61	VC	" "
	3+61	3+96	3+96	3+96	VC	" "
	3+96	4+04	4+04	4+04	VC	" "
	4+04	4+08	4+08	4+08	VC	" "
	4+08	4+16	4+16	4+16	VC	" "
	4+16	4+32	4+32	4+32	VC	" "
	4+32	4+58	4+58	4+58	VC	" "

399sb

3 of 3 Right

Start Point: Clendenway / Sush Creek

End Point: Mailbox 9086

399SC

Direction of Increasing Station: Rt

Reason Codes for NON-COMPLIANCE:

Inspector Name: J.W.T
Date: 4-3-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 9

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	4+58	4+70	4+70	4+70	VC	greater than 1/2" lip
	4+70	4+86	4+86	4+86	VC	" "
	4+86	5+39	5+39	5+39	VC	" "
	5+39	6+02	6+02	6+02	VC	" "
	6+02	6+64	6+64	6+64	VC	" " "
	6+64	6+81	6+81	6+81	VC	" " "
	6+81	6+85	6+85	6+85	VC	" " "
	6+85	9+43	9+43	9+43	VC	" " "
	9+43	9+78	9+78	9+78	VC	" " " " " "
	9+78	10+12	10+12	10+12	CS	
	10+12	10+20	10+20	10+41	VC	" " " " " " " " " "
9086 Mailbox						

399SC

LA

192

Start Point: MAJOR Smith / ~~clendenin~~ clendenin way

3985a

End Point: Bush Creek See Page 2

Direction of Increasing Station: _____

Inspector Name: J/W/T

Date: 4/3/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 111 111 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
clendenin way			0+00	0+05	CS	
clendenin way	0+05	1+25	1+25	1+25	VC	Greater than 1/2" Gap
	1+25	1+35	1+35	1+35	VC	" " " "
	1+35	1+63	1+63	1+63	VC	" " " "
	1+63	2+09	2+09	2+09	VC	" " " "
	2+09	2+48	2+48	2+48	VC	" " " "
	2+48	3+06.7	3+07	3+07	VC	" " " "
	3+07	3+52	3+52	3+52	VC	" " " "
	3+52	3+88	3+88	3+88	VC	" " " "
	3+88	3+93	3+93	3+93	VC	" " " "
	3+93	4+10	4+10	4+10	VC	
	4+10	4+18	4+18	4+18	VC	
	4+18	4+31	4+31	4+31	VC	
	4+31	4+51	4+51	4+51	VC	

3985a

292

6498

Start Point: Major Smith / Clendenn
 End Point: Bush Creek

398sb

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____

Date: _____

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: ~~11~~ 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Clendenn	4+51	4+58	4+58	4+58	VC	green bottom 1/2" Lip
	4+58	4+91	4+91	4+91	VC	" " "
	4+91	5+28	5+28	5+28	VC	" " "
	5+28	5+43	5+43	5+52	C/S.	
			5+52	5+52	DS	MB 9055
			5+52	5+61	CS	
	5+61	5+97	6+01	6+01	VC	> 1/2" Lip
	6+01	6+68	6+68	6+68	VC	" "
	6+68	6+86	6+86	6+86	VC	" "
	6+86	6+98				
Bush Creek						
6+98						

398sb ✓

Start Point: HARRIS BL. / Sprigg st North.

Sidewalk Inventory

192



End Point:

3975a

Direction of Increasing Station:

Right Circle

Reason Codes for NON-COMPLIANCE:

Inspector Name: DTJ
Date: 9/3/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

13

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sprigg st. north	0+00	1+61	1+61	1+61	VC	greater than 1/2" Lip.
	1+61		1+61	1+82	CS	(465 Train)
	1+82	2+22	2+22	2+38	CS	
	2+38	2+57		2+57	VC	> 1/2" Lip.
	2+57	3+03	3+03	3+09	CS	
			3+09	3+09	DS	MB 9068
			3+09	3+15	CS	
	3+15	3+24	3+24	3+24	VC	> 1/2" Lip.
	3+24	3+32	3+32	3+32	VC	" " "
	3+32	3+48	3+48	3+48	VC	" " "
	3+48	3+71	3+71	3+71	VC	" " "
	3+71	4+51	4+51	4+51	VC	" " "
	4+51	4+63	4+63	4+63	VC	" " "
	4+63	4+77	4+77	4+77	VC	" " "

3975a

Start Point: Hanni's Place / Sprigg St. North

Sidewalk Inventory

292

End Point:

397SB

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____
Date: _____

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
(Sprigg North MD- 9067)	4+77	4+80	4+80	4+80	VC	green to show 1/2" Lip.
	4+80	4+97	4+97	4+97	VC	" " " "
	4+97	5+12	5+12	5+22	CS	
			5+22	5+22	DS	9065
			5+22	5+30	CS	
	5+22	5+75	5+75	5+75	VC	> 1/2" Lip.
	5+75	6+15	6+15	6+15	VC	" " "
	6+15	6+67	6+67	6+67	VC	" " "
	6+67	7+05	7+05	7+05	VC	" " "
	7+05	7+21				
Sprigg St North						
7+21						

397sb

Start Point: Harris Street / Sprigg Street North (Left) ^{Sidewalk Inventory}

End Point: Bush Creek Drive

3965

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/w
Date: 4/3/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

1111
11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sprigg St. North	0+00	0+32	0+32		VC	Gas Valve
	0+32	1+73	1+73		VC	
	1+73	4+19	4+19		VC	
	4+19	7+68	7+68		VC	
	7+68	7+81	7+81		VC	
	7+81	10+12	10+12		VC	
	10+12	10+20				
Bush Creek Drive	10+20					

3965

Start Point: Cleadenin Way / Sidewalk Inventory Bush Creek Driveway (Left)

pg 1 of 2

End Point: _____

3955a

Direction of Increasing Station: _____

Inspector Name: T/V

Date: 4-3-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 111 111 111 (5)

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Dr.	0+00	2+22	2+22		VC	
	2+22	4+31	4+31		VC	
	4+31	4+77	4+77		DS	9041
			4+77	4+91	CS	
	4+91	5+73	5+73		VC	
	5+73	6+13	6+13		VC	
	6+13	6+72	6+72		VC	
	6+72	8+88	8+88		DS	9051
	8+88	9+09	9+09		VC	
	9+09	9+97	9+97		VC	
	9+97	11+60				
Major Smith Lane	0+00	1+02	1+02		VC	
	1+02	1+88	1+88		VC	
	1+88	2+71	2+71	2+80	CS	

3955a

Start Point: Clendenin Way / Bush Creek Drive (Left) (Circle) pg 2 of 2
 End Point: House # 9086

Direction of Increasing Station: _____

395 SB

Inspector Name: T/W
 Date: 4/3/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

(8)

Total Number of Driveways: 44111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	2+80	3+60	3+60		DS	9063
			3+60	3+67	CS	
	3+67	3+84	3+84		VC	
	3+84	3+95	3+95		VC	
	3+95	4+95	4+95		VC	# 9086
	4+95	7+09	7+09		VC	
	7+09	9+12				
house # 9086	9+12					

395 SB

Start Point: Major Smith Lane / Clendenin Way (Left)

End Point: Bush Creek Drive

Sidewalk Inventory

3945

Direction of Increasing Station:

Inspector Name:

T/W

Date:

7-3-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

HHH (10) HHH

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Clendenin Way	0+00	2+05	2+05		VC	
	2+05	2+33	2+33		VC	
	2+33	2+62	2+62		VC	
	2+62	2+73	2+73		VC	
	2+73	3+42	3+42		VC	
	3+42	3+80	3+80		VC	
	3+80	4+75	4+75		VC	
	4+75	4+92	4+92		VC	
	4+92	6+71	6+71		VC	
	6+71	7+22				
Bush Creek Dr.	7+22					

3945

Start Point: Mantz Lane / McPherson St. Sidewalk Inventory (Rt.)

End Point: Dead End

Direction of Increasing Station:

Inspector Name: T/w

Date: 4-3-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:

Compliant

From

To

Non-Compliant

From

To

Code

Comments

[illegible]

13035

Start Point: McPherson St. / Sprigg Street South (Right) 3925

End Point: Mantz Lane

Direction of Increasing Station: _____

Inspector Name: T/W
Date: 4-3-14

Reason Codes for NON-COMPLIANCE:

- | | |
|-----------------------|-------------------------|
| VC Vertical Clearance | DS Driveway Cross Slope |
| PP Pinch Point | CS Panel Cross Slope |
| PZ Passing Zone | WP Width of Panel |
| PO Protruding Object | |

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sprigg St. South	0+00	0+21	0+21	2+22	CS	
			2+22		PO	TREE
	2+22	2+67				
Dead End (#9064)	2+67					
Dead End	0+00	0+20	0+20		VC	
Begin	0+20	0+35	0+35		VC	
(#9012)	0+35	0+74	0+74		VC	
	0+74	0+79	0+79		VC	
	0+79	0+91	0+91		PO	TREE
	0+91	1+99	1+99		VC	
	1+99	2+16				
Mantz Lane	2+16					

3925

Start Point: McPherson St. / Rine's Tavern Lane (Prt.)

3915

End Point: Spring St. South

Direction of Increasing Station: _____

Inspector Name: T/w

Date: 4-3-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Rine's Tavern Ln.	0+00	0+87				
Alley	0		0+60		VC	
	0+00	0+08	0+08		VC	
	0+08	1+32	1+32		VC	
	1+32	1+53	1+53		VC	
	1+53	1+72				
John Simmons St.	0+00	0+38	0+38	0+77	CS	
	0+77	0+95				
Alley	0+00	0+07	0+07	2+08	CS	
Bremen St.	0+00 0+00	1+37				
Worthington Alley	0+00	0+63				
Spring St. South	0+63					

3915

Start Point: Rine's Tavern Lane / Worthington Blvd.

End Point: McPherson Hinks Lane

Direction of Increasing Station: _____

Inspector Name: T/w

Date: 7-3-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:

Compliant

From

To

Non-Compliant

From

To

Code

Comments

[illegible]

13905

3895

Direction of Increasing Station:

Date:

WP Width of Panel

Total Number of Driveways: 0

Non-Compliant

Comments

3895

Start Point: MANTZ La / Hinks La Sidewalk Inventory
 End Point: Brien

3885

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWJ
 Date: 4/3/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hinks La	0+00	0+15	0+15	0+31	CS	
	0+31	0+41	0+41	0+77	CS	
	0+77	0+81				
3405 Ramp	9' wide into house steps					
3405 "	0+00	0+14	0+14	0+36	CS	
	0+36	0+68	0+68	0+72	CS	
BRIEN PL.	0+00	0+23	0+23	0+25	CS	Concrete Corner Missing.
See number.	0+25	0+40	0+40	0+49	CS	
	0+49	0+68	0+68	0+72	CS	
	0+72	0+92	0+92	1+05	CS	
	1+05	1+12				
Alleyway						
3400						

3885

Start Point: Brien Pl / Main + 2nd La. Sidewalk Inventory

3875

End Point: Susan Loft Pkwy

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTJ
Date: 4/3/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Brien Pl	0+00	0+69	0+69	0+69	VC	Green to Home 1/2" Cur
	0+69	1+33	1+33	1+33	VC	" " " "
	1+33	1+44	1+44	1+44	VC	" " " "
	1+44	1+78	1+78	1+78	VC	" " " "
Alley 9116	1+78	1+98	1+78			
Alley	0+00	2+03	2+03	2+08	CS	
	2+08	2+13	2+13	2+28	CS	
	2+28	2+62	2+62	2+78	CS	
	2+78	3+34				
Susan Loft Pkwy						
3+34						

3875

172

Start Point: Barren PL / Sugar Loaf PKwy Sidewalk Inventory

3865a

End Point:

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTS
Date: 4/3/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sugar Loaf PKwy			0+00	0+15	CS	
	0+15	0+70	0+70	0+75	CS	
	0+75	0+84				
Alleyway 3466	0+00	0+05	0+05	0+18	CS	
	0+18	0+27	0+27	0+27	VC	greater than 1/2" lip.
	0+27	0+47	0+47	0+47	VC	" " " "
	0+47	0+92	0+92	0+92	VC	" " " "
	0+92	1+02	1+02	1+02	VC	" " " "
	1+02	1+22	1+22	1+22	VC	" " " "
	1+22	1+37	1+37	1+37	VC	" " " "
	1+37	1+41	1+41	1+41	VC	" " " "
	1+41	1+76	1+76	1+76	VC	" " " "
	1+76	2+49	2+49	2+49	VC	" " " "
	2+49	2+63	2+63	2+63	VC	" " " "

3865a

272

Start Point: Brien PL / Sugar Coast Pkwy

Sidewalk Inventory

386sb

End Point: Mantz LaDirection of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TWJ
Date: 4/3/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Alleyway 3466	2+63	2+63	2+63	2+63	VC	Greater than 1/2" gap
	2+63	2+78	2+78	2+78	VC	" " " "
	2+78	2+92	2+92	3+01	CS	
	3+01	3+70	3+70	3+70	VC	" " " "
	3+70	4+82	4+82	4+82	VC	
	4+82	5+19				
Mantz La						
5+19-						

386sb

Islington St.

Start Point: Islington St / Lew Wallace Rd Sidewalk Inventory
 End Point: AME Lung St.

3655

Direction of Increasing Station: Rt.

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTJ.

Date: 4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Lew Wallace	0+00	0+86	0+80	0+85	CS	
	0+85	0+97	0+97	0+97	VC	> 1/2" low Lip.
	0+97	1+34	1+34	1+43	CS	
	1+43	1+60	1+60	1+60	VC	" " "
	1+60	2+09	2+09	2+17	CS	
	2+17	2+33	2+33	2+49	CS	
	2+49	2+99	2+99	3+03	CS	
	3+03	3+86				
AME Lung St.						
3+86						

3855

Islington St.

Start Point: Islington St / Amelung St.

Sidewalk Inventory

3845

End Point: Lew Wallace Rd.

Direction of Increasing Station: Rt. 41

Reason Codes for NON-COMPLIANCE:

Inspector Name: W.T.J.

Date: 4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Amelung St.	0+00	0+04	0+04	0+04	VC	1/2" Lip.
	0+04		0+04	0+11	CS	
	0+11	0+21	0+21	0+21	VC	" " "
	0+21	0+85	0+85	0+85	VC	" " "
	0+85	1+13	1+13	1+24	CS	
	1+24	1+28	1+28	1+28	VC	" " "
	1+28	2+33				
Alleyway Garage	8801					
			0+00	0+05	CS	
	0+05	0+84	0+84	0+84	VC	0+29 to 0+40 Trim Bushes
Lew Wallace	0+84	1+03				> 1/2" cur.
	1+03					

3845

Sidewalk Inventory

Start Point: TAVISTOCK Rd / Lew Wallace

3835

End Point: _____

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____
Date: 4/2/15

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Lew Wallace	0+00	0+98.				
alley ^{way} - 18821	Gange					
	0+00	0+18	0+18	0+18	VC	> 1/2" Lip
	0+18	0+38	0+38	0+38	VC	" " "
	0+38	0+94	0+94	0+98	CS	
	0+98	1+89	1+89	1+89	VC	" " " "
	1+89	1+98	1+98	1+98	VC	" " "
	1+98	2+15	2+15	2+28.	CS	
AMELUNG st.						
(2+28)						

3835

Start Point: TAVISTOCK RD / AMELUNG ST. 3825

End Point: _____

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
AMELUNG ST.	0+00	1+15	1+15	1+15	VC	> 1/2" sidewalk up
	1+15	1+66	1+66	1+66	VC	" " " " "
	1+66	1+78	1+78	1+78	VC	" " " "
	1+78	1+87	1+87	1+87	VC	" " " "
	1+87	2+10	2+10	2+10	VC	" " " "
	2+10	2+19	2+19	2+19	VC	
	2+19	2+25				
(Alley Rt. to Garage #8823)	0+00	1+00				
Low wall area						

3825

Start Point:

Sprigg St. north

Sidewalk Inventory

Steward

192

381sa

End Point:

Direction of Increasing Station:

Left

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Inspector Name: WTS

Date: 4/2/14

Total Number of Driveways:

⑥
1111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Steward	0+00	1+59	1+59	1+59	VC	> 1/2" Lip.
	1+59	1+95	1+95	1+95	VC	" " "
	1+95	2+20	2+20	2+20	VC	" " "
	2+20	2+31	2+31	2+31	VC	" " "
	2+31	3+40	3+40	3+50	CS DS	Mail box 3702
			3+50	3+50	DS	Mail box 3702
			3+50	3+59	CS	
	3+59	3+73	3+73	3+73	VC	> 1/2" Lip
	3+73	3+97	3+97	3+97	VC	" " "
	3+97	4+11	4+11	4+11	VC	" " "
	4+11	4+30	4+30	4+30	VC	" " "
	4+30	4+50	4+50	4+50	VC	
	4+50	4+74	4+74	4+74	VC	> 1/2" Lip
			4+74	5+00	CS	

4+90

Mail box
DS 3124

381sa

272

381sb

Sidewalk Inventory

Start Point: Sprigg St. North / SewardEnd Point: Bush Creek Dr.Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: WTSDate: 4/2/14Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
M.B. 3724	5+00	6+05	6+05	6+05	VC	> 1/2" L.p. sidewalk
	6+05	6+14	6+14	6+14	VC	" " "
	6+14	6+53	6+53	6+53	VC	" " " "
	6+53	7+31	7+31	7+31	VC	" " " "
	7+31	8+44				
Bush Creek Dr.						
8+44						

381sb

Start Point: Sprigg St. Wt. / Bealls Fann Rd. 3805
 End Point: Seward St
 Direction of Increasing Station: Lt.

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____
 Date: _____

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

①

Total Number of Driveways: 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bealls Fann Rd	0+00	0+10	0+10	0+10	VC	> 1/2" Joint Lip
	0+10	1+71	1+71	1+71	VC	GAS meter/valve any.
1+HARRIS	1+71	1+86				
1+86						
1+HARRIS PL.	0+00	0+31	0+31	0+31	VC	> 1/2" Joint Lip
	0+31	0+59	0+59	0+59	VC	" " " "
	0+59	1+05	1+05	1+05	VC	" " " "
	1+05	1+53	1+53	1+53	VC	" " " "
	1+53	1+65	1+65	1+65	VC	" " " "
SEWARD St	1+65	2+55				

3805

Sidewalk Inventory

Wrothly / m

3795

Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

WP Width of Panel

C

[illegible]

3795

TOP 9 Circle
Washington Blvd /
Ramp

Sidewalk Inventory
Start Point: SPRIGG South / 355 Washington Street Brick side
End Point: Lew Wallage walk
Direction of Increasing Station: Left. 3785

Inspector Name: T/W/J
Date: 7/2/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Washington Blvd			0+00	1+00	CS	CS
Ramp	1+00	1+38				
Ramp section	1+38	1+56				
	1+56	2+04	2+04	2+17	CS	
	2+17	2+56				
Amelung St.	0+00	0+19	0+19		VC	Concrete > 1/2" Lip
	0+19	0+31	0+31		VC	" "
	0+31	0+88	0+88		VC	" "
	0+88	2+22	2+22		VC	" "
	2+22	3+55	3+55	3+76	CS	
	3+76	3+96				
Lew Wallage						
3+96						

3785

Start Point: Beall's Farm Ct. / Beall's Farm Rd. (Rt.) ^{Sidewalk Inventory} (Circle)

377Sa

pg 192

End Point: Beall's Farm Rd.

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/S/W
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 16

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Beall's Farm Rd.	0+00	0+94	0+94	1+24	CS	
	1+24	1+95	1+95	2+19	CS	
	2+19	2+39	2+39	2+44	CS	
	2+44	2+65	2+65	2+72	CS	
	2+72	3+51	3+51	3+66	CS	
			3+66		DS	3627
	3+66	4+86	4+86	4+97	CS	
			4+97		DS	3633
			4+97	5+04	CS	
	5+04	6+18	6+18	6+30	CS	
			6+30		DS	3641
			6+30	6+43	CS	
	6+43	6+75	6+75	6+82	CS	
			6+82		DS	3643

6+82
6+98

6+98

DS 3645 3645 RC

377Sa

Start Point: Bealls Farm Ct. / Bealls Farm Rd.

Sidewalk Inventory

(Rt.)

377sb

pg 2 of 2

End Point: Bealls Farm Rd.

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/S/W
Date: 4-2-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
			6+98	7+13	CS	
	7+13	7+21	7+21		DS	3647
			7+21	7+36	CS	
	7+36	7+83	7+83	8+07	CS	
	8+07	8+93	8+93		DS	3651
			8+93	9+13	CS	
	9+13	9+50	9+50	9+61	CS	
			9+61		DS	3653
			9+61	9+71	CS	
	9+71	10+03	10+03		VC	Gas valve
	10+03	10+14	10+14	10+20	CS	
Bealls Farm	10+20					
RA.						

377sb

Start Point: Seward Street / Sprigg St. South (Rt.) 3765
 End Point: ~~Bentley's Farm Drive~~ Rushworth Street

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/D
 Date: 4-2-14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 8 ~~111~~

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sprigg St. South	0+00	0+39	0+39		VC	
	0+39	0+82	0+82		VC	
	0+82	1+31	1+31		DS	9052
			1+31	1+40	ES	
	1+40	1+83	1+83		VC	
	1+83	1+91	1+91		VC	
	1+91	2+34				
Seward Ln.	0+00	0+63	0+63		DS	9102
	0+63	0+74	0+63	0+74	CS	
	0+74	1+15	1+15	1+75	CS	
	1+75	2+39				
Rushworth St.	0+00					
	2+39					

3765

Start Point: Seward Lane / ^{Sidewalk Inventory} Seward Street (RT. ~~Left~~)
 End Point: Bush Creek Drive

Direction of Increasing Station: _____

Inspector Name: T/D
 Date: 4-2-14

Reason Codes for NON-COMPLIANCE:
 VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

13

Total Number of Driveways: HHH HHH 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Seward St.	0+00	2+53	2+53		VC	
	2+53	2+72	2+72		VC	
	2+72	4+04	4+04		DS	3711
			4+04	4+27	CS	
	4+27	4+52	4+52	4+76	CS	
			4+76		DS	3713
			4+76	4+89	CS	
	4+89	5+09	5+09	5+46	CS	
			5+46		DS	3715
			5+46	5+55	CS	
	5+55	5+89	5+89	6+10	CS	
	6+10	6+70	6+70		VC	
	6+70	7+83	7+83		VC	
	7+83	10+04	10+04		VC	

Start Point:

Seward Lane / Seward Street

Sidewalk Inventory

(Rt. ~~Lt.~~)

375sb

pg 2 of 2

End Point:

Bush Creek Drive

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

①

Inspector Name:

T/O

Date:

4-2-14

Total Number of Driveways: 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	10+04	10+55	10+55		DS	3727
			10+55	10+67	CS	
	10+67	10+94	10+94		VC	
	10+94	11+02	11+02		VC	
	11+02	11+26	11+26		VC	
	11+26	11+63				
Bush Creek						
Drive						

375sb

✓

Start Point: Seward Lane / Sidewalk Inventory Bush Creek Drive (Rt.)

3745

End Point: ~~Seward Street~~ Dead End Seward Street

Direction of Increasing Station: _____

Inspector Name: T/D
Date: 4-2-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

8

Total Number of Driveways: HHH III

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bush Creek Drive	0+00	0+06	0+06	0+14	CS	
	0+14	1+29	1+29		VC	
	1+29	3+68			CS	
Dead End house # 3720	3+68					
Begins # 3708	0+00		0+00	0+40	CS	
			0+40		DS	3708
			0+40	0+63	CS	
	0+63	1+72	1+72	2+15	CS	
	2+15	2+80				
Seward Street	2+80					

Distance of Gap 578' of no sidewalk

3745

3735

End Point: Mackall Court

Direction of Increasing Station:

Inspector Name: T/O
Date: 4-2-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		

[illegible]

3735

Start Point: Mackall Street / Beall's Farm Road (Left)
 End Point: Beall's Farm Road

3725

Direction of Increasing Station: _____

Inspector Name: T/5/10
 Date: 4-2-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 7 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Beall's Farm Rd.			0+00	0+67	CS	
			0+67		DS	3725
			0+67	0+77	CS	
	0+77	1+46	1+46	1+81	CS	
	1+81	2+05	2+05	2+17	CS	
	2+17	2+54	2+54	2+98	CS	
	2+98	6+35	6+35	6+39	CS	
Beall's Farm Road	6+39	7+69				

3725

Start Point: SEWARD St / Spriggs St North
 End Point: Seall's Farm Rd

192

3715a

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: WJ
 Date: 4/2/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 11

11

p/s sta #

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Spriggs St. North	0+00	1+16	1+16		VC	> 1/2" cur.
	1+16	1+67	1+67		VC	" " "
	1+67	1+97	1+97		VC	" "
	1+97	2+04	2+04	2+23	CS	
			2+13		DS	MB 9057
	2+23	2+41	2+41	2+45	CS	
	2+45	2+59	2+59	2+77	CS	
				2+68	DS	MB 9059
	2+77	3+21		3+21	PO	Gas valve box
	3+21	3+32	3+32	4+44	CS	
	4+44	4+89	3+86		DS	MB 9103
	4+89	6+03		4+89	VC	> 1/2"
			6+03	6+27	CS	
	6+27	6+87	6+13		DS	MB 9111

3715a

Start Point: SEWARD Street / Sprigg St. North ²⁹²
 End Point: Beall's Farm Rd

37156

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: W/T
 Date: 4/2/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sprigg St. North	6+27	6+87	6+87	7+11	CS	
	6+87	6+997				
	7+11	7+24	7+24	8+06	CS	
				7+37	DS.	
	8+06	8+37				
Beall's Farm Rd.						
8+37						

37156

Start Point: Mackall Street / Beall's Fann. Rd.

3705

End Point: _____

Direction of Increasing Station: Right.

Reason Codes for NON-COMPLIANCE:

Inspector Name: WJ
Date: 7/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 7 1111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Beall's Fann Rd.			0+00	0+10	CS.	
	0+10	2+65	2+65	2+65	VC	> 1/2" Lip.
	2+65	3+64	3+64	3+84	CS	
				3+74	DS.	M.B. 3712
	3+84	5+68.				
Mackall Ct.						
0 L						

3705

Start Point: Mackall ct / Mackall Street circle

3695

End Point: _____

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: WT
Date: 2/2/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: TH 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Mackall street	0+00	0+82	0+82	1+09	CS	
	1+09	1+43	1+43	1+70	CS	
	1+70	2+06	2+06	2+38	DS. MB.8902	
			2+38	4+58	CS	
	2+38	4+58		4+69	DS. 6b 8900	
			4+58		CS.	
Mackall st.						
(Mackall ct.						
4+69 circle)						

3695

Sidewalk Inventory

Start Point: Crestwood Blvd @ New Design Rd

End Point: Corporate Dr

Direction of Increasing Station: UP

F2
3685a

Reason Codes for NON-COMPLIANCE:

Inspector Name: BT/RH

Date: 4-2-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name: <u>Crestwood Blvd</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
New Design Rd	0+00	1+22	1+22	✓	VC	Broken Slabs
	1+22	7+66				
Foxcraft Dr	0+00	11+64				
Entrance #1	0+00	0+81	0+81	✓	PO	Tree
	0+81	1+25	1+25	✓	PO	Tree
	1+25	1+75	1+75	✓	PO	Tree
	1+75	4+16				
Entrance #2	0+00	4+59	4+59	✓	VC	
	4+59	6+92				
Bank CT	0+00	5+81				
BREAK						
Reste@ Bechtel Ent #1	0+00	4+80				
Westvian Dr	0+00	2+45	2+45	✓	VC	
			2+45	2+60	CS	
			3+05	✓	VC	

3685a

2012
368sb

Start Point: Crestwood Blvd @ New Design Rd

Sidewalk Inventory

End Point: Corporate Dr

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/RH
Date: 4-2-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

LT

Street Name: Crestwood Blvd	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+05	4+00	4+00	4+10	CS	
	4+10	7+06				FENCE Corporate Dr

368sb

1-675

Start Point: East Sidewalk Inventory Mercantile @ Ballenger Creek - Right

End Point: Mercantile East

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: SC/cm/CB
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name: <u>Mercantile East</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Ballenger</u>			0+00	0+35	CS	5' sidewalk
	0+35	0+80	0+80	0+96	CS	
	0+96	1+90				
<u>Ent to Bank</u>	0+00	0+10	0+10	0+52	CS	
	0+52	0+97				
<u>2nd @ Bank</u>	0+00	2+47	2+47	2+79	CS	4' sidewalk
	2+79	3+87				
<u>Ent Clearbrook</u>	0+00	1+88				
<u>Howard Farm La</u>	0+00	1+20	1+20	1+44	CS	
	1+44	3+62	3+62	3+74	CS	
	3+74	3+90	3+90	4+10		
	4+10	5+86				
<u>Howard Farm La</u>	0+00	0+27	0+27	0+47	CS	End Mercantile East
<u>@ circle</u>						

3675

Sidewalk Inventory

Start Point: International Blvd @ Executive Way Right

End Point: sidewalk terminates mid way

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: P.M./CB

Date: 4/2/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

RT
31st
Street Name: International **Compliant**

Street Name: <u>International</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Executive Way	0+00	1+59	1+59	1+87		
	1+87	2+19				
1st Entrance	0+00	2+80				
2nd "	0+00	3+59				End 3rd Ent.

12.55

Sidewalk Inventory

Start Point: Executive Way @ New Design - Right

End Point: Buckeystown Pike

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: SO/RH/CB

Date: 4/2/94

Total Number of Driveways: 0

Street Name: <u>Executive Way</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
New Design	0+00	2+56	2+56	2+88		
	2+88	2+98				
Ent @ 100	0+00	2+40				
International Blvd	0+00	2+93				
Future Ent #1	0+00	3+50				
Executive Ct S	0+00	7+54				Future Ent
Future Westview Dr	0+00	2+49				Buckeystown Pike

13655

Start Point: Mercantile Dr E @ Ballenger Creek Pkce Sidewalk Inventory

End Point: Mercantile Dr E

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BE/RH
Date: 4-2-10

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name: <u>Mercantile Dr E</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Ballenger Creek Pkce	0+00	1+00				
Entrance to Exxon	0+00	0+41				
Entrance to Shopping center	0+00	0+25				
Shopping center #2			0+00	0+30	CS	
	0+30	0+84				
Hannover Dr	0+00	0+11	0+11	0+16		
	0+16	3+60	3+60	3+78		No PZ
	3+78	4+02	4+02	4+62		No PZ
	4+62	11+21	11+21	11+33		
Redas CR	0+00	0+57				END @ Mercantile Dr E

20F2

3635

Start Point: Westview Dr @ Crestwood Blvd

Sidewalk Inventory

End Point: Crestwood Blvd

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF SRH
Date: 4-2-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name: Westview Dr	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Agency 1000' Grand	0+00	0+11				
Entrance to Marriott	0+00	2+89				
Golds Gym Ent	0+00	1+12	1+12	1+26	CS	
	1+26	1+57				
Bechtel Ent #1	0+00	2+19	2+19	—	VC	
	2+19	3+20				
Bechtel Ent #2	0+00	2+49				
Bechtel Ent #3	0+00	0+58	0+58	0+84	CS	
	0+84	4+62				END @ Crestwood Blvd

3635

Start Point: Westview Dr @ Executive Way

Sidewalk Inventory

3625

End Point: Westview Ent. #3

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: RS/RH/SC
Date: 4-2-19

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name: <u>Westview Dr</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	0+00	1+22	1+22	1+43	CS	
Westview Ent #1	0+00	0+50	0+50	—	PO	Bushes
	0+50	0+81	0+81	—	VC	
	0+81	0+93	0+93	1+26	CS	
	1+26	1+40	1+40	—	PO	Bushes
	1+40	1+62	1+62	2+24	CS	No PZ
	2+24	2+44	2+44	2+76	CS	
	2+76	2+84	2+84	3+01	CS	
	3+01	3+85	3+85	—	VC	
	3+85	4+18	4+18	4+34	CS	
	4+34	4+52				
Westview Ent #2	0+00	1+40	1+40	—	VC	
	1+40	2+98				END @ Westview Ent #3

3625

Sidewalk Inventory

Start Point:

Westview Dr @ Crestwood Blvd

- Left

3615

End Point:

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name:

CM/CB

Date:

4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name: Westview Dr	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Ent 5220	0+00	0+15	0+00	0+15	CS	
	0+15	2+43				
Ent 5230	0+00	1+16				
Ent 5240	0+00	6+07				
Ent 5300	0+00	0+05	0+05	0+05	VC	
	0+05	0+13	0+13	0+13	VC	
	0+13	0+25	0+25	0+25	VC	
	0+25	1+67	1+67	2+08	CS	
			2+08	2+08	VC	
			2+08	2+33	CS	
	2+33	4+47				End

3615

New Design
Washington
T. Hall

Muffin way

Sidewalk Inventory

Start Point: English @ New Design

End Point: English Muffin

Right

3605

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: CM/CB
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name: English Muffin	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
New Design Rd	0+00	0+97	0+97	1+05	CS	Broken panels
	1+05	2+89	2+89	2+89	VC	
	2+89	3+29	3+29	3+29	VC	
	3+29	3+42	3+42	3+42	VC	
	3+42	4+33	4+33	4+33	VC	
	4+33	7+21	7+21	7+21	VC	
	7+21	8+15				
Tennison Dr	0+00	0+30	0+30	0+30	PO	
	0+30	0+75				End

3605

3545

Sidewalk Inventory

Start Point: International Blvd @ Executive Way

End Point: Sidewalk Terminates mid way

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Inspector Name: BF/RH
Date: 4-2-14



Total Number of Driveways: 0

Street Name: <u>International Blvd</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Executive Way</u>	<u>2+00</u>	<u>5+72</u>				
<u>Future Ent #1</u>	<u>0+00</u>	<u>2+87</u>				
<u>Future Ent #2</u>	<u>0+00</u>	<u>0+15</u>				

3595



Sidewalk Inventory

Start Point: Ridge Field Ln / Baldridge

3585

End Point: Spring Ridge Pkwy

Direction of Increasing Station: Right.

Reason Codes for NON-COMPLIANCE:

Inspector Name: D. T. W.
Date: 3/13/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Baldridge Dr.	0+00	0+39	0+39	0+51	CS	
	0+51	0+55	0+55	0+87	CS	
	0+87	1+60	1+48	1+48	VC	greater than 1/2" joint
	1+48	2+08	2+08	2+36	CS	
	2+36	2+48	2+48	3+06	CS	
Baldridge Hill Ct			0+00	0+46	CS	
	0+46	0+82	0+82	1+45	CS	
	1+45	1+63	1+63	2+05	CS	
Spring Ridge Pkwy						
511						

3585

3572

End Point: Whitworth Terr. South

Inspector Name: OZ, KA
Date: 4/2/14

WP Width of Panel

Total Number of Driveways: 1

357 s

3 S

Sidewalk Inventory

Start Point:

Whitworth Terr South @ Whitworth Terr Right

End Point:

Whitworth Ct

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: 02, KA
Date: 4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Whitworth Terr	0+00	0+08	0+08	—	VC	
	0+08	0+15	0+15	—	VC	
	0+15	1+02				
Oberlin Cir	0+00	0+79	0+79	—	VC	
	0+79	1+12	1+12	1+25	CS	
	1+25	1+90				
Entrance 1	0+00	0+04	0+04	—	VC	
	0+04	2+18	2+18	—	VC	
	2+18	3+20				
Oberlin Pl.	0+00	1+98				End

3565



Sidewalk Inventory

Start Point: Whitworth Ct. @ Whitworth Terr Left

End Point: Whitworth Terr

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Inspector Name: OZ/KA

Date: 4/6/14

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Whitworth Terr	0+00	0+53				
Ashburn Terr	0+00	2+54				
Entrance 1	0+00	0+32				
Entrance 2	0+00	0+12				
Entrance 3	0+00	2+71				
Collinsworth Pl	0+00	0+39	0+39	0+55	CS	
	0+55	0+88				End

3555

Sidewalk Inventory

545

Start Point: Whitworth Terr @ Crestwood Blvd Right

End Point: Whitworth Ct.

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/8/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Crestwood	0+00	0+17	0+17	—	VC	
	0+17	0+71	0+71	0+80	CS	
	0+80	1+00	1+00	1+08	CS	
	1+08	1+40	1+40	1+53	CS	
	1+53	1+81	1+81	2+17	CS	
	2+17	2+33	2+33	—	VC	
	2+33	2+41	2+41	—	VC	
	2+41	3+41	3+41	3+61	CS	
	3+61	3+95				End

3543

Sidewalk Inventory

3535

Start Point: Foxcroft @ New Design Right

End Point: Crestwood Blvd

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA

Date: 4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
New Design	0+00	0+07	0+07	0+23	CS	
	0+23	0+43	0+43	—	VC	
	0+43	0+83	0+83	1+15	CS	
	1+15	1+67				
Sunset View Ln	0+00	0+12	0+12	—	VC	
	0+12	3+66	3+66	—	VC	
	3+66	3+72				
Brook Hill Ln	0+00	0+69	0+69	—	VC	
	0+69	3+85	3+85	—	VC	
	3+85	4+08				
Golden Valley Ct.	0+00	0+64	0+64	—	VC	
	0+64	1+24	1+24	—	VC	
	1+24	2+47	2+47	—	VC	End

3535

Sidewalk Inventory
Start Point: Farmgate Ct @ Foxcroft Left

3525a

End Point: Foxcroft Dr.

Direction of Increasing Station:

Inspector Name: OZ, KA
Date: 4/2/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Foxcroft Dr.			0+00	0+20	CS	
	0+20	0+67	0+67	0+67	DS	5804
	0+67	0+73	0+73	—	VC	
	0+73	0+80	0+80	—	VC	
	0+80	1+16	1+16	—	VC	
	1+16	1+38	1+38	1+38	DS	5808
	1+38	1+45	1+45	1+61	CS	
	1+61	1+69	1+69	1+69	DS	5812
	1+69	1+82	1+82	—	VC	
	1+82	1+94	1+94	—	VC	
	1+94	1+94	1+94	2+12	CS	
	2+12	2+12	2+12	2+12	DS	5812
	2+12	2+18	2+18	2+27	CS	
	2+27	2+37	2+37	2+37	DS	5814

3525a

Sidewalk Inventory

Start Point:

Farmgate Ct. @ Foxcroft Left

End Point:

Foxcroft

352sb

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: OZ, KA

Date: 4/2/14

Total Number of Driveways: 6

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	2+37	2+47	2+47	2+74	CS	
	2+74	2+80	2+80	2+80	DS	5816
	2+80	2+86	2+86	3+01	CS	
	3+01	3+11	3+11	3+11	DS	5818
	3+11	3+21	3+21	3+46	CS	
	3+46	3+53	3+53	3+53	DS	5820
	3+53	3+78	3+78	3+78	DS	5822
	3+78	3+89	3+89	4+01	CS	
	4+01	4+07	4+07	4+07	DS	5824
	4+07	4+12	4+12	4+21	CS	
	4+21	4+61	4+61	5+03	CS	
	5+03	5+35	5+35	5+35	DS	5819
	5+35	5+41	5+41	-	VC	
	5+41	5+62	5+62	-	VC	

352-sb

Sidewalk Inventory

Start Point: Farmgate Ct. @ Foxcroft Left
 End Point: Foxcroft

352 Sc

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
 Date: 4/2/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+62	5+68	5+68	—	VC	
	5+68	5+71	5+71	5+98	CS	
	5+98	6+05	6+05	6+05	DS	5817
	6+05	6+11	6+11	6+20	CS	
	6+20	6+25	6+25	6+25	DS	5815
	6+25	6+31	6+31	6+54	CS	
	6+54	6+61	6+61	—	VC	
	6+61	6+71	6+71	6+71	DS	5813
	6+71	6+82	6+82	6+90	CS	
	6+90	6+96	6+96	6+96	DS	5811
	6+96	7+02	7+02	—	VC	
	7+02	7+06	7+06	7+27	CS	
	7+27	7+37	7+27 7+37	7+27 7+37	VC DS	5869
	7+37	7+48	7+48	7+67	CS	

352 SC

✓

Sidewalk Inventory

Start Point: Farmgate Ct. @ Foxcroft Left
End Point: Foxcroft

4 of 4
352SD

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 4

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	7+67	7+73	7+73	7+73	DS	5807
	7+73	7+79	7+79	8+03	CS	
	8+03	8+13	8+13	8+13	CS	5805
	8+13	8+27	8+27	8+35	CS	
	8+35	8+40	8+40	8+40	DS	5803
	8+40	8+47	8+47	8+69	CS	
	8+69	8+80	8+80	8+80	DS	5801
	8+80	9+01	9+01	—	VC	
	9+01	9+01	9+01	9+13	CS	End

352SD

Sidewalk Inventory

351S

Start Point: English Muffin @ New Design Right

End Point: Lime Kiln way

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Inspector Name: OZ, KA
Date: 4/8/14

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
New Design Rd.	0+00	1+33	1+33	1+65	CS	
	1+65	4+48	4+48	—	VC	
	4+48	4+92	4+92	4+96	CS	
Entrance @ 6701	0+00	1+47				End

351S ✓

Sidewalk Inventory

3505

Start Point: Westview Dr @ Executive Way Left

End Point: Crestwood Blvd

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, K.A. CM

Date: 4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Executive Way	0+00	1+31	1+31	1+40	CS	
Entrance 1	0+00	2+10				
Entrance 2	0+00	1+49	1+49	1+58	CS	
	1+58	2+04	2+04	2+30	CS	
	2+30	3+31	3+31	3+79	CS	
	3+79	5+41	5+41	5+48	CS	
	5+48	7+10	7+10	8+33	CS	
	8+33	9+01	9+01	10+69	CS	
	10+69	12+43	12+43	13+05	CS	
	13+05	15+93	15+93	15+93	PO	tree
	15+93	19+54	19+54	19+88	CS	End

3505

Sidewalk Inventory

Start Point: Executive Way @ New Design Left

3495

End Point: Buckenstown Pike

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: DZ, LA, CM
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
New Design			0+00	0+11	CS	
	0+11	6+25				
International Blvd	0+00	2+38				
Entrance 1						
Future Subdiv.	0+00	3+59				
Executive Ct N	0+00	2+43	2+43	2+76	CS	
	2+76	3+67	3+67	4+49	CS	
	4+49	7+14	7+14	7+36	CS	
Entrance 2	0+00	4+76	4+76	5+55	CS	
	5+55	6+14	6+14	6+99	CS	
	6+99	10+57	10+57	10+97	CS	
	10+97	12+06			CS	
Westview Dr.	0+00	2+67				End

3495

12,163

Sidewalk Inventory

Start Point: Foxcroft Ct. @ New Design Left

End Point: Crestwood Blvd

3475a

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
New Design	0+00	0+63	0+63	0+96	CS	
	0+96	1+44	1+44	1+60	CS	
Farmgate Ct.	0+00	0+23	0+23	0+43	CS	
	0+43	1+79				
Drawbridge Ct.			0+00	0+07	CS	
	0+07	0+20	0+20	—	VC	
	0+20	2+45	2+45	2+57	CS	
	2+57	3+06				
Whitfield Ct.	0+00	1+81	1+81	1+86	CS	
Canterbury Ct.			0+00	0+33	CS	
	0+33	0+48	0+48	—	VC	
	0+48	0+69	0+69	0+81	CS/VC	
	0+81	2+14				
Chase Ct.	0+00	0+27	0+27	—	VC	

3475a

Sidewalk Inventory

Start Point: Foxcroft Ct @ New Design Left

347sb

End Point: Crestwood Blvd

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____
Date: _____

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	0+27	1+20				

347sb

TINA

(481)

10FZ

Start Point: SPRIGG STREET SOUTH @ WORTHINGTON BLVD

346sa

End Point: BUSH CREEK

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JH, TC, WE

Date: 4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 12

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
WORTHINGTON BLVD	0+00	1+36	1+36	1+66	CS	BRICK PAVERS
	1+66	2+63	2+63	—	VC	GAS VALVE IN SIDEWALK
AMBUNY ST	2+72					
	0+00	0+20	0+20	0+28	CS	CONCRETE SIDEWALK
	0+28	0+68	0+60	0+68	CS	
SPRIGG ST S	0+68	1+76				SPRIGG ST SOUTH ENDS
SPRIGG ST N	0+00	0+76	0+76	—	VC	SPRIGG ST NORTH ENDS
HARRIS ST	1+76	2+01				
	0+00	0+66	0+66	—	VC	
	0+66	1+27	1+27	—	VC	
	1+27	1+39	1+39	—	VC	
	1+39	2+33	2+33	—	DS	3707
	1+39	2+24	2+24	2+50	CS	
	2+50	2+50	2+98	3+21	CS	

OK 3412 DS @ 3707

346sa

Sidewalk Inventory

Start Point: SPRING STREET SOUTH @ WASHINGTON BLVD ^{2/2}

End Point: BUSH CREEK DR.

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: TC, WCNH
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

346sb

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+21	4+47	4+47	4+56	CS	
			4+47		DS	@ 3713
	4+56	4+93	4+93		VC	7 1/2" lip
	4+93	5+14	5+14	5+32	DS	@ 3715
	5+32	5+64	5+64		VC	7 1/2" lip
	5+64	5+72	5+72		VC	" "
			5+72	5+76	CS	
	5+76	5+94	5+94	6+03	CS	
	6+03	5+93	5+93		DS	@ 3717
	5+93	6+24	6+24	6+40	CS	
	6+40	7+20	7+20		VC	7 1/2" lip
	7+20	7+44	7+44		VC	" "
	7+44	9+84	9+84		VC	" "
	9+84	10+63	10+63		VC	" "

Bush Creek Dr 11+05

346sb

1.051

Start Point: WASHINGTON BLVD @ ROUTE 355

3455

End Point: BEAULS FARM RD

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JH, TC, WC
Date: 4/2/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 13

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
WASH BLVD	0+00	0+36	0+36	0+49	CS	BUCKS/DENARK
	0+49	1+21	1+21	1+37	CS	
AMBLING ST	1+37	1+60				
	0+00	1+67	1+67	—	VC	
	1+67	2+06	2+06	2+24	CS	
	2+24	2+37	2+37	—	VC	
	2+37	2+83	2+83	—	VC	
	2+83	3+07	3+07	—	VC	
	3+07	3+07	3+07	3+24	CS	
	3+24	4+17	4+17	4+26	CS	
	4+26	4+32	4+32	—	VC	
LEW WACKER RD	4+32	5+28				
BEAULS FARM	0+00	2+59				
SHUT WACK TO	0+00	0+47				

BEAULS FARM

13455

Start Point: BEAUS FARM RD @ LEW WILCOX ST

3445

End Point: SDR166 STREETS N & S

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: TC, W, SH

Date: 4/17/19

VC Vertical Clearance

PP Pinch Point

PZ: Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		

[illegible]

344s

107A

Sidewalk Inventory

Start Point: BRALLS FARM RD @ SPRIGG STREET N4S

End Point: DEAD END @ COTHURDY ST

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JH TC WC

Date: 4/2/11

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

3435a

Total Number of Driveways: 36

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
SPRIGG ST N4S	0+00	1+62	1+62	-	VC	
	1+62	2+15	2+15	-	VC	
	2+15	2+53	2+53	3+02	CS	
	2+53	2+93	2+93	←	DS	9008
	3+02	3+26	3+26	-	VC	
	3+26	3+61	3+61	-	VC	
	3+61	4+68	4+68	-	VC	
	4+68	5+11	5+11	-	VC	SEWER CLEANOUT COVER IN SIDEWALK
	5+11	5+20	5+20	-	VC	
	5+20	6+31	6+31	6+36	CS	
	6+36	6+60	6+60	-	VC	GAS VALVE IN SIDEWALK
	6+60	6+75	6+75	7+03	CS	
	7+03	7+77	7+77	7+97	CS	
			7+87		DS	

3435a

2014

Start Point: BEALLS FARM RD @ SPRIGG ST ALKS

End Point: DEAD END

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JATE WC
Date: 4/2/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

343 Sb

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	7+97	8+34	8+34	8+43	CS	
	8+43	8+60	8+60	8+74	CS	
			8+74		DS	9/1/2
	8+74	8+95	8+95	9+81	CS	
			9+67		DS	9/1/4
	9+81	10+17	10+17	10+34	CS	
BEALLS FARM CT	10+34	10+45	10+45	10+52	CS	-
	0+00	0+31	0+31	1+76	CS	
	1+76	2+07	2+07	2+49	CS	
	2+49	2+67	2+67	2+80	CS	
	2+80	3+01	3+01	3+40	CS	
			3+24		DS	9/1/29
	3+40	3+49	3+49	3+75	CS	
SPRINGFIELD ST	3+75	5+74	5+74	6+33	CS	

343 Sb

30FA

Sidewalk Inventory

Start Point: BEALL'S FARM RD @ SPRING ST N.E.S

End Point: DEAD END

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTC, WCP
Date: 4/2/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

3435c

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
SENARD ST			5+74	-	DS	9/136
	0+00	0+00	0+00	0+04	CS	
	0+04	0+88	0+88	1+50	CS	
			1+40	-	DS	9/142
	1+50	2+06	2+06	2+18	CS	
	2+18	3+24	3+24	3+40	CS	
			3+29	-	DS	9/150
	3+40	3+83	3+83	3+98	CS	
			3+93	-	DS	9/154
	3+98	4+36	4+36	4+47	DS	9/152
			4+36	-	DS	9/158
	4+47	5+30	5+30	6+40	CS	
			5+46		DS	9/160
			6+03		DS	9/162

3435c

4054

Start Point: BEALL'S FARM @ SPRINGST N & S

End Point: DEAD END

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: T. W. C. JH
Date: 4/2/11

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

3435d

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	6+40	6+69	6+69	7+05	CS	
	7+05	7+99	7+99	8+23	CS	
			8+23		DS	9170
	8+23	8+74	8+74	9+91	CS	
			8+84	9+39 9+41	DS	9172
	9+61	9+61	9+61	9+84	CS	
	9+31		9+41		DS	9174
	9+41	9+86	9+86	10+37	CS	
			9+87		DS	9176
DEAD END -	10+37	10+53				

3435d

Start Point: SEWARD ST @ BEAL'S FARM RD

3425

End Point: SEWARD LA

Direction of Increasing Station: LT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JH, TC, WC
Date: 4/2/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 60

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
BEAL'S FARM RD	0+00	0+61	0+61	0+76	CS	
	0+76	0+88	0+88	1+39	CS	
			1+08		DS	9/14
	1+39	1+51	1+51	1+72	CS	
			1+77		DS	9/12
RUSHWORTH ST	1+72	2+43				
	0+00	0+00	0+00	0+04	CS	
	0+04	0+63	0+63	1+24	CS	
	1+24	1+59	1+59	1+86	CS	
			1+73		DS	
SEWARD LA	1+86	2+37				

Sidewalk Inventory
Start Point: RUSHWORTH ST @ SEWARD ST

3415

End Point: SEWARD ST

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JH. W. TC
Date: 4/2/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 9

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
SEWARD ST	0+00	0+00	0+00	0+08	CS	
	0+08	0+35	0+35	—	VC	GAS VALVE IN SIDEWALK
	0+35	1+00	1+00	1+04	CS	
	1+04	1+50	1+50	2+29	CS	
			1+55	—	DS	3703
			2+11	—	DS	3705
	2+29	2+70	2+70	2+99	CS	
			2+99		DS	3709
	2+99	3+17	3+17	3+72	CS	DEAD END AT "T"
SEWARD @ "T"	0+00	0+57	0+57	0+93	CS	" " " "
			0+79	—	DS	3710
	0+93	3+36	3+36	3+91	CS	
SEWARD ST	3+91	3+98				

10F2

1060
668/
771

Sidewalk Inventory

Start Point: BEAUS FARM RD @ DEAD END / LOTHBURY ST

3405a

End Point: DEAD END AT ASPHALT TRAIL

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JH TC WC

Date: 9/17/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 17

Comments

	Street Name:	Compliant		Non-Compliant		Code	
		From	To	From	To		
RT	LOTHBURY ST	0+00	0+18				
	TO DEAD END						
LT	LOTHBURY ST	0+00	0+30				
	TO DEAD END						
LT	ISLAND @	0+00	0+18				
	LOTHBURY ST						
RT	DEAD END @	0+00	2+38	2+38	2+51	CS	
	LOTHBURY ST						
		2+51	2+68	2+68	3+52	CS	
	ISLAND @	0+00	0+20				
	MACKALL ST						
	MACKALL ST	0+00	0+00	0+00	1+31	CS	
		1+31	1+68	1+68	1+78	CS	
		1+78	2+46	2+46	2+70	CS	
		2+70	3+61	3+61	3+77	CS	
				3+66		DS	9/51

3405a

Bealls

20FZ

340sb

Start Point: BEALL'S FARM RD @ DEAD END / LOT 1300 STEnd Point: DEAD END AT ASPHALT TRAILDirection of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: TC, WC, JK
Date: 4/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+77	4+89	4+89	5+05	CS	
	5+05	5+13	5+13	5+34	CS	
			5+24		DS	9/43
	5+34	6+92	6+92	7+07	CS	
MACKALL ST	7+07	8+14		-		
	0+00	1+88	1+88	2+09	CS	
			1+98	-	DS	9/29
	2+09	2+70	2+70	2+91	CS	
	2+91	3+12	3+12	3+61	CS	
			3+56	-	DS	9/21
	3+61	3+95	3+95	-	VC	
Bealls	3+95	4+58	4+58	4+86	CS	
BEALLS FARM	4+86	5+77	5+77	5+86	CS	SIDEWALK DEAD END INTO
CT						ASPHALT TRAIL.

340sb

3191

Sidewalk Inventory

Start Point: SPRING FOREST RD @ SADDLEBROOK LNEnd Point: SPRING RIDGE PARKWAYDirection of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: TC, WC, JHDate: 4/1/14Total Number of Driveways: 35

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>SADDLEBROOK LN</u>	0+00	0+12	0+12	—	VC	
	0+12	0+98	0+98	—	VC	
	0+98	1+11	1+11	—	VC	
	1+11	1+27	1+27	1+44	CS	
	1+44	1+82	1+82	—	VC	
	1+82	2+30	2+30	—	VC	
	2+30	2+82	2+82	2+98	CS	
	2+98	3+07	3+07	—	DS	6432
	3+07	3+07	3+07	3+60	CS	
	3+60	4+02	4+02	—	VC	
	4+02	4+55	4+55	—	VC	
	4+55	4+69	4+69	—	VC	
	4+69	5+01	5+01	—	VC	
	5+01	5+92	5+92	—	DS	6426

33952

20F4

Start Point: SPRING FOREST RT @ SADDLE BROOK LN

339sb

End Point: SPRINGRIDGE PKWYDirection of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: TC, NC, JHDate: 4/11/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+92	10+51	10+51	10+63	CS	
	10+63	10+92	10+92	—	DS	6412
	10+92	11+31	11+31	11+63	CS	
	11+63	11+71	11+71	—	DS	6410
	11+71	12+05	12+05	12+37	CS	
	12+37	12+46	12+46	—	DS	6408
	12+46	12+55	12+55	12+71	CS	
	12+71	12+95	12+95	13+29	CS	
	13+12	13+20	13+20	—	DS	6406
	13+20	13+52	13+52	13+79	CS	
	13+79	14+40	14+40	14+74	DS	6402
	14+74	14+74	14+74	14+91	CS	
	14+91	16+37	16+37	—	VC	
BARRINGTON DR	16+37	16+75				

900

1675

616

3191

339sb

Sidewalk Inventory

339Sc

Start Point: SPANISH FORESTED @ SADDLEBROOK LN

End Point: STRING RIDGE PARKWAY

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JRWCNH

Date: 4/1/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
BARRINGTON RD	0+00	0+00	0+00	0+04	CS	
	0+04	0+85	0+85	-	VC	
	0+85	0+97	0+97	-	VC	
	0+97	1+54	1+54	-	VC	
	1+54	2+05	2+05	-	DS	6330
	2+05	2+17	2+17	-	VC	
	2+17	2+49	2+49	2+84	DS	6328 GOOD AFTER DRIVEWAY
	2+84	2+95	2+95	-	VC	
	2+95	3+06	3+06	3+35	CS	
	3+35	3+53	3+53	-	VC	
	3+53	3+63	3+63	3+79	DS	6326 GOOD AFTER DRIVEWAY
	3+79	4+36	4+36	4+65	DS	6324 GOOD AFTER DRIVEWAY
	4+65	4+81	4+81	-	VC	
SADDLEBROOK LN	4+81	5+01	5+01	-	VC	

339Sc

4.054

Sidewalk Inventory

Start Point: SPRINGFORD ST RT @ SPRINGBROOK LN

3395d

End Point: SPRING PARKWAY

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: TC, WC, JH
Date: 4/1/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
HILLS BOULEVARD	5+01	6+02	6+02	6+16	CS	
	0+00	0+24	0+24	-	VC	
	0+24	0+87	0+87	-	VC	
	0+87	1+43	1+43	-	VC	
	1+43	1+55	1+55	-	VC	
	1+55	2+28	2+28	-	VC	
	2+28	2+51	2+51	-	VC	
	2+51	3+91	3+91	-	VC	
	3+91	4+52	4+52	4+73	CS	
	4+73	5+23	5+23	5+30	CS	
	5+30	7+16	7+16	-	VC	
	7+16	7+78	7+78	-	VC	
	7+78	7+89	7+89	8+31	CS	
	8+31	8+72	8+72	8+84	CS	

SPRING RIDGE
RD RT 8+84 9+00

3395d

2495

7052

338 SA

Start Point: SPRING FOREST RD @ SPRING RIDGE PARKWAY

End Point: SPRING BROOK LN

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: TC, WK, JA
Date: 4/11/14VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding ObjectDS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 18

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
SPRING RIDGE PARKWAY	0+00	0+00	0+00	1+93	CS	ASPHALT SIDEWALK.
			0+83	0+83	PO	TRIM TREE LIMBS
	1+39	2+47	1+39	1+39	PO	" " "
	1+39	2+47	2+47	4+62	CS	
ENTRANCE TO PLAYGROUND	4+62	4+72	4+72	5+36	CS	NO PZ -
	0+00	0+00	0+00	0+52	CS	
	0+52	0+94	0+94	1+39	CS	
			0+80	0+80	PO	TREE LIMBS
	1+39	2+11	2+11	2+51	CS	
			2+20	2+20	PO	TREE LIMBS
	2+51	3+26				SIDEWALK DEAD ENDS @ HILLSBOROUGH DR
BARRINGTON DR	0+00	2+64	2+64	-	VC	SIDEWALK PICKS UP AGAIN AT PARK TRAIL @ BARRINGTON DR
	2+64	4+28	4+28	-	DS	CALL
	4+28	5+62	5+62	5+70	CS	!

536
326
1137
2495

2495

338 SA

Sidewalk Inventory

Start Point: SPRING BROOK RD @ SPRING RIDGE PARKWAYEnd Point: SPRING BROOK LNDirection of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: TC, W/C, JHDate: 2/1/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+70	7+13	7+13-	—	VC	
	7+13 5+70	8+13	8+13	—	VC	
	8+13	10+37	10+37	—	VC	
	10+37	10+45	10+45	—	VC	
	10+45	10+53	10+53	—	VC	
	10+53	11+95	11+95	—	VC	
	11+95	12+91	12+91	—	VC	
	12+91	13+68	13+68		DS	
	13+68	14+05	14+05	14+36	CS	
	14+36	14+58	14+58	—	VC	MANHOLE IN SIDEWALK
SADDLEBROOK LN	14+58	16+10	16+10	16+33	CS	

18
35

Sidewalk Inventory

Start Point: URBANA CHURCH RD

3375

End Point: DYNAMIC AUTOMOTIVE

Direction of Increasing Station: Rt

Reason Codes for NON-COMPLIANCE:

Inspector Name: TC WELSH
Date: 4/11/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Street Name: <u>8826</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
DYNAMIC	0+00					START @ 8826 DEAD END
AUTOMOTIVE	0+14					
ENTRANCE	0+00	0+00	0+00	0+04	CS	
TOTDYNAMIC 8826	0+04	0+33	0+33	0+38	CS	
END @ 8816	0+38	0+93				DEAD END @ 8816 EXIST

3375

Start Point: Lew Wallace Rd / Lew Wallace St 102

336 Sa

End Point: SPRIGG ST SOUTH

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: T. J. W
Date: 4-1-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Lew Wallace St	0+00	0+40	0+40		VC	7 1/2" lip
	0+40	0+64	0+64		PO	trim bush
	0+64	0+81	0+81		VC	7 1/2" lip
	0+81	0+90	0+90		VC	" "
	0+90	1+21	1+21		VC	" "
	1+21	1+38	1+38	1+50	CS	" "
Alley @ 8800	0+00	0+69	0+69		VC	7 1/2" lip
	0+69	1+17	1+17		VC	" "
	1+17	1+28	1+28		VC	" "
	1+28	1+45	1+45	1+71	CS	
	1+71	1+91	1+91		VC	" "
	1+91	2+40	2+40		VC	" "
	2+40	2+52	2+52		VC	" "
	2+52	4+19	4+19		VC	" "

336 Sa

Start Point: CEW WALLACE RD / CEN WALLACE ST

336sb

End Point: SPRING ST. SOUTH

Direction of Increasing Station: LT

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____

Date: _____

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: _____

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+19	4+31	4+31		VC	" "
	4+31	4+44	4+44		VC	" "
Alley @ 8836	4+48					
	0+00	0+48	0+48		VC	" "
	0+48	1+07	1+07	1+40	CS	
	1+40	1+93	1+93	2+05	CS	
Spring St. S.	2+05	2+54	2+54	2+58	CS	

336sb

Right

page 1 of 1

Start Point: Ameling St. Sidewalk Inventory / Bremen St

End Point: LEW WALLACE ST.

3355

Direction of Increasing Station: RGT page 1 of 1

Reason Codes for NON-COMPLIANCE:

Inspector Name: T.W.J
Date: 4-1-14 Tues.

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Library Entrance	0+00	1+32				
Alley @ 8980	0+00	0+76	0+76	0+91	CS	
	0+91	1+40				
Sprigg St, S.	0+00	1+03				
Alley @ 8956	0+00	0+61	0+61		VC	> 1/2" lip
	0+61	0+74	0+74		VC	" "
	0+74	0+97	0+97		VC	" "
Tavistock Rd	0+97	2+09				
	0+00	0+06	0+00	0+47	CS	
	0+47	1+04				
Alley across 8923	0+00	0+30	0+30		PO	Trim trees
	0+30	0+97				
Islington St	0+00	1+42				
Alley across Ameling	0+00	0+00 1+10	1+10		VC	> 1/2" lip

Alley

Lew Wallace St.

3355

Start Point: AMLungst / Bremen St

Sidewalk Inventory

192

334Sa

End Point: Lee wall

Direction of Increasing Station: Left

Inspector Name: LT
Date: _____

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: _____

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bremen St	0+00	0+38	0+38	0+50	CS	
	0+50	0+69	0+69	1+12	CS	
	1+12	1+46	1+46	2+10	CS	
Bremen Alley			0+00	0+79	CS	
Spiggs St. South.	0+00	0+88				> 1/2" Lip
AME Lung Alley	0+00	1+47	1+47		VC	(Trim bush 1+43 note)
	1+47	2+87	2+87		VC	> 1/2" Lip.
	2+87	3+40	3+40		VC	> 1/2" Lip
	3+40	3+51	3+51			(Trim bush 3+51 note)
	3+51	3+90	3+90			Trim Bush. 3+90 note
	3+90	4+32	4+32		VC	greater than 1/2" Lip.
	4+32	4+46	4+46	4+78	CS	
	4+46	5+32	5+32	5+40	CS	
			5+40		PO	Trim Bush
			5+40	5+50	CS	
	5+50	6+36	6+36	6+64	CS	
	6+64	6+82				

334Sa

334sb

Start Point: Lew Wallace Road / Lew Wallace Street (Rt.) 333 S
 End Point: Spring St. South

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/J/W
 Date: 9/1/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: _____

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Lew Wallace St.			0+00	0+09	CS	
	0+09	0+22	0+22	0+70	CS	
	0+70	1+47				
Amelung Alley	0+00	0+21	0+21		PO	Bushes
	0+21	1+08				
Islington St.	0+00	0+23	0+23		VC	
	0+23	0+64	0+64		VC	
	0+64	0+87	0+87		VC	
	0+87	1+07	1+07		PO	Bushes
	1+07	2+14	2+14		VC	
	2+14	2+46				
Tavistock Rd.	0+00	0+41	0+41		VC	
	0+41	1+61	1+61		VC	
	1+61	3+30				

Spring St. South 3+30

333-S

Sidewalk Inventory

Start Point: Springridge Pkwy to Claridge Dr. S. to Claridge Dr. N to Springridge Pkwy

End Point: Springridge Pkwy

3325

Inspector Name: T/S/W
Date: 4-1-14

Date: 4-1-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

③

Total Number of Driveways: 11

Clayton, W. W.

332-S

Start Point: Claridge Drive South / Spring Ridge Pkwy (Rt.)
 End Point: Quinn Rd.

pg 1 of 2

3315a

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/J/W
 Date: 4-1-14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Spring Ridge Pkwy			0+00	0+16	CS	
	0+16	0+97	0+97		VC	
	0+97	1+25	1+25		VC	
			1+25	1+58	CS	
	1+58	2+25	2+25	2+36	CS	
Fleetwood Ct.	0+00	0+23	0+23	0+29	CS	
	0+29	1+38	1+38	1+49	CS	
	1+49	2+02	2+02		VC	
	2+02	2+85				
Bridgewater Ct.	0+00	0+37	0+37		VC	
west	0+37	0+60	0+60	0+92	CS	
			0+92		PO	sign
	0+92	2+82	2+82		VC	
	2+82	3+22	3+22		DS	6308

3+22

3+49

CS

3315a

Start Point: Claridge Dr. South / Spring Ridge Pkwy (Rt.)
 End Point: Quinn Rd.

pg 2 of 2
331 Sb

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/J/w
 Date: 7-1-14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 111 (3)

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+49	4+18	4+18	5+27	CS	
	5+27	5+67	5+67	5+74	CS	
Bellhaven Ct.			0+00	0+16	CS	
	0+16	0+21	0+21		VC	
	0+21	0+48	0+48		VC	
	0+48	0+68	0+68		VC	
	0+68	1+37				
Newport Dr. East	0+00	0+10	0+10		VC	
	0+10	0+39	0+39		PO	Bush
	0+39	1+28	1+28		VC	
	1+28	1+84	1+84		VC	
	1+84	1+92	1+92	2+22	CS	
	2+22	2+65	2+65	2+78	CS	
Quinn Rd.	2+78					

331 Sb

Start Point: Claridge Drive South / Quinn Road (Pt.)

Sidewalk Inventory

pg 1 of 2

End Point: Spring Ridge Pkwy

3305a

Direction of Increasing Station:

Inspector Name: T/J/W
Date: 4/1/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

111 ⑧
~~111~~ 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Quinn Road			0+00	0+10	CS	
	0+10	0+66	0+66		VC	
	0+66	1+03	1+03		VC/PO	sign ~ $> \frac{1}{2}$ "
	1+03	1+53	1+53		VC	
	1+53	2+81	2+81		VC	
	2+81	3+01	3+01		VC	
	3+01	3+47	3+47		VC	
	3+47	3+94	3+94		VC	
	3+94	4+87	4+87		VC	
	4+87	5+06	5+06		VC	
	5+06	6+55	6+55		VC	
	6+55	7+72	7+72		VC	
	7+72	8+83	8+83	8+94	CS	
	8+94	9+32	9+32		VC	

3305a

Start Point: Claridge Drive South / Quinn Road (Rt.)
 End Point: Spring Ridge Pkwy

Pg 2 of 2

330sb

Direction of Increasing Station: _____

Inspector Name: T/J/W
 Date: 4-1-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	9+32	10+15	10+15	10+67	CS	
Bridgewater Ct.	0+00	0+53	0+53	0+74	CS	
East	0+74	0+99	0+99		VC	
	0+99	1+56	1+56		VC	
	1+56	1+69	1+69	1+78	CS	
	1+78	2+52	2+52		VC	
	2+52	3+18	3+18	3+26	CS	
Fleetwood Way	0+00	0+08	0+08	0+41	CS	
	0+41	0+84	0+84		VC	
	0+84	1+48	1+48		VC	
	1+48	1+68	1+68		VC	
	1+68	2+08	2+08	2+28	CS	
Spring Ridge Pkwy	2+28					

330sb

Start Point: Claridge Drive North / Bannister Dr. (Rt.)
 End Point: Spring Ridge Pkwy

pg 1 of 3
3295a

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/J/W
 Date: 7/1/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 44 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bannister Dr.	0+00	1+52	1+52		VC	
	1+52	2+38	2+38		VC	
	2+38	2+51	2+51		VC	
	2+51	3+03	3+03	3+38	CS	
			3+38		DS	6364
			3+38	3+49	CS	
	3+49	3+97	3+97		VC	
	3+97	4+42	4+42		VC	
	4+42	4+67	4+67		VC	
	4+67	4+80	4+80	4+92	CS	
			4+92		DS	6360
			4+92	5+04	CS	
	5+04	5+50	5+50	5+67	CS	
			5+67		DS	6358

5+67 5+79 CS

3295a

Start Point: Claridge Dr. North / Bannister Dr.
 End Point: Spring Ridge Pkwy

(Rt.)

pg 2 of 3
329sb

Direction of Increasing Station: _____

Inspector Name: T/S/w
 Date: 7/1/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 1111 1111

(10)

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+79	6+03	6+03	6+27	CS	
	6+27	6+36	6+36	6+44	CS	
			6+44		DS	6356
	6+44	7+60	7+60		VC	
	7+60	7+64	7+64		VC	
	7+64	8+52	8+52		VC	
	8+52	9+03	9+03		VC	
	9+03	10+15				
Saddlebrook Ln.	0+00		0+00	0+39	CS	
	0+39	1+81	1+81		VC	
	1+81	2+52				
Ashbury Place	0+00	0+31	0+31	0+43	CS	
			0+43		PO	
			0+43	0+47	CS	

329sb

Start Point: Claridge Drive North / Bannister Dr. (Rt.)
 End Point: Spring Ridge Pkwy

pg 3 of 3
 32950

Direction of Increasing Station:

Inspector Name: T/S/W
 Date: 4/1/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 11

2

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	0+47	0+64	0+64	0+77	CS	
	0+77	1+40	1+40	1+60	CS	
	1+60	2+28	2+28		VC	m/H
	2+28	2+97	2+97		VC	
	2+97	3+27	3+27	3+53	CS	
	3+53	5+17	5+17	5+27	CS	
			5+27		DS	6332
			5+27	5+37	CS	
	5+37	5+56	5+56	5+60	CS	
	5+60	6+12	6+12	6+25	CS	
			6+25		DS	6330
			6+25	6+38	CS	
	6+38	6+78				
Spring Ridge Pkwy	6+78					

32950

Claridge Drive North

Sidewalk Inventory

Start Point:

~~North Claridge Drive~~ / Spring Ridge Pkwy (Rt.)

pg 1 of 2

End Point:

Bannister Drive

Direction of Increasing Station:

3285a

Inspector Name:

T/SW

Date:

4/1/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Total Number of Driveways:

8

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Spring Ridge Pkwy	0+00	1+45	1+45		VC	
	1+45	1+91	1+91		VC	
	1+91	3+38	3+38		PO	Bushes
	3+38	3+71	3+71		VC	
	3+71	3+91	3+91		VC	
	3+91	4+23	4+23	4+64	CS	
	4+64	5+40	5+40	5+96	CS	
			5+96		DS	6345
			5+96	6+23	CS	Bushes
	6+23	6+58	6+58	6+64	CS	8+23 to 8+41
	6+64	8+26	8+26		VC	
	8+26	8+59				
Saddlebrook	0+00	0+72	0+72	0+84	CS	
Place			0+84		DS	6351

0+84

1+00

CS

3285a

Start Point: Claridge Dr. North / Spring Ridge Pkwy (Rt.)
 End Point: Bannister Drive

pg 2 of 2
328sb

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/J/W
 Date: 7/1/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 3 HH 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	1+00	1+73	1+73		VC	
	1+73	2+37	2+37		DS	6355
			2+37	2+45	CS	
	2+45	3+63				
Bellevue Pkwy	0+00	0+09	0+09		VC	
	0+09	2+50	2+50		VC	
	2+50	4+63	4+63		VC	
			4+63	4+72	CS	
			4+72		DS	6389
			4+72	4+83	CS	
	4+83	5+10	5+10		VC	
	5+10	5+18	5+18		VC	
	5+18	5+85	5+85		VC	
	5+85	5+90				

Bannister Drive 5+90

328sb

3275

Start Point: Hannaer CT @ Crestwood BlvdEnd Point: Lot 5765Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/SC/CBDate: 4-1-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 16

Street Name: LT Hannaer CT

Compliant		Non-Compliant		Code	Comments
From	To	From	To		

Crestwood Blvd	0+00	0+06	0+06	—	PO	STOP Sign corner
	0+06	4+61	4+61	4+73	CS	
	4+73	5+42	5+42	5+62	CS	
	5+62	8+76	8+78	9+16	CS	
	9+16	9+47	9+47	9+79	CS	
	9+79	12+80				END @ Lot 5765

3275

Start Point: Rainier Dr @ Aly Sheba Way Sidewalk Inventory
 End Point: Lot 6218

18-2
326sa

Direction of Increasing Station: UP

Inspector Name: RF/SC/CB
 Date: 4-1-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 22

Street Name: <u>Rainier Dr</u>	Compliant		Non-Compliant		Code	Comments
From	To	From	To			
<u>Aly Sheba Way</u>	<u>0+00</u>	<u>0+63</u>	<u>0+63</u>	<u>/</u>	<u>DS</u>	<u>6260</u>
	<u>0+63</u>	<u>1+38</u>	<u>1+38</u>	<u>/</u>	<u>DS</u>	<u>6258</u>
	<u>1+38</u>	<u>1+72</u>	<u>1+72</u>	<u>/</u>	<u>DS</u>	<u>6256</u>
	<u>1+72</u>	<u>2+28</u>	<u>2+28</u>	<u>/</u>	<u>PO</u>	<u>Tree</u>
	<u>2+28</u>	<u>2+41</u>	<u>2+41</u>	<u>/</u>	<u>DS</u>	<u>6254</u>
	<u>2+41</u>	<u>3+09</u>	<u>3+09</u>	<u>/</u>	<u>DS</u>	<u>6252</u>
	<u>3+09</u>	<u>3+79</u>	<u>3+79</u>	<u>/</u>	<u>DS</u>	<u>6250</u>
	<u>3+79</u>	<u>4+51</u>	<u>4+51</u>	<u>/</u>	<u>DS</u>	<u>6248</u>
	<u>4+51</u>	<u>5+21</u>	<u>5+21</u>	<u>/</u>	<u>DS</u>	<u>6246</u>
	<u>5+21</u>	<u>5+92</u>	<u>5+92</u>	<u>/</u>	<u>DS</u>	<u>6244</u>
	<u>5+92</u>	<u>6+46</u>	<u>6+46</u>	<u>7+05</u>	<u>CS</u>	<u>6242</u>
	<u>6+46</u>	<u>6+94</u>	<u>6+94</u>	<u>/</u>	<u>DS</u>	<u>6240</u>
	<u>7+05</u>	<u>7+60</u>	<u>7+60</u>	<u>/</u>	<u>DS</u>	<u>6238</u>
	<u>7+60</u>	<u>7+91</u>	<u>7+91</u>	<u>7+97</u>	<u>CS</u>	<u>6236</u>

326sa

2.22

326sb

Start Point: Rainier Dr @ Alysheba Way

End Point: Lot 6218

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: BT/SC/CB

Date: 9-1-19

Total Number of Driveways: see sheet

RT

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	7+97	8+46	8+46	—	DS	6238
	8+46	8+75	8+75	—	DS	6236
	8+75	9+77	9+77	—	DS	6234
	9+77	10+17	10+17	—	DS	6232
	10+17	10+45	10+45	10+70	CS	
	10+45	10+91	10+91	—	DS	6230
	10+91	11+48	11+48	—	DS	6228
	11+48	12+14	12+14	—	DS	6226
	12+14	12+73	12+73	—	DS	6224
	12+73	13+00	13+00	13+21	CS	
	13+21	13+45	13+45	—	DS	6222
	13+45	13+82	13+82	—	DS	6220
	13+82	14+15	14+15	—	DS	6218
	14+15	14+30				END @ Lot 6218

326sa

Start Point: Darlington CT @ Kirkland Dr

3255a

End Point: Lot 6236

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/SC/CB

Date: 4-1-19

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 11

Street Name: <u>Darlington CT</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Kirkland Dr	0+00	0+34	0+34	—	DS	6260
	0+34	0+54	0+54	—	DS	6258
	0+54	1+55	1+55	—	DS	6256
	1+55	2+14	2+14	—	DS	6254
	2+14	2+62	2+62	—	PO	Bush
	2+62	2+81	2+81	—	DS	6252
	2+81	3+21	3+21	—	VC	
	3+21	3+47	3+47	—	DS	6250
	3+47	4+07	4+07	—	DS	6248
	4+07	4+18	4+18	4+30	CS	
	4+30	4+45	4+45	4+61	CS	
Cart	4+61	4+95				
Calvin Way	0+00	1+37	1+37	—	DS	6244
	1+37	3+01	3+01	—	DS	6242

3255a

Sidewalk Inventory
Start Point: Darlington CT @ Kirkland Dr

325sb

End Point: Lot 6236

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: DF/SC/CB
Date: 4-9-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: See Sheet 1

RT

Street Name: <u>Darlington CT</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+01	3+31	3+31	—	DS	6240
	3+31	3+44	3+44	3+55	CS	
	3+44	3+71	3+71	—	DS	6238
	3+71	3+91				END @ lot 6236

3245

End Point: Lot 5766

Direction of Increasing Station: UP

Inspector Name: BF/sc/cb
Date: 4-1-17

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

Compliant

Non-Compliant

From

To

From

To

Code

Comments

[illegible]

3245

3235

End Point: Rolling area #2

Direction of Increasing Station: UD

Reason Codes for NON-COMPLIANCE:

Inspector Name: BT/SC/CB
Date: 4-11-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Mercantile Dr. W						

[illegible]

3235

Sidewalk Inventory

3225

Start Point: Caitlin Way @ Rainier Dr

End Point: Rainier Dr

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: JS/SC/CB
Date: 4-1-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 4

Street Name: <u>Caitlin Way</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Rainier Dr	0+00	0+85	0+85	—	DS	5620
	0+85	1+22	1+22	—	DS	5622
	1+22	1+83	1+83	—	DS	5624
	1+83	2+53	2+53	—	DS	5626
Rainier Dr	2+53	3+13				END @ Darlington CT.

3225

Sidewalk Inventory

3215

Start Point: Stuart Dr @ Hanover Dr

End Point: Hanover Dr

Direction of Increasing Station: UP


Inspector Name: BF/CB/SC
Date: 4-1-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0



Street Name: <u>Stuart Dr</u>		Compliant		Non-Compliant		Code	Comments
From	To	From	To				
Hanover Dr	0+00	0+67					
Rutherford CT	0+00	0+15	0+15	0+39	CS		
	0+39	1+40	1+40	1+48	CS		
	1+48	2+08	2+08	2+71	CS		
	2+71	2+76			-		
Westherby CT	0+00	0+74			-		END @ Hanover Dr

3215

3205

Start Point: Derby Dr @ Alysheba Way

End Point: Alysheba Way

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/SC/CB

Date: 4-1-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 31

Street Name:	Compliant		Non-Compliant			
	From	To	From	To	Code	Comments
	0+00	4+80	4+80	5+07	CS	
	5+07	6+93	6+93	—	VC	
	6+93	10+30	10+30	10+42	CS	
	10+42	12+95	12+95	—	DS	6243
	12+95	13+21	13+21	—	VC	
	13+21	13+55	13+55	—	VC	
	13+55	14+71	14+71	—	VC	
	14+71	15+95	15+95	—	VC	
	15+95	16+61	16+61	—	VC	
	16+61	18+82	18+82	—	VC	
	18+82	19+93	19+93	—	VC	
	19+93	20+01	20+01	—	DS	6267
	20+01	20+35	20+35			6269
	20+35	20+98				END@ Alysheba Way

3205

Sidewalk Inventory

Start Point: Derby Cir @ Alyshoba Way

3195

End Point: Alyshoba Way

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Inspector Name: BF/SC/CB
Date: 4-1-14

Total Number of Driveways: 5



Street Name: <u>Derby Cir</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Alyshoba way</u>	<u>0+00</u>	<u>0+15</u>	<u>0+15</u>	<u>0+23</u>	<u>CS</u>	
	<u>0+15</u>	<u>0+36</u>	<u>0+36</u>	<u>0+72</u>	<u>DS</u>	<u>6301</u>
	<u>0+36</u>	<u>0+51</u>	<u>0+51</u>	<u>0+72</u>	<u>CS</u>	
	<u>0+72</u>	<u>0+95</u>	<u>0+95</u>	<u>1+79</u>	<u>DS</u>	<u>6303</u>
	<u>0+95</u>	<u>1+61</u>	<u>1+61</u>	<u>1+79</u>	<u>CS</u>	
	<u>1+79</u>	<u>3+07</u>			<u>/</u>	<u>END @ Alyshoba Way</u>

3195

Right

3185

End Point: Hahner Dr

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/SC/CB

Date: 9/2/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 11

Street Name: Dorchester Ln From Compliant

Non-Compliant

Street Name:	From	To	From	To	Code	Comments
Dorchester Ln						

[illegible]

3185

Sidewalk Inventory

Start Point: Kara Cir @ Hanover Dr

End Point: Hanover Dr


Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Inspector Name: BT/SC/CB
Date: 4-1-14



Total Number of Driveways: 8

R

Street Name: Kara Cir

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hanover Dr			0+00	0+26	CS	
	0+26	1+85	1+85	1+93	CS	
	1+93	2+85	2+85		VC	
	2+85	4+38	4+38	4+49	CS	
	4+49	4+60				END @ Hanover Dr

Sidewalk Inventory

3F2

Start Point: Kirkland Dr @ Hanover Dr

316Sa

End Point: Foxhall Ct

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/CB/SC
Date: 4-1-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11

Street Name: Kirkland Dr Compliant Non-Compliant Comments

Street Name:	From	To	From	To	Code	Comments
Hanover Dr #1	0+00	4+03	4+03	5+50	CS	No PZ's
	5+50	5+95				
Devonshire Ln			0+00	0+04	CS	
	0+04	0+25	0+25	0+29		
	0+29	0+93	0+93	—	VC	
	0+93	1+78	1+78	—	VC	
			1+78	2+03	CS	No PZ
	2+03	2+23	2+23	—	VC	
	2+23	2+64	2+64	—	VC	
	2+64	2+68	2+68	—	VC	(Cracked Panel)
	2+68	3+08	3+08	3+16	CS	
			3+08	—	PO	Tree
	3+16	3+61	3+61	3+89	CS	
	3+89	4+17	4+17	4+40	CS	

316Sa

Sidewalk Inventory

2F2
[316sb]

Start Point: Kirkland Dr @ Hawver Dr

End Point: Foxhall Ct

Direction of Increasing Station: UP

Reason Codes for NON-COMPLIANCE:

Inspector Name: BT/SC/CB
Date: 4-1-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: See sheet 1

RT

Street Name: Kirkland Dr	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hawver Dr	0+00	2+87	2+87	3+04	CS	
	3+04	3+38				
Wade Ct	0+00	0+88	0+88	1+05	CS	
	1+05	4+41	4+41		VC	No PZ's
	4+41	6+36	6+36	6+52	CS	
Ajon Shine Pl	0+00	1+13	1+13	1+45	CS	
	1+45	4+66				
Alysheba Way	0+00	3+26				
Darlington Ct	0+00	2+56	2+56		PO	Bush
	2+56	2+96				
Foxhall Ct #1	0+00	0+12	0+12	0+40	CS	
	0+40	2+92	2+92	3+22		
	3+22	4+00				END @ Foxhall Ct

[316sb]

Start Point: Alysheba Way, C Sidewalk Inventory
Hanover Dr

End Point: Hanover Dr

Direction of Increasing Station: UP

Inspector Name: BF/SC/CB
Date: 4-1-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name: Alysheba Way From Compliant

Non-Compliant

From

To

Code

Comments

[illegible]

314 Sa

Start Point: Rainier Dr. @ Alysheba Way ² LeftEnd Point: 6218 Rainier Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZKA CMDate: 4/1/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: ✓

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Alysheba Way			0+00	0+06	CS	
	0+06	1+08				
Cayne Ct	0+00	0+55	0+55	0+55	DS	6257
	0+55	1+29	1+29	-	VC	
	1+29	1+42	1+42	1+42	DS	6255
	1+42	2+18	2+18	2+18	DS	6253
	2+18	2+82	2+82	2+82	DS	6251
	2+82	2+93	2+93	2+97	CS	
	2+97	3+56	3+56	3+56	DS	6249
	3+56	4+07	4+07	-	VC	
	4+07	4+32	4+32	4+32	DS	6247
	4+32	5+04	5+04	5+04	PO	Gas cap
	5+04	5+09	5+09	5+13	CS	
	5+13	5+25				

314 Sa

314sb

Sidewalk Inventory

Start Point: Rainier Dr. @ Alysheba Way Left

End Point: 6218 Rainier Dr.

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KA CM
Date: 4/1/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 8

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Caitlin way	0+00	1+08	1+08	1+08	DS	6237
	1+08	1+57	1+57	—	VC	
	1+57	1+67	1+67	—	VC	
	1+67	1+80	1+80	1+80	DS	6235
	1+80	2+51	2+51	2+51	DS	6233
	2+51	3+05	3+05	3+05	VC	
	3+05	3+27	3+27	3+27	DS	6229
	3+27	4+71	4+71	4+71	DS	6225
	4+71	5+66	5+66	5+66	DS	6221
	5+66	5+78	5+78	—	VC	
	5+78	5+99	5+99	5+99	DS	6219
	5+99	6+53				End

314sb

3135a

Sidewalk Inventory

Start Point: Darlington Ct. @ Kirkland Left

End Point: _____

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, CM
Date: 4/1/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Kirkland	0+00	0+85	0+85	0+85	DS	6259
	0+85	1+35	1+35	1+35	DS	6257
	1+35	2+27	2+27	2+27	DS	6255
	2+27	2+44	2+44	—	VC	
	2+44	2+67	2+67	—	VC	
	2+67	3+19	3+19	3+19	DS	6253
	3+19	3+95	3+95	3+95	DS	6251
	3+95	4+74	4+74	4+74	DS	6249
	4+74	5+29	5+29	5+41	CS	
	5+41	5+68	5+68	5+68	DS	6247
	5+68	6+09	6+09	6+09	DS	6245
	6+09	6+70	6+70	6+70	DS	6243
	6+70	7+63	7+63	7+63	DS	6241
	7+63	7+98	7+98	7+98	DS	6239

3135a

Sidewalk Inventory

313 Sb

Sidewalk Inventory

Start Point: Darlington Ct @ Kirkland Left

End Point: 10236 Darlington Ct.

Direction of Increasing Station:

Inspector Name: OZ, KA
Date: 4/1/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 2

Compliant

Non-Compliant

Street Name:

From

To

From

To

Code

Comments

[illegible]

313sb

Sidewalk Inventory

Start Point: Mercantile Dr W @ Hannover Dr. Left

End Point: 5833 Mercantile Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, CM
Date: 4/1/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: _____

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hannover Entrance 1			0+00	1+34	CS	
			0+00	0+25	CS	
	0+25	0+41	0+41	1+01	CS	
Justin Pl			0+00	0+48	CS	
	0+48	2+75				
Entrance 3	0+00	0+90				End

3115

Sidewalk Inventory

Start Point: Hannover Ct @ Crestwood Blvd - Right

End Point: 5765 Hannover Ct.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, CM
Date: 4/1/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 7

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Crestwood	0+00	1+59				
Ewald Ct.	0+00	0+09	0+09	0+18	CS	
	0+18	1+21	1+21	1+33	CS	
	1+33	2+28	2+28	2+28	PO	tree
	2+28	2+85				
Willard Harne Ct.	0+00	0+64	0+64	0+79	CS	
	0+79	1+92	1+92	1+96	CS	
	1+96	2+85	2+85	2+85	DS	5768
	2+85	3+55	3+55	—	VC	
	3+55	4+33	4+33	4+33	DS	5765 End

3115

310Sa

Sidewalk Inventory

Start Point: Kirkland Dr @ Hannover Dr LeftEnd Point: Prince Williams Ct

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/1/14VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding ObjectDS Driveway Cross Slope
CS Panel Cross Slope
WP Width of PanelTotal Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hannover Dr.	0+00	0+58	0+58	0+58	DS	5633
	0+58	1+27	1+27	1+27	CS	
	1+27	1+79	1+79	1+79	DS	5629
	1+79	2+93	2+93	2+93	VC	
	2+93	3+06	3+06	3+25	CS	
	3+25	3+84	3+84	3+95	CS	
	3+95	5+24	5+24	5+24	VC	
	5+24	5+50	5+50	—	VC	
	5+50	7+06				
Denton Ct.			0+00	0+04	CS	
	0+04	3+29				
Hannover Dr.	0+00	1+01	1+01	—	VC	
	1+01	1+21	1+21	—	VC	
	1+21	2+24	2+24	—	VC	

310Sa

3105b

Sidewalk Inventory

Start Point: Kirland Dr @ Hamover Dr - LeftEnd Point: Prince William Ct.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: BZ KADate: 4/1/14Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	2+24	2+86	2+86	3+11	CS	
	3+11	3+25				
Adelay Ct.	0+00	0+39	0+39	1+05	CS	
	1+05	1+54	1+54	1+54	VC	
	1+54	3+81				
Stuart Dr.	0+00	5+60				
Rivendell Pl.			0+00	0+15	CS	
	0+15	5+44	5+44	5+60	CS	
	5+60	5+80				
Rivendell Pl.	0+00	1+82	1+82	-	VC	
	1+82	2+02	2+02	-	VC	
	2+02	3+51	3+51	3+91	CS	
	3+91	4+68				
Brittany Ct.			0+00	0+19	CS	

3105b

Start Point: Kirkland Dr. @ Hannover Dr Left

End Point: Prince William Ct.

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: 02. KLA

Date: 4/1/4

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		

[illegible]

31050

Sidewalk Inventory

Start Point: Devonshire Ln @ Kirkland Dr. LeftEnd Point: Hannover Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, CMDate: 4/1/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 9

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Kirkland Dr.	0+00	0+91	0+91	—	VC	
	0+91	1+62	1+62	1+62	DS	6403
	1+62	1+74	1+74	—	VC	
	1+74	1+86	1+86	—	VC	
	1+86	2+27	2+27	2+27	DS	6401.
	2+27	2+69	2+69	3+01	CS	
	3+01	3+09	3+09	—	VC	
	3+09	3+45	3+45	—	VC	
	3+45	4+78	4+78	4+78	PP	tree
	4+78	4+90	4+90	4+90	VC	
	4+90	6+45	6+45	—	VC	
	6+45	6+81	6+81	—	VC	
	6+81	6+97	6+97	7+06	CS	End

Sidewalk Inventory

3 SS

m

Start Point: Alysheba Way @ Kirkland Dr. - Left

End Point: Hannover Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KA CM
Date: 4/1/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: _____

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Kirkland Dr.			0+00	0+37	CS	
	0+37	0+44	0+44	0+51	CS	
	0+51	1+32	1+32	1+49	CS	
	1+49	1+77	1+77	2+23	CS	
	2+23	2+30	2+30	2+38	CS	
Rainier Dr.			0+00	0+08	CS	
	0+08	2+03				
Derby Dr.	0+00	2+40				
Derby Dr.	0+00	2+26				End

3085

Start Point: ^{count} Glen Cove @ Derby Dr. Left
End Point: Derby Dr.

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: DZ KA CM
Date: 4/11/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Derby Dr.	0+00	0+07	0+07	0+37	CS	
	0+37	3+57	3+57	-	VC	
	3+57	4+08	4+08	-	VC	
	4+08	7+09	7+09	7+21	CS	End

Start Point: Derby Dr. @ Alysheba Left

End Point: Alysheba way

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KA CM
Date: 4/1/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 15

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Alysheba way	0+00	1+43	1+43	—	VC	
	1+43	2+92	2+92	—	VC	
	2+92	3+12	3+12	—	VC	
	3+12	3+51	3+51	—	VC	
	3+51	5+12	5+12	—	VC	
	5+12	5+30	5+30	—	VC	
	5+30	5+53	5+53	5+62	CS	
	5+62	7+39	7+39	—	VC	
	7+39	8+20	8+20	—	VC	
	8+20	9+76	9+76	9+84	CS	
	9+84	9+93	9+93	9+93	DS	6236
	9+93	11+96	11+96	12+03	CS	
	12+03	13+03	13+03	—	VC	
	13+03	13+63	13+63	—	VC	

306sb

Sidewalk Inventory

Start Point: Derby Dr. @ Alysheba LeftEnd Point: Alysheba Way

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KACM
Date: 4/1/14VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding ObjectDS Driveway Cross Slope
CS Panel Cross Slope
WP Width of PanelTotal Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	13+63	14+73	14+73	—	VC	
	14+73	14+82	14+82	—	VC	
	14+82	15+85				
Glen Cove	0+00	1+08	1+08	—	VC	
	1+08	1+51	1+51	—	VC	
	1+51	2+51				End

306sb

3055

Sidewalk Inventory

Start Point: Cayne Ct @ Ranier LeftEnd Point: Ranier

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, CMDate: 4/1/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 7

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Ranier	0+00	0+27	0+27	0+27	DS	5621
	0+27	1+30	1+30	1+30	DS	5623
	1+30	1+68	1+68	1+68	DS	5625
	1+68	1+76	1+76	1+86	CS	
	1+86	1+97	1+97	1+97	DS	5627
	1+97	2+22	2+22	2+22	DS	5626
	2+22	2+34	2+34	-	VC	
	2+34	2+49	2+49	-	VC	
	2+49	2+61	2+61	2+61	DS	5624
	2+61	2+87	2+87	-	VC	
	2+87	3+05	3+05	3+05	DS	5622
	3+05	3+69	3+69	3+69	PZ	tree
	3+69	4+27	4+27	-	VC	
	4+27	4+31				End

3055

Sidewalk Inventory
 Start Point: Mill Run Ct @ Mill Run Pl. - Left
 End Point: Mill Run Pl.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, CM
 Date: 4/1/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 6

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Mill Run Pl	0+00	0+24	0+24	0+44	CS	
	0+44	1+54	1+54	1+54	VC	
	1+54	2+36	2+36	2+46	CS	
	2+46	3+43	3+43	-	VC	
	3+43	4+13	4+13	4+17	CS	
	4+17	4+43	4+43	4+69	CS	
	4+69	4+92				End

Start Point: Mill Run Pl @ Hammoer Dr Left
 End Point: 5714 Mill Run Pl.

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, CM
 Date: 4/1/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hammoer	0+00	1+97	1+97	1+97	VC	
	1+97	2+08	2+08	2+08	DS	5706
	2+08	2+56				
Mill Run Ct.			0+00	0+04	CS	
	0+04	0+56	0+56	1+09	CS	
	1+09	1+67	1+67	1+67	DS	5712
	1+67	2+01	2+01	2+05	CS	
	2+05	2+13	2+13	2+13	DS	5714 End

Sidewalk Inventory

Start Point: Caitlin way @ Brunier Dr. Left

302S

End Point: Darlington ct.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KACM
Date: 4/1/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Brunier	0+00	0+11	0+11	0+21	CS	
	0+21	0+97	0+97	1+06	CS	
	1+06	1+16	1+16	1+16	DS	5623
	1+16	2+60	2+60	3+03	CS	End

302S

Start Point: Fairbanks LA / Fleetwood Ct end of circle

End Point:

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: J.T
Date: 3-31-14 Mon.

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

12

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Fairbanks LA	0+00	0+05	0+05		VC	> 1/2" lip
			0+05	0+40	CS	0+23 PO pine tree 0+37
	0+40	0+54	0+54 0+54	0+88	CS	
	0+88	0+96	0+96	1+08	CS	
	1+08	1+58	1+58	1+70	CS	
	1+70	1+78	1+78		VC	> 1/2" Lip 6404:6406
	1+78	1+99	1+99	2+03	CS	
	2+03	2+28	2+28	2+31	CS	water cap
	2+31	2+53	2+53	2+61	CS	
	2+61	2+82	2+82	2+87	VC	2+65 to 2+73 Relocate bushes 7 1/2" lip @ 9419
	2+87	2+87				
	2+87	3+30	3+30		VC	Water cap
			3+30	3+36	CS	
	3+36	3+45				

Right
2 of 3

1301sb

Start Point: Fairbanks LA Sidewalk Inventory

End Point: _____

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: TJ
Date: 3-31-14 Mon.

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Fairbanks LA			3+45	3+55	CS	
			3+55		DS	@ 9415
			3+55	3+74	CS	
			3+74	3+82	DS	@ 9413
	3+82	3+96	3+96	4+09	CS	
	4+09	4+19	4+19			
	4+19	4+60	4+60	4+67	CS	
Fairbanks LA						
Bridgman Cr West	0+00	0+50	0+50		VC	7 1/2" lip @
	0+50	1+37	1+37		VC	" " @ 9403
			1+43	1+69	DS	@ 9403
			1+43	1+56	CS	
	1+56	1+69	1+69			
	1+69	1+73	1+73	1+82	CS	

Driveways
3

1301sb

30/SC

30/50