

Start Point: Meandering Woods Ct. / #6304 @ cul-de sac

End Point: Lingapore Rd.

Direction of Increasing Station: Right.

Inspector Name: T/S/O
Date: 4-28-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 27

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
#6304 @ cul-de sac	0+00	0+26	0+26		VC	
	0+26	0+60	0+60		VC	
	0+60	3+32	3+32	3+42	CS	
			3+42		DS	6303
			3+42	3+53	CS	
	3+53	6+22	6+22		VC	
	6+22	6+26	6+26		VC	
	6+26	9+10	9+10	9+24	CS	
			9+24		DS	6319
			9+24	9+54	CS	
	9+54	10+33	10+33	10+65	CS	
	10+65	10+99	10+99	11+45	CS	
	11+45	12+12	12+12	12+21	CS	
	12+21	12+75	12+75	12+99	CS	

12+99

DS

6329

12+99

13+00

CS

78359

Start Point: Mandering Woods Ct. / Sidewalk Inventory #6364 E cul-de-sac pg 2 of 2
 End Point: Lingrove Rd.
 Direction of Increasing Station: Right

Inspector Name: T/S/D
 Date: 4-28-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	13+22	13+31	13+31	13+73	CS	
	13+73	14+43	14+43	14+56	CS	
	14+56	15+12				
Town house entrance #6341	0+00	2+10				
Townhouse entrance #6371	0+00	0+91	0+91		VC	
	0+91	0+99	0+99		VC	
	0+99	1+14	1+14		VC	
	1+14	1+23	1+23		VC	
	1+23	2+77	2+77	3+14	CS	Gravel section approx 12' E point 3+09
	3+14	3+49				
Lingrove Rd.	3+49					

7050

Start Point: Prospect Road / Dove Dr

Sidewalk Inventory

121
195
319

End Point: _____

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TJD
Date: 4/23/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Dove Dr	0+00	0+66	0+66	0+66	VC	Greater than 1/2" Gap
	0+66	1+07	1+07	1+07	VC	" " "
			1+07	1+24	CS	
West Ridge Dr	0+00	0+19	0+19	0+19	VC	" " "
	0+19	1+00	1+00	1+00	VC	" " "
	1+00	1+14	1+14	1+14	VC	" " "
	1+14	1+95				
Across from						
Mount Main						
Sign						
1+95						

7825

Sidewalk Inventory

Start Point: Meadowdale CT / Lingard Rd.

End Point: _____

End Point:

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: 8 TS
Date: 4/28/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

[illegible]

7815

Start Point: Mendenhall - Woods Sidewalk Inventory # 6304

End Point: Lingwood Rd.

pg 1 of 2

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: DST
Date: 4/23/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>E cul-de-sac #6304</u>	<u>0+00</u>	<u>0+56</u>	<u>0+56</u>	<u>0+66</u>	<u>CS</u>	
			<u>0+66</u>		<u>DS</u>	<u>6306</u>
			<u>0+66</u>	<u>0+80</u>	<u>CS</u>	
	<u>0+80</u>	<u>1+20</u>	<u>1+20</u>		<u>VC</u>	
	<u>1+20</u>	<u>1+41</u>	<u>1+41</u>		<u>VC</u>	
	<u>1+41</u>	<u>1+48</u>	<u>1+48</u>		<u>PO</u>	<u>Manhole</u>
	<u>1+48</u>	<u>3+69</u>	<u>3+69</u>		<u>VC</u>	
			<u>3+69</u>	<u>3+95</u>	<u>CS</u>	
			<u>3+95</u>		<u>DS</u>	<u>6312</u>
			<u>3+95</u>	<u>4+05</u>	<u>CS</u>	
	<u>4+05</u>	<u>4+51</u>	<u>4+51</u>		<u>PO</u>	<u>Sewer c/o</u>
	<u>4+51</u>	<u>5+66</u>	<u>5+66</u>		<u>VC</u>	
	<u>5+66</u>	<u>6+06</u>	<u>6+06</u>		<u>VC</u>	
	<u>6+06</u>	<u>6+10</u>	<u>6+10</u>		<u>VC</u>	

7808a

Sidewalk Inventory

Start Point: Meadowood Ct. / E Col-de-sac 6304

End Point: ~~Lingapore Rd.~~ Townhome Entrance #6372

Direction of Increasing Station: Left

pg 2 of 2

Inspector Name: T/5/B

Date: 4-28-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 6

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	6+10	6+42	6+42	6+56	CS	
			6+56		DS	6320
			6+56	6+67	CS	
	6+67	7+39	7+39	7+43	CS	
	7+43	8+12	8+12	8+23	CS	
	8+23	11+48	11+48		VC	
	11+48	12+92	12+92		VC	
	12+92	13+24	13+24	13+74	CS	
	13+74	13+97	13+97	14+25	CS	
	14+25	15+00	15+00	15+16	CS	
	15+16	16+84				
Townhome Entrance #6372	16+84					

7808

Start Point: ~~6~~ Industry Lane / Sidewalk Inventory / Misc. Medals

End Point: Guilford Dr.

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/S/S
Date: 4-28-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Misc. Medals	0+00	0+23				
Guilford Dr.	0+23					

2188

Start Point: Tuscarora Dr. / Yellow Springs Rd. / Hawthorne Dr.
 End Point: Hawthorne Dr.

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: D.J.T.

Date: 4/23/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 21

Dr 2?

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hawthorne Dr.			0+00	0+14	CS	Trim Trees: Brushes
# 2138.	0+14	0+30	0+30	0+41	CS	
			0+41	0+41	DS	# 2186
			0+41	0+54	CS	
	0+54	0+65	0+65	0+65	VC	Greater than 1/2" Gap
	0+65	1+14	1+14	1+14	VC	
	1+14	1+26	1+26	1+36	DS	
			1+36	1+49	CS	# 2184
	1+49	1+57	1+57	1+57	VC	> 1/2" Gap
	1+57	1+78	1+78	1+78	VC	" ~ ~ ~
	1+78	1+86	1+86	1+97	CS	Ends to Out Fall
Hawthorne Dr.						Transformer 35084
197						

7785

Start Point: Hayward Road / Arrowhead Ct. (Crosswalk)

End Point: Oppossumtown Pike

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: T/S/JS
Date: 4-25-14

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Arrowhead Ct.	0+00	1+50	1+50	1+69	CS	
	1+69	2+69	2+69		VC	
	2+69	3+02	3+02	3+10	CS	missing section of sidewalk panel
	3+10	3+24	3+24		VC	
Private Driveway	0+00	2+49	2+49	2+59	CS	
Honey Clover Ct.	0+00	0+91	0+91		VC	
	0+91	1+31	1+31	1+51	CS	
	1+51	1+71	1+71		VC	
	1+71	1+91	1+91		VC	Trim tree
	1+91	2+15				
Oppossumtown Pike	2+15					

17775

Start Point: Hayward Road / Sidewalk Inventory
Opposuntown Pike

End Point: Arrowhead Ct.

Direction of Increasing Station: Left

Inspector Name: T/O/S
 Date: 4-25-04

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Opposuntown Pike	0+00	0+37	0+37		VC	
	0+37	0+98	0+98		PD	TREE Trim, Excessive grass joints
			0+98	1+22	CS	
	1+22	1+59	1+59	1+83	CS	
	1+83	2+19	2+19		VC	
	2+19	2+76	2+76	2+88	CS	
	2+88	4+12	4+12	5+92	CS	
Morning Dew Ln.	0+00	0+14	0+14	1+87	CS	
	1+87	2+42				
Arrowhead Ct.	2+42					

7765

Start Point: Opposumtown Pike / Rainbow Lane Sidewalk Inventory

End Point: Hayward Road

Direction of Increasing Station: left

Inspector Name: T/D/S
Date: 4-25-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Rainbow Ln.	0+00	0+22	0+22		VC	? noticeable
	0+22	8+48	8+48		VC	"
	8+48	10+74				
Hayward Rd.	10+74					

7755

Start Point: Opposuntown Pike / ^{Sidewalk Inventory} Hayward Road

End Point: Middle School Entrance

Direction of Increasing Station: Left

Inspector Name: T/D
Date: 4-25-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Hayward Rd.	0+60	0+23	0+23		VC	
	0+23	0+39	0+39	2+06	CS	
	2+06	3+97	3+97		VC	
	3+97	4+13	4+13	4+28	CS	
	4+28	5+74	5+74		VC	
	5+74	5+94	5+94		VC	
Middle School	5+94					
Entrance						

7745

Start Point: Opposumtown Pike / End of sidewalk Sidewalk Inventory

End Point: Opposumtown Pike / Willowbrook Dr.

Direction of Increasing Station: Right

Inspector Name: T/D/S
Date: 4-25-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
End of sidewalk	0+00	1+11	1+11	1+19	CS	
	1+19	1+55	1+55	1+64	CS	
St. John's School			0+00	0+19	CS	
Entrance	0+19	1+39	1+39		VC	
	1+39	4+92	4+92	4+96	CS	
Opposumtown Pike / Willowbrook Dr.	4+96					

7735

Start Point: Grove Hill Road / Toys R' Us Entrance Sidewalk Inventory

End Point: Rt. 40

Direction of Increasing Station: Right

Inspector Name: T/S
Date: 4-25-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Toys R' Us Entrance	0+00	0+05	0+05		VC	
	0+05	0+40	0+40		VC	
	0+40	0+75	0+75		VC	
	0+75	0+80				
BB&T Entrance	0+00	0+06	0+00	0+06	CS	
	0+06	0+31	0+31		VC	
	0+31	0+46	0+46		VC	
	0+46	0+96	0+96		VC	
	0+96	1+06	1+06		VC	
	1+06	1+17	1+17		VC	
	1+17	1+37				
Rt. 40	1+37					

7725

Start Point: Eagletrace Dr @ Country Club Rd L
End Point: Inverness Ct.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, RH
Date: 4/23/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 7

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Country Club Rd: L	0+00	2+60	2+60	2+60	DS	11104
	2+60	3+39	3+39	3+39	DS	11106
	3+39	4+18	4+18	4+18	DS	11108
	4+18	4+89	4+89	4+89	DS	11110
	4+89	5+77	5+77	5+77	DS	11112
Inverness Ct.	5+77	6+30				End

7725

7725

Start Point: Grove Hill Road / RT. 40 Sidewalk Inventory

End Point: End of sidewalk

Direction of Increasing Station: Right.

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/S
Date: 4-25-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
RT. 40	0+00	0+29				
Exxon Entrance	0+00	0+11	0+11		✓	
	0+11	0+16	0+16		✓	
	0+16	0+37				
Grove Hill	0+00	0+30	0+30	0+67	CS	
Rd.	0+67	0+80				
End of Sidewalk	0+80					

7705

Start Point: Wise Ct. @ Gibbons Rd. ✓

End Point: 1594 Wise Ct.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/24/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 4

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Gibbons Rd.	0+00	0+61	0+61	0+61	DS	1599
	0+61	1+62	1+62	—	VC	
	1+62	3+40				End

7695



WHITE ROCK

SUBDIVISION


7015 HO

5897





















White Rock Dr. /
Ave. /
Flint Circle

Sidewalk Inventory

Start Point:

End Point:

Direction of Increasing Station:

Right

NOTE: no sidewalk on the left side

Inspector Name:

Date:

T/S

9-24-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

6

Street Name:

Compliant

Non-Compliant

From

To

From

To

Code

Comments

Flint Circle			0+00	1+92	CS	All sidewalk failed
Flint Circle / Granite Circle	White Rock Dr		0+00	1+84	CS	All sidewalk failed
Granite Bethel			0+00	1+16		
			1+16	1+16		→ SEE Pictures - 4" drop
			1+16	3+04		All sidewalk failed

1675





Start Point: White Rock Ave. Sidewalk Inventory

End Point: Boulder Rd

Direction of Increasing Station: Right

Inspector Name: T.W
Date: 4-24-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Entire street side walk
Failed VC/PP/PZ/PO/
DS, CS, and WP.

Total Number of Driveways:

111

Add note
here

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Bethel Rd: R	0+00	0+19	0+19	0+19	VC	greater than 1/2" up
	0+19	0+35	0+35	1+18	CS	
	1+18	1+27	1+27	1+27	VC	" "
	1+27	1+40	1+40	1+40	VC	" "
	1+40	1+51	1+51	1+64	CS	
	1+64	1+91	1+91	1+91	VC	" "
	1+91	2+18	2+18	2+18	VC	" "
	2+18	2+26	2+26	2+73	CS	
	2+73	2+86	2+86	2+86	VC	" "
	2+86	2+90	2+90	2+90	VC	" "
	2+90	2+98	2+98	2+98	VC	" "
	2+98	3+33	3+33	3+49	CS	
	3+49	3+57	3+57	3+90	CS	
	3+90	3+97	3+97	4+14	CS	

Start Point: White Rock Ave. Sidewalk Inventory

End Point: Boulder Rd

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T.W
Date: 4-24-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

+++

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	4+14	4+47	4+47	4+50	CS	
	4+50	4+54	4+54	4+75	CS	
	4+75	4+95	4+95	5+28	CS	
Circle	5+28	5+48	5+48	5+48	VC	greater than 1/2" lip
	5+48	5+53	5+53	6+60	CS	
New sidewalk	6+60	7+26	7+26	7+30	CS	End of new sidewalk 7+30
Boulder Rd			7+30	8+67	CS	
8+67						

Start Point: Boulder Rd Sidewalk Inventory

End Point: Bethel Rd

Direction of Increasing Station: left

Reason Codes for NON-COMPLIANCE:

Inspector Name: TW
Date: 4-24-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways:

*Trim Bushes
From Walkway*

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Boulder Rd			0+00	4+90	CS	All side walks
@ 9401						Graded to WP.

Sidewalk Inventory

Start Point: Boulder Rd Sidewalk Inventory over

End Point: ~~XXXXXX~~ White Rock Ave.

Direction of Increasing Station: left

Reason Codes for NON-COMPLIANCE:

Inspector Name: T.W
Date: 4-24-19

VC Vertical Clearance

DS Driveway Cross Slope

pp Pinch Point

CS Panel Cross Slope

PZ: Passing Zone

WP Width of Panel

PO Protruding Object

Total Number of Driveways:

Street Name:

Compliant

Non-Compliant

From

To

From


To

Code

Comments

[illegible]

7645



Start Point: Boulder RD / Stone Hill Rd.

End Point: White Rock Ave

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: TJ
Date: 4/24/14

- ☒ VC Vertical Clearance
- ☒ PP Pinch Point
- ☒ PZ Passing Zone
- ☒ PO Protruding Object

- ☒ DS Driveway Cross Slope
- ☒ CS Panel Cross Slope
- ☒ WVP Width of Panel

Total Number of Driveways: TH 11 (7)

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Stoney Hill Rd			0+00	3+48	CS	All Failed. Trim
Quartz Cr.			0+00			3+00 Trim Trees
Quartz Cr.			0+00	0+83	CS	
			0+83	0+98	CS	removed side walk now
			0+98	1+58	CS	water pipe mound & grade
White Rock Ave						side walk Dead Ends
158						

7635

Start Point: Quartz Sidewalk Inventory Cin - Boulder Rd

End Point: Quartz Cir Boulder Rd

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/S
Date: 4/24/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: ~~7~~ 4 1 1 1 1 9

Street Name: Boulder Rd

Compliant

From

To

Non-Compliant

From

To

Code

Comments

[illegible]

7625

Start Point: Comus Rd. / circle Sidewalk Inventory

End Point: _____

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: WTTJ
Date: 4/24/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Comus Rd.	0+00	0+39	Right			Large gap Bank Joint.
Home # 7902						Many JC Due to Bank Slope
Right.						
	0+00	0+41	0+41	0+41	PO	Stop Sign - ^{Sign} All wall
	0+41	0+59				No Mountain Sides
Comus to Sign						Strong MAUSION.
Cont. MTN. Rd	0+00	0+23				See Comments above about Brick
Right						S- Intersection

7605

Start Point: CANADA Hill Road / End of sidewalk Sidewalk Inventory

End Point: HUNTERS Knoll

Direction of Increasing Station: ~~Left~~ Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/B/W/T
Date: 4-23-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
End of sidewalk	0+00	1+13	1+13		VC	
	1+13	2+13	2+13		VC	
	2+13	2+82	2+82		VC	
	2+82	2+90	2+90		VC	
	2+90	2+98				
HUNTERS Knoll	2+98					

7595

[Signature]

Start Point: Canada Hill Rd / Canada Hill Dr

End Point: _____

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T.T.J.W
Date: 4-23-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: Trim trees ~~0~~

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Canada Hill Dr.	0+00	0+25	0+25	0+25	VC	greater than 1/2" Lip
	0+25	0+29	0+29	0+44		
			0+44	0+44	VC	" "
	0+44	0+73	0+73	0+73	VC	" "
	0+73	1+14	1+14	1+14	VC	" "
	1+14	1+33	1+33	1+33	VC	" "
	1+33	2+83	2+83	2+83	VC	" "
	2+83	3+73	3+73	3+73	VC	" "
	3+73	4+13	4+13	4+13	VC	" "
	4+13	4+16	4+16	4+16	VC	" "
	4+16	4+34	4+34	4+34	VC	" "
	4+34	4+94	4+94	4+94	VC	" "
	4+94	5+14	5+14	5+14	VC	" "
	5+14	5+34	5+34	5+34	VC	" "

Start Point: Canada Hill Rd / Canada Hill Drive

End Point: _____

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T.T.J.W
Date: 4-23-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	5+34	5+69	5+69	5+79	CS	Gravel from 1/2 L.p.
	5+79	6+28	6+28	6+28	VC	" " " "
	6+28	6+42	6+42	6+47	CS	Need Hand laid Culvert Pipe Hand laid
	6+47	6+53	6+53	6+53	VC	> 1/2" Gap
	6+53	7+98	7+98	7+98	VC	" " "
	7+98	8+18	8+18	8+18	VC	" " "
	8+18	8+40	8+40	8+40	VC	> 1/2" Gap
	8+40	8+98	8+98	8+98	VC	" " " "
	8+98	10+18	10+18	10+18	VC	" " " "
	10+18	10+59	10+59	10+59	VC	> 1/2" Gap
	10+59	10+78	10+78	10+78	VC	" " " "
	10+78	11+19	11+19	11+19	VC	" " " "
	11+19	11+39	11+39	11+39	VC	" " " "
	11+39	11+99	11+99	11+99	VC	" " " "

7585b

Start Point: Canada Hill Rd / Canada Hill Drive

End Point: _____

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Inspector Name: SWTT

Date: 4/23/14

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	11+99	12+20	12+20	12+20	VC	Grate to 1/2" Lip
	12+20	12+39				
Meadow Ridge Dr.	0+00	0+08	0+08	0+08	VC	" "
	0+08	0+28	0+28	0+32	VC	Replace section
	0+32	1+02	1+02	1+02	VC	" "
	1+02	1+07	1+07	1+07	VC	" "
	1+07	1+70	1+70	1+70	VC	" "
	1+70	2+05	2+05	2+05	VC	" "
	2+05	3+05	3+05	3+05	VC	" "
	3+05	3+89	3+89	3+89	VC	" "
	3+89	3+99	3+99	3+99	VC	" "
	3+99	4+78	4+78	4+78	VC	" "
	4+78	5+36	5+36	5+36	VC	" "
	5+36	5+41	5+41	5+41	VC	" "

End Point: _____

Reason Codes for NON-COMPLIANCE:

Total Number of Driveways: ~~0~~

7585d

Sidewalk Inventory

Start Point: Country Club Rd @ Sanandrew Dr. (L)

End Point: Sanandrew Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, RH
Date: 4/23/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 10

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	0+00	0+11	0+11	—	VC	
	0+11	5+15				
Eagletrace Dr.	0+00	1+94	1+94	—	VC	
	1+94	3+08				
Fair Lane	0+00	0+96	0+96	—	VC	
	0+96	2+06	2+06	—	VC	
	2+06	2+16	2+16	—	VC	
	2+16	2+74	2+74	—	VC	
	2+74	2+85	2+85	—	VC	
	2+85	3+14	3+14	3+14	DS	11234
	3+14	3+26	3+26	—	VC	
	3+26	3+30	3+30	3+30	PO	sewer cleanout
	3+30	3+57	3+57	—	VC	
	3+57	3+72	3+72	3+72	CS	

Sidewalk Inventory

Start Point: Country Club Rd. @ Sanandrew Dr.End Point: Sanandrew Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: DZ KA. 2HDate: 7/23/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+79	4+57	4+57	4+57	DS	11238
	4+57	4+87	4+87	—	VC	
	4+87	4+98	4+98	—	VC	
	4+98	5+28	5+28	5+28	DS	11240
	5+28	5+64	5+64	—	VC	
	5+64	6+64	6+64	6+64	DS	11244
	6+64	7+97	7+97	—	VC	
	7+97	8+27	8+27	8+27	DS	11248
	8+27	8+30	8+30	—	VC	
	8+30	8+51	8+51	—	VC	
	8+51	8+64	8+64	—	VC	
	8+64	9+54	9+54	9+67	CS	
	9+67	9+79				

75150

Sidewalk Inventory

Start Point: Country Club Rd @ Sanandrew Dr. E

End Point: Sanandrew Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ KA RH
Date: 4/23/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 8

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Pond Fountain			0+00	0+19	CS	
			0+19		VC	
	0+19	0+27	0+27		VC	
	0+27	0+51	0+51		VC	
	0+51	0+70	0+70		VC	
	0+70	1+11	1+11		VC	
	1+11	1+74	1+74		VC	
	1+74	1+83	1+83		VC	
	1+83	2+53	2+53		VC	
	2+53	2+61	2+61		VC	
	2+61	3+05	3+05		VC	
	3+05	3+18	3+18		VC	
	3+18	3+26	3+26		VC	
	3+26	3+46	3+46		VC	

Start Point: Country Club Rd @ Sanandrew Dr. ←

End Point: Sanandrew Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: 07 KA RH
Date: 4/23/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 8

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+46	3+70	3+70			
	3+70	5+48	5+48			
	5+48	5+77	5+77			
	5+77	5+97	5+97		CS	
	5+97	6+81	6+81		DS	11278
	6+81	7+80	7+80		DS	11280
	7+80	9+29	9+29		DS	11282
	9+29	10+00	10+00		DS	11284
	10+00	10+79	10+79		DS	11286
	10+79	11+24	11+24		DS	11288
	11+24	12+02	12+02			11290
	12+02	14+71	14+71			11296
	14+71	16+12				
11302 Country Club Rd			0+00	2+08	CS	

75750 ~~45880~~

Sidewalk Inventory

Start Point: Country Club Rd @ Sanandrew Dr. E

End Point: Sanandrew Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: DZ KA. RH
Date: 4/28/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 8

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
			0+80		DS	11302
			1+32		DS	11304
			0+00	2+89	CS	
			0+75		DS	11308
			1+23		DS	11310
			2+61		DS	11312
			0+00	2+53	CS	
			0+27		DS	11324
			1+09		DS	11326
			2+23		DS	11328 / End.

Sidewalk Inventory

Start Point: Pond Fountain Ct. @ Country Club Rd. (R)

End Point: Country Club Dr

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, RH
Date: 4/23/21

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 30

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Country Club Rd.			0+00	0+08	CS	
	0+08	0+92	0+92	1+01	CS	
	1+01	2+10	2+10	—	VC	
	2+10	2+28	2+28	2+28	DS	11109
	2+28	4+09	4+09	—	VC	
	4+09	4+31	4+31	4+42	CS	
	4+42	4+57	4+57	—	VC	
	4+57	6+82	6+82	7+02	CS	
	7+02	7+89	7+89	8+01	CS	
	8+01	8+24	8+24	—	VC	
	8+24	10+18	10+18	10+27	CS	
	10+27	12+59	12+59	12+59	DS	11163
Country Club Rd.	12+59	12+75	12+75	15+70	CS	End

75CS

Start Point: Country Club Rd @ Sanandrew Dr. (R)

End Point: Sanandrew Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, RH
Date: 4/22/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 21

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Sanandrew Dr: R	0+00	4+12	4+12	—	VC	
	4+12	7+42	7+42	—	VC	
	7+42	8+21	8+21	—	VC	
	8+21	8+56	8+56	—	VC	
	8+56	9+21	9+21	—	VC	
	9+21	9+80	9+80	9+92	CS	
	9+92	10+21	10+21	—	VC	
	10+21	10+83	10+83	—	VC	
	10+83	12+17	12+17	—	VC	
	12+17	12+35	12+35	—	VC	
	12+35	12+71	12+71	—	VC	
	12+71	13+99	13+99	—	VC	
	13+99	14+56	14+56	—	VC	
	14+56	14+62	14+62	14+74	CS	

7555a

8/73

Sidewalk Inventory

Start Point: Country Club Rd @ Sanandrew Dr R

End Point: Sanandrew Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, RH
Date: 4/23/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: |

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	14+74	16+76	16+76	17+16	CS	
	17+16	17+23	17+23	17+23	DS	11257
11257 Country Club Rd.	17+23	17+36				
Path before Bledon Ct.			0+00	1+27	CS	
Entrance to Bledon Ct. Clubhouse			0+00	1+78	CS	
Entrance to Club House			0+00	3+65	CS	End

75550 75551

Sidewalk Inventory

Right

Start Point: Barngate Pk - Meadow Way

End Point: Meadow Way

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: JH/CB
Date: 4/10/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

7545

5278

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Meadow Way	0+00	0+13	0+13	-	VC	Gas Valve in Sidewalk
	0+13	0+86	0+86	-	VC	
	0+86	2+34				
Vineyard Path	0+00	2+97				
Vineyard Path	0+00	2+85				
Bucks Run Trl	0+00	2+99				
Bucks Run Trl	0+00	1+17	1+17	1+17	VC	
	1+17	4+13				
Honey Glen Ct	0+00	1+92	1+92	-	PZ	
	1+92	2+19				End
Hearthstone Trl	0+00	2+29				
Heatherfield	0+00	0+23	0+23	-	VC	
PI	0+23	1+09	1+09	1+09	PO	Gas Valve - End

7545

5278

Start Point: Riverside Place / River Run Rd

End Point: _____

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____
Date: _____

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: _____

7535 78
165
267
530

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
River Run Rd	0+00	0+59	0+59	0+59	VC	Greater than 1/2" Lip
	0+59	0+89	0+89	0+89	VC	" " " "
	0+89	0+98				
Swimming Pool	0+00	0+14	0+14	0+14	VC	> 1/2" concrete joint plus ^{sewer} hole and
Entrance	0+14	0+25	0+25	0+25	VC	> 1/2" Lip
	0+25	1+55	1+55	1+55	VC	
	1+55	1+65	1+65	1+65	VC	> 1/2" Lip
Thrush Ct.			0+00	0+49	VC	> " "
	0+49	0+68	0+68	0+78	CS	
	0+78	1+76	1+76	1+76	VC	> 1/2" Lip
	1+76	2+67	2+67	2+72	CS	
Wind sail Ct						
2+67						

7535

Start Point: Waterside Dr. / Red wing. Sidewalk Inventory

7525

4' 5"
257
632

End Point: _____

Direction of Increasing Station: Left Gory toward R 26

Reason Codes for NON-COMPLIANCE:

Inspector Name: W.S
Date: 4/22/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Red wing			0+00	0+16	CS	
	0+16	1+15	1+15	1+15	VC	Greater than 1/2" slope
	1+15	2+82	2+82	2+91	CS	
	2+91	3+77	3+77	3+77	VC	" " " "
	3+77	4+25				
River Run Rd	0+00	1+60	1+60	1+60	VC	" " " "
	1+60	2+00	2+00	2+00	VC	> 1/2" Lip
	2+00	2+25	2+25	2+25	VC	" " "
	2+25	2+36	2+36	2+36	VC	
	2+36	2+42	2+42	2+42	VC	" " " "
	2+42	2+57				
Blue Heron Dr.						
257						

7525

Stottemeyer Rd

(Ramp - No)

19R

751sa

Start Point: ~~Stottemeyer~~

Sidewalk Inventory

/ Home

End Point:

See Page 2 Wolfsville Rd

Direction of Increasing Station:

Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: WDTJ

Date: 4/22/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
12416 Home 12	0+00	0+00	0+07	0+07	VC	Gravel thru 1/2" Gap
	0+07	0+62	0+62	0+62	VC	---
			0+62	1+02	CS	
	1+02	1+12	1+12	1+23	CS	
			1+23	1+23	DS	12403
			1+23	1+48	CS	Trim Bushes
	1+48	2+07	2+07	2+07	VC	> 1/2 Gap
	2+07	2+19	2+19	2+23		
			2+23	2+23	DS	12406? Gray house
			2+23	2+43	CS	Trim Bushes
	2+43	2+63	2+63	2+63	VC	> 1/2 Gap
	2+63	2+93	2+93	2+93	VC	
			2+93	3+09	CS	
			3+09	3+09	DS	

751sa

75.5b

Start Point: River Run Rd. / Schooner Ct.

End Point: _____

Direction of Increasing Station: Right

2.7
173
49
462

Reason Codes for NON-COMPLIANCE:

Inspector Name: W.J.
Date: 04/22/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

750s

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Schooner Ct.	0+00	0+06	0+06	0+06	VC	Greater than 1/2" Gap
	0+06	0+51	0+51	0+51	VC	" " " "
	0+51	0+61	0+61	0+61	VC	> 1/2" Gap
	0+61	0+76	0+76	0+76	VC	" " " "
	0+76	1+33	1+33	1+33	VC	" " " "
	1+33	1+49	1+49	2+07	CS	
	2+07	2+40				
Clippers Ct.	0+00	0+03	0+03	0+03	VC	Top 9 Ramp Slope
	0+03	0+81	0+81	0+81	VC	> 1/2" Gap
	0+81	1+32	1+32	1+32	VC	> 1/2" Gap
	1+32	1+73				
Quay Ct.	0+06	0+49				
water side Dr						
0+49						

750s

Start Point: Waterside Drive / River Run Road (7495)

End Point: Blue Heron Drive

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/D
Date: 9-22-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
River Run Rd.	0+00	0+47	0+47		VC	
	0+47	0+57	0+57		VC	
	0+57	0+72	0+72		VC	
	0+72	1+74	1+74	1+78	CS	
	1+78	2+34	2+34	2+38	CS	
	2+38	3+66	3+60	4+40	CS	
	4+40	4+77	4+77	5+41	VC	
	4+77 5+41	5+62	5+62	5+66	CS	
	5+66	5+74	5+74		VC	
	5+74	5+82	5+82		VC	
	5+82	6+14				
Blue Heron Dr.	6+14					

7495

Start Point:

River Run

Sidewalk Inventory

193

work zone

work zone

420

End Point:

Direction of Increasing Station:

Left

74852

Reason Codes for NON-COMPLIANCE:

Inspector Name:

WJ

Date:

4/22/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:

Compliant

From

To

Non-Compliant

From

To

Code

Comments

Waterside Dr.	0+00	0+20	0+20	0+20	VC	Greater than 1/2" Gap
	0+20	0+66	0+66	0+66	VC	" " " "
	0+66	0+76	0+76	0+91	CS	
	0+91	1+16	1+16	1+21	CS	
	1+21	1+57	1+57	2+07	CS	
	2+07	2+16	2+16	2+16	VC	" " " "
	2+16	2+65	2+65	2+65	VC	> 1/2" Gap
	2+65	4+25				
Blue Heron Dr.	0+00	0+05	0+05	0+05	VC	" " "
	0+05	0+11	0+11	0+11	VC	" " " "
	0+11	0+36	0+36	0+36	VC	" " " "
	0+36	1+66	1+66	1+66	VC	" " " "
	1+66	2+26	2+26	2+26	VC	" " " "
	2+26	2+46	2+46	2+46	VC	

74852

293

Start Point: River Run Rd / Water side Dr

Sidewalk Inventory

58
121
424

End Point:

Direction of Increasing Station:

Left

748sb

Reason Codes for NON-COMPLIANCE:

Inspector Name: WS

Date: 4/22/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Water side Dr	2+46	3+96	3+96	3+96	VC	Greater than 1/2" Lip
	3+96	5+50	5+50	5+55	CS	
REED Ct.	0+00	0+55	0+55	0+55	VC	" " " "
River Run Reed Ct.	0+55	0+85	0+85	0+85	VC	" " " "
	0+85	1+54	1+54	1+59	CS	
Reed Ct			0+00	0+05		
	0+05	1+29	1+29	1+29	VC	> than 1/2" Lip
	1+29	1+38	1+38	1+58	CS	
	1+58	2+78	2+78	2+78	VC	" " " "
	2+78	3+14	3+14	3+14	VC	" " " "
	3+14	4+14	4+14	4+19	VC	Entire slab plus storm hole
	4+19	4+24				
Broken Reed Ct	0+00	0+05	0+05	0+05	PO	Storm drain new hole &
	0+05	1+31	1+31	1+31	VC	> 1/2" Lip

748sb

393

+485c

Start Point: River Run Rd / ^{Sidewalk Inventory} Waterside Dr.

286

End Point: Waterside Dr

88

153

Direction of Increasing Station: LEFT

Reason Codes for NON-COMPLIANCE:

Inspector Name: W/S
Date: 7/22/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Broken Road Ct	0+30	2+64	2+64	2+74	CS	
	2+74	2+74	2+74	2+86		
	2+74	2+86				
Hollow Road Ct	0+00	0+88				
Blue Heron	0+00	0+08	0+08	0+08	VC	Grate thru 1/2" gap
Dr.	0+08	1+30	1+30	1+30	VC	
	1+30	1+47	1+47	1+53	CS	
Waterside Dr.						
153						

7485c

Start Point: RIVERSide Place / River Run Road Sidewalk Inventory

7475

End Point: WATERVIEW COURT

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/D
Date: 4-22-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
River Run Rd.	0+00	0+93				
Lighthouse Landing	0+00	0+25	0+25		VC	
	0+25	0+70	0+70	0+90	CS	
	0+90	2+67	2+67		VC	
Harbor Place	0+00	1+48				
Waterview Ct.	1+48					

7475

7465

Start Point: Cleasonville Rd / Rt. 26 Sidewalk Inventory

End Point: Unionville Road

Direction of Increasing Station: Left.

Inspector Name: D/W
Date: 4-22-14

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 10

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Rt. 26	0+00	0+36				#8839; 3' wide sidewalk
←	GAP IN SIDEWALK					
			0+00	0+73	CS	near #8821; 2 1/2' brick sidewalk
←	GAP IN SIDEWALK					
	0+00	0+40				#8819; 3' wide sidewalk
←	GAP IN SIDEWALK					
	0+00	0+69	0+69	0+78	CS	#8815; 3 1/2' sidewalk
			0+78		DS	#8815
			0+78	0+84	CS	
	0+84	1+66	1+66	1+74	CS	
			1+74		DS	#8813
			1+74	1+88	CS	
	1+88 1+88	3+47	1+88			near #8811
←	GAP IN SIDEWALK					

Unionville Rd. 1+04

0+00 1+04 CS GRASS/cracks in sidewalk

7465

7455

ing Station: Left

Inspector Name: T/O
Date: 4-22-14

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

745s

Start Point:

River Run Road / Waterside Drive

pg 1 of 2

74452

End Point:

Waterside Drive

Direction of Increasing Station:

Right

Reason Codes for NON-COMPLIANCE:

Inspector Name:

T/D

Date:

4-22-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways:

0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Waterside Drive	0+00	0+72				
Store Entrances	0+00	0+82				
Daycare Entrance	0+00	0+58	0+58		VC	
	0+58	1+93	1+93		VC	
	1+93	2+24				
Riverside Place	0+00	3+85	3+85	3+93	CS	2+95 asphalt d/w on path
Admiralty Place			0+00	0+04	CS	
	0+04	0+20	0+20	0+37	CS	
	0+37	0+57	0+57	0+69	CS	
	0+69	1+08	1+08		VC	
	1+08	1+46	1+46		PO	TREE
	1+46	2+54	2+54		PO	Tree
	2+54	5+07				
Admiralty Place			0+00		VC	

74452

Start Point: River Run Road / Sidewalk Inventory

pg 2 of 2

(7445b)

End Point: Waterside Drive

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/D
Date: 4-22-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	0+00	0+90				
Captains Ct.	0+00	2+29				
Parkland Place	0+00	0+49	0+49		VC	
	0+49	2+23	2+23		VC	
	2+23	2+79	2+79		VC	
	2+79	2+90	2+90		VC	
	2+90	3+01	3+01		VC	
	3+01	3+06				
Waterside Ct.	0+00	2+50	2+50		VC	
	2+50	2+57	2+57		VC	Gas Valve
	2+57	2+63	2+63		VC	
	2+63	2+71	2+71		VC	
	2+71	3+09				
Waterside Drive	3+09					

7445b

Sidewalk Inventory

Start Point: Country Club Rd @ Sanandrew Dr

7435

End Point: Country Club Rd @ House Address 11046

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, CM
Date: 4/22/2014

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 24

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Sanandrew Dr</u> <u>Right side</u>	<u>0+00</u>	<u>1+49</u>	<u>1+49</u>	<u>1+49</u>	<u>VC</u>	
	<u>1+49</u>	<u>2+23</u>	<u>2+23</u>	<u>—</u>	<u>VC</u>	
	<u>2+23</u>	<u>2+67</u>	<u>2+67</u>	<u>2+67</u>	<u>PO</u>	<u>Tree</u>
	<u>2+67</u>	<u>7+63</u>	<u>7+63</u>	<u>7+63</u>	<u>PO</u>	<u>Tree / Bush</u>
	<u>7+63</u>	<u>12+00</u>	<u>12+00</u>	<u>12+00</u>	<u>VC</u>	
	<u>12+00</u>	<u>15+52</u>	<u>15+52</u>	<u>15+61</u>	<u>CS</u>	
	<u>15+61</u>	<u>16+54</u>	<u>16+54</u>	<u>16+54</u>	<u>WP</u>	<u>Storm Drain</u>
	<u>16+54</u>	<u>19+53</u>				<u>End 11046</u>

7435

Start Point: Country Club Rd @ San Andrew Dr

Sidewalk Inventory

7425

End Point: San Andrew Dr

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, CM
Date: 4/22/2014

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 13

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
San Andrew Dr (Left)	0+00	4+35	4+35	4+35	DS	11007
	4+35	9+19	9+19	9+19	DS	11019
	9+19	10+45	10+5	10+54	CS	
	10+54	10+74	"	10+74	DS	11023
	10+74	11+25		11+25	VC	
	11+25	11+		11+19	VC	
	11+19	11+		11+70	VC	
	11+70	12+08		12+16	CS	
	12+16	14+98	18	15+25	CS	Wash out
			15+25	15+89	CS	
	15+89	18+02	18+02	18+22	CS	
	18+22	19+28				End @ San Andrew Dr

7425

Stauffer
Start Point: Stauffer Road Sidewalk Inventory / 194
End Point: _____

7415

Direction of Increasing Station: Left

Inspector Name: WTS
Date: 4/21/14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name: _____

Compliant

Non-Compliant

	From	To	From	To	Code	Comments
194	0+00	0+00	0+27	0+27	VC	Greater than 1/2" Cyf
	0+27	0+57	0+57	0+57	VC	" " " "
	0+57	0+87	0+87	0+87	VC	" " " "
	0+87	1+11				
Shopping Center	0+00	0+28	0+28	0+28	VC	" " " "
Entrance	0+28	0+58	0+58	0+58	VC	7 1/2" Cyf
	0+58	0+88	0+88	0+88	VC	" " " " on @ m
	0+88	1+13	1+13	1+13	VC	" " " "
	1+13	1+38	1+38	1+38	VC	" " " "
	1+38	1+68	1+68	1+68	VC	" " " "
	1+68	1+93	1+93	1+93	CS	
	1+93	1+98	1+98	1+98	VC	" " " "
	1+98	2+24				
Shopping Center						
Service Ramp						

7415

7405a

Sidewalk Inventory

Start Point: San Andrew Dr @ Country Club Rd

End Point: 12004 San Andrew

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/20/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Country Club Rd	0+00	0+12	0+12	0+84	CS	
	0+84	0+84	0+84	0+84	DS	11050
	0+84	0+84	0+84	1+10	CS	
	1+10	2+22	2+22	2+22	DS	11052
	2+22	2+46	2+46	2+63	CS	
	2+63	2+63	2+63	2+63	VC	
	2+63	3+20	3+20	3+20	DS	11054
	3+20	3+31	3+31	3+52	CS	
	3+52	4+10	4+10	4+10	DS	11056
	4+10	4+20	4+20	4+56	CS	
	4+56	4+90	4+90	5+04	CS	
	5+04	5+04	5+04	5+04	DS	11058
	5+04	5+04	5+04	5+35	CS	
	5+35	6+00	6+00	6+00	DS	11060

7405a

7402

Sidewalk Inventory

Start Point: San Andrew @ Country Club Rd E

End Point: 12004 San Andrew

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OE, KA
Date: 4/8/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 13

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	6+00	7+14	7+14	7+14	DS	11062
	7+14	12+38	12+38	—	VC	
	12+38	13+64	13+64	13+64	DS	11080
	13+64	14+21	14+21	—	VC	
	14+21	15+29	15+29	15+29	DS	11084
	15+29	15+68	15+68	—	VC	
	15+68	16+03	16+03	—	VC	
	16+03	16+48	16+48	—	VC	
	16+48	16+90	16+90	16+90	DS	11088
	16+90	17+01	17+01	—	VC	
	17+01	17+21	17+21	—	VC	
	17+21	17+71	17+71	17+71	DS	11090
	17+71	17+81	17+81	—	VC	
	17+81	17+94	17+94	—	VC	

74066

1111

3013

740sc

Sidewalk Inventory

Start Point: San Andrew Dr @ Country Club E

End Point: 12004 San Andrew

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/21/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	17+94	18+51	18+51	18+51	DS	11092
	18+51	18+63	18+63	—	VC	
	18+63	18+71	18+71	—	VC	
	18+71	18+84	18+84	—	VC	
	18+84	19+34	19+34	19+34	DS	11094
	19+34	20+10	20+10	20+10	DS	11096
	20+10	20+35	20+35	20+71	CS	
	20+71	20+85	20+85	20+85	DS	11098
	20+85	23+61	23+61	23+81	CS	
	23+81	23+97				
Country Club Rd.			0+00	0+11	CS	
12004 San Andrew	0+11	0+84				End

4616

740sc

Start Point: San Andres Dr @ Country Club Rd Sidewalk Inventory

End Point: Dal End @ Cort Rd

Direction of Increasing Station: RT

106-3
7395

Reason Codes for NON-COMPLIANCE:

Inspector Name: BK/RH/cm

Date: 4-21-14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 29

Street Name: <u>San Andres Dr</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Country Club Rd</u>	0+00	1+41	1+41	—	DS	Lt# 11045
	1+41	1+56	1+56	1+64	CS	
	1+56	2+18	2+18	—	DS	11047
	2+18	2+79	2+79	3+54	CS	
			3+88	—	DS	11049
	3+54	4+00	4+00	—	DS	11051
	4+00	4+10	4+10	4+21	CS	
	4+21	4+67	4+67	4+76	CS	
	4+76	6+00	6+00	6+35	CS	
			6+18	—	DS	11057
	6+35	8+86	8+86	—	DS	11063
	8+86	9+57	9+57	—	DS	11065
	9+57	9+68	9+68	10+02	CS	
	10+02	10+14	10+14	10+61	CS	
			10+34	—	DS	11067

7395

20F3 #399b

Sidewalk Inventory

Start Point: San Andrew Dr @ Country Club Rd

End Point: Dard End Court Rd

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/RL/CM
Date: 4-21-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: See Sheet 1

Compliant		Non-Compliant				Comments
Street Name: <u>San Andrew Dr</u>	From	To	From	To	Code	
	10+61	11+77	11+77	✓	DS	11071
	11+77	11+91	11+91	12+00	CS	
	12+00	13+51	13+51	✓	DS	11075
	13+51	15+58	15+58	✓	DS	11079
	15+58	16+29	16+29	✓	DS	11081
	16+29	16+69	16+69	✓	DS	11083
	16+69	17+40	17+40	✓	DS	11085
	17+40	18+16	18+16	✓	DS	11087
	18+16	18+28	18+28	18+37	CS	
	18+37	18+76	18+76	✓	VC	
	18+76	19+35	19+35	19+65	CS	
	19+65	20+38	20+38	✓	VC	
	20+38	21+40	21+40	✓	DS	11095
	21+40	22+58	22+58	22+94	CS	
		22+78	✓	DS	11099	

#399sb

30F ?
 739sc

Sidewalk Inventory

Start Point: San Andres Rd @ Country Club Rd

End Point: Dead End @ cart Path

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/RH/cm
 Date: 9-21-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: See sheet 1

Street Name: <u>San Andres Rd</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	22+94	24+95				
<u>Country Club Rd</u>	0+00	0+14	0+14	0+42	CS	
	0+42	1+75	1+75	2+08	CS	No PZ
	2+08	6+54	6+54	6+94	CS	No PZ's
	6+94	10+66	10+66	—	PO	Bush No PZ's
	10+66	11+36	11+36	11+89	CS	
	11+89	12+96				
<u>Club House Cir</u>			0+00	0+98	CS	Asphalt Path

739sc

Sidewalk Inventory

7385

Start Point: Lamar Dr @ Dead End

End Point: Dead End

Direction of Increasing Station: LT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF
Date: 4-21-17

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 4

Street Name: <u>Lamar Dr</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Dead End</u>	0+00	0+68	0+68	—	PO	sewer %
	0+68	0+94	0+94	—	DS	Lot # 4056/4054
			2+53	3+11	CS	
			2+83	—	DS	Lot # 4060/4058
	3+11	3+60	3+60	3+82	CS	
	3+82	4+56	4+56	—	PO	sewer %
	4+56	5+63	5+63	—	PO	sewer %
	5+63	5+97	5+97	—	DS	Lot # 4066
	5+97	8+36	8+36	8+52	CS	
			8+80	8+90	CS	
			11+13	11+53	CS	
	11+53	15+40				END @ Dead End

7385

Sidewalk Inventory

Start Point: Long Dr @ DEAD END

End Point: Autumn Crest Dr

Direction of Increasing Station: RT

1052
7375a

Reason Codes for NON-COMPLIANCE:

Inspector Name: RH, CM, BE

Date: 5/12/16

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: **11**

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	0+00	0+99	0+99		DS	4059, 4057
	0+99	1+36	1+36		PO	
	1+36	2+56	2+56	2+65	CS	
			2+65		DS	4063
			2+65	3+00	CS	
	3+00	6+02	6+02		VC	
	6+02	7+52	7+52	7+68	CS	
	7+68	7+90	7+90		VC	
	7+90	8+83	8+83	8+91	CS	
	8+91	9+17	9+17	9+21	CS	
	9+21	10+66	10+66		VC	
	10+66	11+65	11+65		PO	
	11+65	14+42	14+42	15+02	CS	
	15+02	17+12	17+12		PO	

7375a

2 of 7
7375

Sidewalk Inventory

Start Point: Lower @ Dond Road

End Point: Autumn Crest Dr

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: RH/CM
Date: 4-21-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: See Sheet 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	17+12	17+93	17+93	17+97	CS	
	17+97	18+11	18+11		DS	4083
	18+11	18+35	18+35		PO	
	18+35	19+52	19+52		VC	
	19+52	19+90	19+90	20+02	CS	
	20+02	20+17	20+17		DS	4087
	20+17	20+38	20+38		PO	
	20+38	21+10	21+10		PP	
	21+10	21+66	21+66	21+70	CS	
	21+70	22+23	22+23		DS	4091
	22+23	23+26	23+26	23+35	CS	
	23+35	24+14	24+14		DS	4095
	24+14	24+28	24+28	24+36	CS	
	24+36	24+89	24+89		PO	
	24+89	25+06	25+06	25+24	CS	
	25+26	26+16	26+16		DS	4094
	26+16	27+36				

7375b

Start Point: Liberty East Terr. Liberty East Run
 End Point: Liberty East Run

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: WS
 Date: 4/21/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 1111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Liberty East Terr.	0+00	0+06	0+06	0+06	VC	Greater than 1/2" gap
Home #12368	0+06	0+30	0+30	0+30	VC	Center of Drive may 12366
Mail Box.	0+30	1+32	1+32	1+32	VC	> 1/2" gap
	1+32	1+43	1+43	1+43	VC	" " "
	1+43	1+73	1+73	1+73	VC	" " " " "
	1+73	2+17	2+17	2+17	VC	" " " " "
	2+17	2+37	2+37	2+37	VC	" " " " "
	2+37	2+76	2+76	2+76	VC	
Ganth Place	0+00	0+06	0+06	0+06	VC	> 1/2 Gap
	0+06	0+46	0+46	0+46	VC	" " " " "
	0+46	0+56				

7365

Start Point: Liberty East Terrace / Q' cul-de-sac (#12368) (7355)

End Point: Cracked Bell Court

Direction of Increasing Station: Left

Inspector Name: T/D
Date: 4-21-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Q' cul-de-sac #12368	0+00	0+25	0+25		VC	
	0+25	4+38				
Liberty East Run	0+00	0+20	0+20	0+50	CS	
	0+50	0+65	0+65	0+86	CS	
	0+86	0+96	0+96	1+32	CS	
	1+32	1+86				
Cracked Bell Ct.	1+86					

7355

Start Point: Liberty East Run / Liberty East Terrace

Sidewalk Inventory

#345

End Point: End of sidewalk

Direction of Increasing Station: Left

Inspector Name:

T/D

Date:

4-21-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Liberty East Terr.	0+00	0+05	0+05	0+15	CS	
	0+15	0+55				
End of sidewalk	0+55					

7345

Start Point: Liberty East Run / Liberty East Terrace Sidewalk Inventory

1335

End Point: Rt. 26

Direction of Increasing Station: Right

Inspector Name: T/D
Date: 4-21-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Liberty East Terrace	0+00	1+66	1+66		VC	
	1+66	1+81	1+81		VC	
	1+81	2+11				
Rt. 26	2+11					

1335

7325

Start Point: Highlander Blvd. / Devilbiss Bridge Road

End Point: Cramer Ave.

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/J/W/D
Date: 4-29-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

5

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Devilbiss Bridge Rd.	0+00	0+17	0+17		VC	
	0+17	0+31	0+31		VC	
	0+31	0+38	0+38	0+56	CS	
			0+56		DS	9512
			0+56	0+62	CS	
	0+62	1+82	1+82		VC	
	1+82	3+13	3+13		VC	
	3+13	4+02	4+02		DS	9504
			4+02	4+11	CS	
	4+11	6+53	6+53		VC	
Cramer Ave	6+53	6+80				
	6+80					

7325

Start Point: Highlander Blvd. ^{Sidewalk Inventory} / Devil's Bridge Rd. ^{#315}

End Point: House Number 9413

Direction of Increasing Station: Left

1
-3
242
117
392
242
434

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 1

Inspector Name: WJ
Date: 4/21/14

Side walk
Dead ends both S. & W.

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Devil's Bridge	0+00	0+87				
Albany Ave	0+00	0+33	0+33	0+33	VC	Greater than 1/2" Lip
	0+33	1+15	1+15	1+15	VC	" " " "
	1+15	2+42				
Burlington N.	0+00	0+91	0+91	0+91	VC	> 1/2" Lip
	0+91	1+00	1+00	1+00	VC	" " "
	1+00	1+16	1+16	1+46	CS	
	1+46	2+42				
Gramer Ave	0+00	0+17	0+17	0+17	VC	> 1/2" Lip
	0+17	0+29	0+29	0+33	CS	
	0+33	0+53	0+53	0+53	PO	Clear out center of 2 side walk sections
	0+53	1+02	0+53	1+02	CS	
			1+02	1+02	DS	9413
			1+02	1+17	CS	

End Home # 9413
117

7315

730sa

Start Point: Glade Ave. / Farmingdale Ave

pg 1 of 2

End Point: End of Sidewalk

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: T/S/W/D
Date: 4-21-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

5

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Farmingdale Ave			0+00		VC	
			0+00	0+13	PCS	
	0+13	0+69	0+69	0+75	CS	
			0+75		DS	9508
			0+75	0+90	CS	
	0+90	1+05	1+05		VC	
	1+05	1+45	1+45	1+56	CS	
			1+56		DS	9506
			1+56	1+70	CS	
	1+70	1+85	1+85		VC	
	1+85	1+97	1+97	2+25	CS	
	2+25	3+31	3+31		VC	(Also TREE Limbs)
	3+31	3+37	3+37	3+50	CS	
	3+50	3+94	3+94		VC	

730sa

730sb

pg 2 of 2

Start Point: Glade Ave / Farmingdale Ave

End Point: End of sidewalk

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: TLD
Date: 4-21-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	3+94	4+14	4+14		VC	
	4+14	4+34	4+34		VC	
	4+34	4+39	4+39		VC	
	4+39	5+13	5+13	5+25	CS	
	5+25	5+37	5+37	5+49	CS	
	5+49	5+64				
End of sidewalk	5+64					

730sb

Start Point: Glade Ave / Farming Dale Ave. Sidewalk Inventory

192
7295a

End Point: _____

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

Inspector Name: WJ
Date: 4/21/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Farming Dale Ave	0+00	0+36	0+36	0+36	VC	Concrete Run 1/2" Lip
	0+36	0+42	0+42	0+60	CS	
	0+60	0+70	0+70	0+79	CS	
			0+79	0+79	DS	Home # 9511
			0+79	0+86	CS	
	0+86	0+97	0+97	1+15	CS	
	1+15	1+28	1+28	1+58	CS	
			1+58	1+58	DS	9509
			1+58	1+71	CS	
	1+71	1+83	1+83	1+83	VC	> 1/2" Lip
	1+83	2+44	2+44	2+44	VC	" " "
	2+44	2+79	2+79	2+79	VC	" " " "
	2+79	3+12	3+12	3+52	CS	
	3+52	3+68				

382

7295a

Start Point: Glade Ave / Fanning Dale Ave 292 (1295)

150
382
540

End Point: _____

Direction of Increasing Station: _____

Inspector Name: WJ
Date: 4/21/14

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
322			3+68	3+82	CS	
Albany Ave East			0+00	0+27	CS	
	0+27	0+51	0+51	0+51	VC	Greater than 1/2" Lys
	0+51	0+67	0+67	0+73	CS	
			0+73	0+73	DS	9505
			0+73	0+87	CS	
	0+87	0+91	0+91	0+91	VC	> 1/2" Lys
	0+91	1+11	0+87	1+11	CS	
	1+11		1+11	1+58		
Pass 9505						
Towards Daysale						
1+58 Vane						

729sb

Start Point: ^{Garth} ~~Garth~~ Plan / Liberty East Terr.

192 #285a

End Point:

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: WJ

Date: 4/21/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 111

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Liberty East Terr	0+00	0+25	0+25	0+25	VC	Garth Plan 1/2" Lip
	0+25	0+46	0+46	0+53	CS	0+43 to 0+46 Trim Bush, P?
			0+53	0+53	DS	12358
			0+53	0+60	CS	
	0+60	0+65	0+65	0+65	VC	> 1/2" Lip
	0+65	0+75	0+75	0+75	VC	---
	0+75	0+86	0+86	0+86	VC	> 1/2" Lip
	0+86	1+00	1+00	1+00	VC	" " " "
	1+00	1+40	1+40	1+46	CS	
	1+46	1+75	1+75	1+75	VC	
	1+75	1+80	1+80	1+87	CS	
			1+87	1+87	DS	12350
			1+87	1+95	CS	
	1+95	2+04	2+04	2+04	VC	> 1/2" Lip

#285a

Garth Place

292

7285b

Start Point:

~~Garth Place~~ Sidewalk Inventory Liberty East Ter

End Point:

Liberty East Ter

Direction of Increasing Station:

Rt

Reason Codes for NON-COMPLIANCE:

Inspector Name:

WS

Date:

4/21/14

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Total Number of Driveways:

0

Street Name:

From

Compliant

To

From

Non-Compliant

To

Code

Comments

Liberty East Ter	2+04	2+36	2+36	2+44	CS	

7285b

Start Point: Farmingdale Ave ^{Sidewalk Inventory} Albany Ave East ~~Devil's Bridge Road~~

7275 *MA*

End Point: End of Sidewalk

Direction of Increasing Station: Left

Inspector Name: TJS/DW
Date: 4-21-14

Reason Codes for NON-COMPLIANCE:
VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Devil's Bridge			0+00	0+09	CS	
Albany Ave East	0+09	0+98	0+98		VC	
	0+98	1+01	1+01	1+18	CS	
	1+18	1+26	1+26	2+03	CS	
	2+03	2+07	2+07		VC	
	2+07	2+22				
Burlington Circle	0+00	0+11	0+11	0+26	CS	
	0+26	0+84	0+84	1+73	CS	
	1+73	2+20	2+20	2+32	CS	
Glade Ave	0+00	0+41	0+41	0+89	CS	
	0+89	1+10	1+10		VC	
	1+10	1+22	1+22		VC	
	1+22	1+70	1+70	1+78	CS	
	1+78	2+51	2+51		VC	

End of sidewalk 2+51 2+62

7275

Sidewalk Inventory

Start Point: Farmingdale Ave / Develbliss Bridge Rd.

End Point: Pass house # 200 on Cramer Ave.

726S

(11 245 144)

501

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: _____

Date: _____

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Develbliss Rd	0+00	0+23			PO	Remove cedar Trees or Trim
	0+23	0+87	0+87	1+08	CS	
	0+87	1+12				
Albany Ave west			0+00	0+27	CS	
	0+27	2+13	2+13	2+45	CS	
Burleighton Ave	0+00		0+00	0+04	CS	
	0+04	0+96				Excess Grass in sidewalk joints
			1+96	1+96	VC	Greater than 1/4" gap
	1+96	2+08	2+08	2+46	CS	
Cramer Ave	0+00	0+11	0+11	0+11	VC	" " " "
	0+11	0+22	0+22	0+22	VC	" " " "
	0+22	1+12	1+12	1+12	VC	
House # 200	1+12	1+44				
144						

House Number 200

726S

7255

Start Point: Fair lane @ Sidewalk Inventory
Country Club Rd

End Point: Country Club Rd

Direction of Increasing Station: ~~check~~




Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/RT/CM
Date: 4-21-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel



Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Country Club Rd	0+00	0+73	0+73	—	VC	
	0+73	0+88	0+88	—	VC	
	0+88	2+71	2+71	—	VC	
	2+71	3+48	3+48	—	DS	L# 6960
	3+48	3+58	3+58	3+73	CS	
	3+73	5+29	5+29	—	VC	
	5+29	6+12				END @ Country Club Rd

7255

Start Point: Discovery Blvd / Stauffer Rd 7245a

End Point: _____

Direction of Increasing Station: Left

Inspector Name: TWS
Date: 4/21/14

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 0

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Stauffer Rd.	0+00	0+06	0+06	0+06	VC	Greater than 1/2" Lip
	0+06	0+14	0+14	0+14	VC	" " " "
	0+14	0+26	0+26	0+26	VC	" " " "
	0+26	0+33	0+33	0+33	VC	" " " "
	0+33	0+46	0+46	0+46	VC	" " " "
	0+46	0+56	0+56	0+56	VC	" " " "
	0+56	0+91	0+91	1+16	CS	
	1+16	1+29	1+29	1+35	CS	
	1+35	1+35	1+35	1+35	VC	> 1/2" Lip
	1+35	1+45	1+45	1+45	VC	" " " "
	1+45	1+66	1+66	1+66	VC	" " " "
	1+66	1+75	1+75	1+75	VC	" " " "
	1+75	1+86	1+86	1+86	VC	" " " "
	1+86	2+15	2+15	2+15		

Sidewalk Inventory

Start Point: Deer Brook Ct. @ Autumn Crest Dr. (4)

7235

End Point: 13586 Deer Brook Ct.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/21/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 9

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Autumn Crest	0+00	0+16	0+16	0+26	CS	
	0+26	1+90	1+90	1+90	DS	13572
	1+90	4+77	4+77	4+77	DS	13578
	4+77	5+67	5+67	5+67	DS	13580
	5+67	5+78	5+78	—	VC	
	5+78	5+82	5+82	6+02	CS	
	6+02	6+19	6+19	6+19	DS	13582
	6+19	6+32	6+32	7+04	CS	
	7+04	7+12	7+12	7+12	DS	13584
	7+12	7+12	7+12	8+04	CS	
13586 Deer Brook Ct.	8+04	8+15				End

7235

Sidewalk Inventory

7228

Start Point: Autumn Crest Dr @ Deer Brook Ct (2)

End Point: 13418 Autumn Crest Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: DL KA
Date: 4/21/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 2

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Deer Brook Ct.			0+00	0+27	CS	
	0+27	0+31	0+31	—	VC	
	0+31	1+70	1+70	—	VC	
	1+70	2+46	2+46	2+46	PO	tree
	2+46	7+09				SILT SHK fence crossing sidewalk
The Preserve @ Harvest Ridge	0+00	4+38				End

7225

Sidewalk Inventory

Start Point: Autumn Crest Dr. @ Four Seasons Ct.

End Point: 13415 Autumn Crest Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/21/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 8

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Four Seasons Ct.	0+00	1+16	1+16	1+16	DS	13433 & 13431
	1+16	2+27	2+27	—	VC	
	2+27	2+42	2+42	2+54	CS	
	2+54	2+58	2+58	—	VC	
	2+58	2+69	2+69	2+79	CS	PO @ Sta 2+75
	2+79	2+99	2+99	2+99	DS	13429 & 13427
	2+99	3+17	3+17	3+37	CS	
	3+37	3+68	3+68	3+68	PO	Sewer cleanout
	3+68	4+47	4+47	—	VC	
	4+47	4+58	4+58	4+58	PO	Sewer cleanout
	4+58	5+41	5+41	—	VC	
	5+41	6+27	6+27	—	VC	
	6+27	6+43	6+43	—	VC	
	6+43	6+50	6+50	—	VC	

Sidewalk Inventory

Start Point: Autumn Crest Dr. @ Four Seasons Ct. (L)

End Point: 13415 Autumn Crest Dr.

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/21/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 2

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		

[illegible]

721sb

Sidewalk Inventory

Start Point: Four Seasons Ct. @ Autumn Crest Dr. (L)

7205a

End Point: Autumn Crest Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: DZ, KA
Date: 4/18/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 11

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Autumn Crest	0+00	1+90	1+90	—	VC	
	1+90	2+08	2+08	—	VC	
	2+08	2+48	2+48	—	VC	
	2+48	2+77	2+77	2+77	DS	13453
	2+77	2+77	2+77	2+77	DS	13455
	2+77	4+29	4+29	—	VC	
	4+29	4+52	4+52	—	VC	
	4+52	4+56	4+56	—	VC	
	4+56	5+17	5+17	—	VC	
	5+17	6+79	6+79	6+79	DS	13465
	6+79	8+16	8+16	8+16	DS	13469
	8+16	8+91	8+91	8+91	DS	13471
	8+91	9+58	9+58	9+58	DS	13473
	9+58	9+86	9+86	—	VC	

7205a

10.697

Start Point: Four Seasons Ct. @ Autumn Crest Dr. L

End Point: Autumn Crest Dr.

720sb

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: 02, KA
Date: 4/12/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 17

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	9+80	10+25	10+25	10+25	DS	13475
	10+25	16+16	16+16	16+16	DS	13478
	16+16	16+33	16+33	—	VC	
	16+33	16+41	16+41	—	VC	
	16+41	16+73	16+73	16+73	DS	13476
	16+73	17+16	17+16	17+16	DS	13474
	17+16	18+09	18+09	—	VC	
	18+09	18+36	18+36	18+36	DS	13472
	18+36	19+23	19+23	19+23	DS	13470
	19+23	20+19	20+19	20+19	DS	13468
	20+19	21+06	21+06	21+06	DS	13466
	21+06	22+00	22+00	22+00	DS	13464
	22+00	22+95	22+95	22+95	DS	13462
	22+95	24+33	24+33	24+33	DS	13460

720sb

720sc

Start Point: Four Seasons Ct. @ Autumn Crest Dr. E

End Point: Autumn Crest Dr.

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/18/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 2

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	24+33	24+67	24+67	24+84	CS	
	24+84	26+59				
Summer Ridge Ct.	0+00	1+57	1+57	1+66	CS	
	1+66	1+94	1+94	1+94	DS	13454 E 13452
	1+94	2+38	2+38	—	VC	
	2+38	2+45	2+45	—	VC	
Autumn Crest	2+45	4+00				End

720sc

Start Point: Summer Ridge Ct. @ Four Seasons (L)
 End Point: Four Seasons Ct.

1 of 2
 719sa

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: 02 KA
 Date: 4/18/14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 14

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Four Seasons	0+00	0+91	0+91	0+91	DS	4500
	0+91	1+27	1+27	1+43	CS	
	1+43	2+33	2+33	2+33	DS	4502
	2+33	3+27	3+27	3+27	DS	4504
	3+27	3+52	3+52	—	VC	
	3+52	4+21	4+21	4+21	DS	4506
	4+21	5+06	5+06	5+06	DS	4508
	5+06	5+84	5+84	5+84	DS	4510
	5+84	6+93	6+93	6+93	DS	4512
	6+93	8+40	8+40	—	VC	
	8+40	8+81	8+81	—	VC	
	8+81	9+33	9+33	9+33	DS	4515
	9+33	10+03	10+03	10+03	DS	4513
	10+03	10+76	10+76	10+76	DS	4511

719sa

Start Point: Summer Ridge @ Four Seasons Ct. E

End Point: Four Seasons Ct.

719sb

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/18/14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	10+76	10+09	10+09	—	VC	
	10+09	11+47	11+47	11+47	DS	4509
	11+47	12+19	12+19	12+19	DS	4507
	12+19	13+62	13+62	13+62	DS	4503
	13+62	14+32	14+32	14+32	DS	4501
Four Seasons	14+32	15+49				End

719sb

Sidewalk Inventory

Start Point: 5566 Broadmoor Terr N @ Cut-de-sac

End Point: Pebble Beach Ter

Direction of Increasing Station: Left

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

DS Driveway Cross Slope

PP Pinch Point

CS Panel Cross Slope

PZ Passing Zone

WP Width of Panel

PO Protruding Object

Inspector Name: OZ, KA, CM

Date: 4/18/14

Total Number of Driveways: 9

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Cut-de-sac	0+00	13+30	13+30	—	VC	
	13+32	15+14	15+14	—	VC	
	15+14	17+97	17+97	18+09	CS	
	18+09	19+20	19+20	19+37	CS	
	19+37	19+69	19+69	19+86	CS	
	19+86	20+27	20+27	20+35	CS	
	20+35	20+59	20+59	20+71	CS	
	20+71	21+30	21+30	21+60	CS	
	21+60	21+84	21+84	—	VC	
	21+84	21+92	21+92	22+08	CS	
	22+08	23+11	23+11	23+67	CS	
	23+67	24+18	24+18	—	VC	
	24+18	25+50	25+50	—	VC	
	25+50	25+58	25+58	—	VC	

7185a

71856

Sidewalk Inventory

Start Point: 5566 Broadmoor Terr @ Cut-de-sac

End Point: Pebble Beach Terr

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZKA, CM

Date: 4/18/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 6

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	25+58	26+19	26+19	—	VC	
	26+19	27+06	27+06	—	VC	
	27+06	27+20	27+20	—	VC	
	27+20	27+51	27+51	—	VC	
	27+51	27+51	27+51	27+71	CS	
	27+71	28+09	28+09	—	VC	
	28+09	28+62	28+62	28+73	CS	
	28+73	29+05	29+05	—	VC	
	29+05	30+02	30+02	30+17	CS	
	30+17	30+17	30+17	—	VC	
	30+17	30+32	30+32	30+48	CS	
	30+48	30+73	30+73	30+73	DS	5619
	30+73	30+97	30+97	31+17	CS	
	31+17	31+25	31+25	—	VC	

71856

718sc

Sidewalk Inventory

Start Point: 5566 Broadmoor Ter @ Cul-de-sacEnd Point: Pebble Beach Ter

Direction of Increasing Station: _____

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA, CMDate: 4/18/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	31+25	31+49	31+49	31+65	CS	
	31+65	31+95	31+95	31+95	PO	tree
	31+95	33+42	33+42	33+92	CS	
	33+92	35+11	35+11	35+36	CS	
	35+36	35+55	35+55	—	VC	
	35+55	36+07	36+07	—	VC	
	36+07	37+54	37+54	37+82	CS	
	37+82	38+77	38+77	38+77	DS	5629
	38+77	38+77	38+77	38+89	CS	
	38+89	40+06	40+06	40+15	CS	
	40+15	40+37				
Wentworth Pl			0+00	0+47	CS	
	0+47	0+71	0+71	0+91	CS	
	0+91	1+31	1+31	1+39	CS	
	1+39	3+24	3+24	—	VC	
Pebble Beach Ter	3+24	3+24	3+24	3+42	CS	End

718sc

111

1 of 3

717sa

Sidewalk Inventory

Start Point: Mahogany Run @ Pebble Beach Ter

End Point: Lonsdale Rd

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA
Date: 4/18/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object
- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 5

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Pebble Beach Ter	0+00	0+31	0+31	—	VC	
	0+31	0+31	0+31	0+44	CS	
	0+44	0+44	0+44	—	VC	
	0+44	0+82	0+82	—	VC	
	0+82	0+82	0+82	1+23	CS	
	1+23	1+23	1+23	1+23	DS	9802
	1+23	1+23	1+23	2+75	CS	
	2+75	2+93	2+93	3+57	CS	
	3+57	3+73	3+73	4+05	CS	
	4+05	4+05	4+05	4+05	DS	9806
	4+05	4+05	4+05	4+15	CS	
	4+15	4+37	4+37	4+84	CS	
	4+84	4+98	4+98	5+83	CS	
	5+83	6+08	6+08	—	VC	

717sa

Sidewalk Inventory

Start Point: Mahogany Run @ Pebble Beach Ter

717sb

End Point: Jansville Rd

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

Inspector Name: DZ, KA
Date: 4/18/14VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding ObjectDS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 6

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	6+08	6+08	6+08	6+26	CS	
	6+26	6+44	6+44	6+61	CS	
	6+61	6+61	6+61	—	VC	
	6+61	6+93	6+93	7+05	CS	
	7+05	7+05	7+05	—	VC	
	7+05	7+57	7+57	7+74	CS	
	7+74	8+23	8+23	8+42	CS	
	8+42	8+42	8+42	—	VC	
	8+42	8+85	8+85	—	VC	
	8+85	8+97	8+97	9+30	CS	
	9+30	9+62	9+62	9+75	CS	
	9+75	10+36	10+36	—	VC	
	10+36	10+89	10+89	—	VC	
	10+89	11+37	11+37	—	VC	

717sb

717sc

Sidewalk Inventory

Start Point: Mahogany Run @ Pebble Beach Ter

End Point: Ijamsville Rd.

Direction of Increasing Station:

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Inspector Name: OZ, KA
Date: 4/18/14

Total Number of Driveways: 3

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
	11+37	13+13	13+13	13+13	DS	9800
	13+23	13+23	13+23	—	VC	
	13+23	13+23	13+23	13+39	CS	
	13+39	13+39	13+39	—	VC	
Ijamsville Rd.	13+39	16+50				End

717sc

11111

Sidewalk Inventory

7165

Start Point: Broadmoor Ter @ Pebble Beach Ter.

End Point: 6506 Broadmoor Ter.

Direction of Increasing Station: Right

Reason Codes for NON-COMPLIANCE:

Inspector Name: OZ, KA

Date: 4/16/14

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 4

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Pebble Beach Ter.	0+00	2+69	2+69	—	VC	
	2+69	3+65	3+65	—	VC	
	3+65	3+89	3+89	—	VC	
	3+89	3+98	3+98	—	VC	
Pebble Beach Ter.	3+98	4+19				End

7165

Start Point: Minor Dr S @ Penn Shop Rd. Sidewalk Inventory

End Point: Lamar Terr

Direction of Increasing Station: RT

Inspector Name: BF/CB/CM

Date: 4-18-19

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 17

Street Name: Minor Dr. S	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Penn Shop Rd	0+00	0+84	0+84	1+09	CS	
	1+09	2+02	2+02	2+14	CS	No PZ
	2+14	5+75				
Turf CT			0+00	0+34	CS	
	0+34	1+41	1+41	—	DS	L#13209
	1+41	1+87	1+87	2+06	CS	
	2+06	5+43				
Tennis CT Part 1	0+00	0+16	0+16	0+32	CS	
	0+32	0+68	0+68	0+88	CS	
	0+88	1+29				
Tennis CT Part 2	0+00	6+45	6+45	7+05	CS	
	7+05	7+57	7+57	8+01	CS	
	8+01	8+26	8+26	—	DS	L#13231
	8+26	8+45	8+45	8+60	CS	

2 of 2
715sb

Sidewalk Inventory

Start Point: Manor Dr S @ Penn Slope Rd

End Point: Lower Terr

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/CM/CB
Date: 4-18-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: See Sheet #1

Street Name: Manor Dr S	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Cont.	8+60	8+88	8+88	8+96	CS	NOTES
	8+96	9+20	9+20	10+73	CS	
	10+73	11+65	11+65	12+34	CS	
	12+34	12+94	12+94	13+30	CS	
	13+30	14+11	14+11	17+65	CS	
	17+65	17+77	17+77		DS	C# 13237
	17+77	18+24	18+24	18+64	CS	
	18+64	19+67	19+67	19+75	CS	
	19+75	19+99	20+07	20+32	CS	
	20+32	20+52	20+52	20+61	CS	
	20+61	20+89	20+89	23+23	CS	END @ Lower Terr

715sb

Sidewalk Inventory

7145

Start Point: Champlaine Dr @ Heller Rd

End Point: Dead End

Direction of Increasing Station: LT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF
Date: 4-18-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 1

Street Name: Champlaine Dr	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Heller Rd	0+00	2+27				No PZ's
Manheim Pl	0+00	3+62				
Amesbury Jct	0+00	0+56	0+56	0+94	CS	
	0+94	3+27				
Deck Entrance	0+00	1+49				END @ Dead End

7145

7135

End Point: Dead END

Direction of Increasing Station: 

Inspector Name: BF/CB/cm
Date: 8-18-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Gulfview Terrace						

[illegible]

7135

Sidewalk Inventory

7125

Start Point: Penn Shop Rd @ Loma Terr

End Point: Golf Club Terr

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/cm/cb
Date: 8-18-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 1

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Loma Terr	0+00	0+21	0+21	/	VC	
	0+21	1+62	1+62	/	VC	
	1+62	3+83	3+83	4+04	CS	
	4+04	5+44	5+44	/	VC	
	5+44	6+48	6+52	7+18	CS	Cart Path
	7+18	7+28	7+28	7+52	CS	
	7+52	7+84				

7125

Start Point: Lamar Terr @ Manor Dr S

Sidewalk Inventory

7115

End Point: Penn Shop Rd

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BF/CB/cm
Date: 4-18-14

VC Vertical Clearance
PP Pinch Point
PZ Passing Zone
PO Protruding Object

DS Driveway Cross Slope
CS Panel Cross Slope
WP Width of Panel

Total Number of Driveways: 2

Street Name: <u>Lamar Terr</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Manor Dr S</u>	<u>0+00</u>	<u>2+70</u>	<u>2+70</u>	<u>3+02</u>	<u>CS</u>	
	<u>3+02</u>	<u>3+55</u>	<u>3+55</u>	<u>3+68</u>	<u>CS</u>	
	<u>3+68</u>	<u>4+61</u>	<u>4+61</u>	<u>4+65</u>	<u>CS</u>	
	<u>4+65</u>	<u>6+47</u>				<u>End</u>

7115

Start Point: Annandale Road Sidewalk Inventory from Mt. St. Mary's to Lincoln Ave / RT. 146

End Point: _____

Direction of Increasing Station: _____

Inspector Name: T/J
Date: 4-18-14

Date: 4-18-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP. Pinch Point

PZ: Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope.

WP Width of Panel

Total Number of Driveways:

Compliant

Non-Compliant

Street Name:

From.

To

From

To

Code

Comments

[illegible]

710s

Direction of Increasing Station:

Inspector Name:

Date:

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ :Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope.

WP: Width of Panel

Total Number of Driveways:

Street Name: _____

From .

To

Non-Compliant

From

To

Code

Comments

No Sidewalk

There is sidewalk near Alumni Center Approx. 100'

17095

7085

Direction of Increasing Station:

Date:

Total Number of Driveways:

Non-Compliant

From -

From

To

Code

Comments

	From	To	Code	Comments
		@ Rt. 77	- "Approx. 50' of " 2 1/2' wide	deteriorated sidewalk
Rt. 77 (Left side)		0+00	1+24 CS	3' wide entire side between Cross Slope! Vertical Clearance Entire side Failed

7085

Start Point: Broadford Ct / Broadford way Sidewalk Inventory

End Point: Broadford way

Direction of Increasing Station: all Right

cont

192

70659

Reason Codes for NON-COMPLIANCE:

Inspector Name: TJ

Date: 7/18/14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Compliant

Non-Compliant

Total Number of Driveways:

111 111 (8)

Street Name:

From

To

From

To

Code

Comments

Broadford way						
	0+29	0+57	0+00	0+29	CS	
	0+29	0+57	0+57	0+57	VC	Greater than 1/2" gap
	0+57	0+92	0+92	0+92	VC	
	0+92	1+05	1+05	2+25	CS	
	2+25	2+41	2+41	2+51	CS	
			2+51	2+51	DS	6303
			2+51	3+09	CS	
			3+09	3+09	DS	6305
			3+09	3+32	CS	
			3+32	3+32	DS	6307
			3+32	4+11	CS	
			4+11	4+11	DS	6308
			4+11	4+46	CS	
			4+46	4+46	DS	6306

70652

Start Point: Bradford Ct / Bradford way Sidewalk Inventory

706sb

End Point: Bradford way

Direction of Increasing Station: RIGHT (R)

Inspector Name: ST
Date: 4/18/14

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: _____

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
			4+46	4+55	CS	Greater than 1/2" Lip
	4+55	4+75	4+75	4+75	VC	" " " "
	4+75	4+95	4+95	4+95	VC	" " " "
	4+95	5+12	5+12	5+12	VC	> 1/2" Lip
	5+12	5+33	5+33	5+47	CS	
	5+47	5+70	5+70	5+70	VC	> " "
	5+70	5+83	5+83	6+00	CS	
			6+00	6+00	DS	6302
			6+00	6+09	CS	
	6+09	6+50	6+50	6+50	VC	> 1/2" Lip
	6+50	6+99				
Bradford way						
699						

706sb

Sidewalk Inventory
Start Point: Adams ST @ Cherry Alley

7055

End Point: MTville Rd

Direction of Increasing Station: LT

Inspector Name: BF 302
Date: 9-17-14

Reason Codes for NON-COMPLIANCE:

VC Vertical Clearance

PP Pinch Point

PZ Passing Zone

PO Protruding Object

DS Driveway Cross Slope

CS Panel Cross Slope

WP Width of Panel

Total Number of Driveways: 0

Street Name: <u>Adams ST</u>	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
<u>Cherry Alley</u>	<u>0+00</u>	<u>1+15</u>	<u>1+15</u>	<u>✓</u>	<u>VC</u>	
			<u>1+60</u>	<u>✓</u>	<u>VC</u>	
	<u>1+15</u>	<u>1+60</u>	<u>1+60</u>	<u>1+89</u>	<u>CS</u>	<u>END</u>

7055

70

Sidewalk Inventory

Start Point: Washington ST @ Mountville Rd

End Point: Dandel Fence

Direction of Increasing Station: RT

Inspector Name: BF102
Date: 4-17-14

Reason Codes for NON-COMPLIANCE:

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 4

Street Name: Washington ST	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Mountville Rd			0+00	2+41	CS	Broken up very bad /
			0+66	—	PO	Large Tree
		OK ✓ 2+41	2+41	—	PO	Large Tree
	2+41	3+55	3+55	—	PO	Bush
			3+60	—	VC	
	3+60	4+80	4+80	6+60	CS	sidewalk ads @ D/H Lt 2780
			4+86	—	DS	Lt 2780
			5+00	—	VC	Tree stump
		6+60				FMD @ Lt 2774

7045

7035

Sidewalk Inventory

Start Point: Washington ST @ Dead END Lot 2781

End Point: Mountville Rd

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: JF 307
Date: 4-17-14

- VC Vertical Clearance
- PP Pinch Point
- PZ Passing Zone
- PO Protruding Object

- DS Driveway Cross Slope
- CS Panel Cross Slope
- WP Width of Panel

Total Number of Driveways: 2

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
Dead END	0+00	0+11	0+11	/	VC	3' Sidewalk
			0+53	/	VC	
			0+60	1+10	CS	Tree destroyed Sidewalk
			0+67	/	VC	Tree
	1+10	1+54	1+54	/	PO	Bush
			1+52	/	DS	Lot 2785
	1+52	2+98	3+17			
Cherry Alley	0+00	0+28	0+28		VC	
			0+28	0+54	CS	END @ Mountville Rd

7035

mountville
 Start Point: ~~Mountville Rd @ RR Tracks~~ / Post Office

Sidewalk Inventory

702s

End Point: Dead End

Direction of Increasing Station: RT

Reason Codes for NON-COMPLIANCE:

Inspector Name: BE
 Date: 9-17-14

VC Vertical Clearance
 PP Pinch Point
 PZ Passing Zone
 PO Protruding Object

DS Driveway Cross Slope
 CS Panel Cross Slope
 WP Width of Panel

Total Number of Driveways: 7

Street Name:	Compliant		Non-Compliant		Code	Comments
	From	To	From	To		
RR Tracks / Post Office: R	0+00	0+85	0+85		DS	65541
			0+85	1+10	CS	
	1+10	1+22	1+22	1+58	CS	Missing Section
			1+58	2+79	CS	Bricks
Washington ST	0+00		0+00	0+56	CS	2'-3' Sidewalk
			0+56	2+52	CS	Cobble stone
	2+52	3+59				3'
Adams ST.	0+00	1+42	1+42	—	DS	church
			1+64	—	PP	1'-2' wide
			1+89	—	PO	Bush
	1+89	4+77	4+77	5+99	CS	Broken Bad / partially buried

702s

7015

7015